

Register entry, as of 27 October 2026

Listed for sale

Record ID c5215d95fd89

2006 Chevrolet Corvette

6.0 L, 8 cylinders · Convertible · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1G1 YY36U 0 6 5 101017

WMI 1-3

Chevrolet · GENERAL MOT...

DESCRIPTOR 4-8

Corvette · 6.0 L

CHECK 9

Verified

YEAR 10

2006

PLANT 11

Bowling Green

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2006	Engine	6.0 L, 8 cylinders
Make	Chevrolet	Fuel	Gasoline
Model	Corvette	Drive	Not in the decode
Trim	Not in the decode	Maker	GENERAL MOTORS LLC
Body	Convertible	Plant	Bowling Green, Kentucky, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/chevrolet/corvette/2006

5 recalls listed by Transport Canada for this model year

Lights and instruments

2014174 16 May 2014

On certain vehicles, wiring within the underhood fuse panel wiring may break, causing intermittent low beam function. This could compromise driver visibility and increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the underhood fuse panel.

Brakes

2010134 27 Apr 2010

Certain vehicles equipped with tilt and telescoping steering column may have an intermittent or open condition in a connector in the Steering Wheel Position Sensor (SWPS) circuit located in the steering column. If this intermittent or open condition occurs, the "SERVICE ACTIVE HANDLING SYSTEM" message is displayed, and a short-duration brake apply may occur if the signals for steering wheel rotation or ground are corrupted. The manufacturer assessed the brake application as observable, but controllable and vehicle handling is maintained by minor corrections in steering, however, if the driver does not respond to the change in vehicle movement, it could result in a crash causing property damage, personal injury or death. Correction: Dealers will inspect and, if necessary, install a terminal position assurance clip to the connector.

Other

2009362 21 Dec 2009

On certain vehicles equipped with a removable roof, the adhesive between the roof and the frame may separate. If there is a complete separation, the roof panel may detach from the vehicle and should this happen while driving, it could result in a crash causing property damage, personal injury or death. Correction: Dealers will install a new design roof panel.

Other

2006123 26 May 2006

On certain vehicles with a painted roof, the adhesive between the roof panel and the frame may separate. As a result, the roof panel may detach from the vehicle and strike a road user, causing injury and property damage. Correction: Dealers will inspect and, if required, replace the roof.



Steering

2005296 7 Oct 2005

Certain vehicles may have been built with a power steering hose that is not to specification. Under extreme steering manoeuvres, such as turning the steering wheel fully to the left or right while braking, the hose may fracture and leak fluid. If this were to occur, power steering assist would be lost and increased steering effort would be required. On vehicles equipped with hydro-boost power brakes, it could also result in loss of power brake assist and increase braking effort would be required. If power steering fluid were to spray onto hot engine parts, an engine compartment fire could occur. Correction: Dealers will inspect the power steering hose(s) for two suspect date codes and replace them if required.

Listed for the model year, not checked against your VIN. Chevrolet confirms which apply.


Check your VIN with Chevrolet Canada or call a Chevrolet dealer with your VIN.

www.chevrolet.ca/en/ownercenter/recalls

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$39,990^[5], \$5,045 over the median of \$34,945^[4].



Lowest ask	\$29,900
Middle half	\$32,422 – \$37,468
Median ask	\$34,945
This car	\$39,990

Same model year · 2 live listings · as of 27 Oct 2026

OTHER 2006 CHEVROLET CORVETTE LISTINGS [5]

Sherwood Park, AB · 115,823 km	\$29,900
Edmonton, AB · 115,823 km	\$29,900

§4 EVENTS

2006	Model year 2006 ^[1] Assembly plant Bowling Green, Kentucky, United States
7 Oct 2005	Transport Canada recall 2005296 ^[2] Issued for the model year · Steering
26 May 2006	Transport Canada recall 2006123 ^[2] Issued for the model year · Other
21 Dec 2009	Transport Canada recall 2009362 ^[2] Issued for the model year · Other
27 Apr 2010	Transport Canada recall 2010134 ^[2] Issued for the model year · Brakes
16 May 2014	Transport Canada recall 2014174 ^[2] Issued for the model year · Lights and instruments
9 Oct 2026	Listed for sale, Carstairs, AB ^[5] Champion Ford · asking \$39,990



27 Oct 2026 Listing last updated^[5]
asking \$39,990

§5 DOCUMENTS

Window sticker This VIN reads as model year 2006, before our coverage for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 2 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

