Register entry, as of 24 November 2026 Listed for sale Record ID f72ea5896181

2010 Pontiac G5

2.2 L, 4 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1G2	AD5F5	2	A	7	113440
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Pontiac · GENERAL MOTO…	G5 · 2.2 L	Verified	2010	Lordstown	Build sequence

§1 IDENTITY [1]

Model year	2010	Engine	2.2 L, 4 cylinders
Make	Pontiac	Fuel	Gasoline
Model	G5	Drive	Not in the decode
Trim	Not in the decode	Maker	GENERAL MOTORS LLC
Body	Sedan	Plant	Lordstown, Ohio, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/pontiac/g5/2010

4 recalls listed by Transport Canada for this model year

Steering

2015010 9 Jan 2015

Certain vehicles equipped with electric power steering may experience a sudden loss of power steering assist that could occur at any time while driving. If the power steering assist is lost, a message is displayed on the Driver Information Centre and a chime sounds to inform the driver. Steering control can be maintained, as the vehicle will revert to a manual steering mode, but will require greater driver effort. The sudden change in steering may increase the risk of a crash causing injury and/or property damage. Correction: Dealers will affect repairs as necessary. Note: This recall is an expansion of recall 2014-104 for vehicles that may have received defective parts through prior servicing for recall 2010-059.

Other

2014126 10 Apr 2014

On certain vehicles, a defect may allow the ignition key to be removed from the ignition switch when the key is not in the "Off" position. This could result in unintended vehicle movement if the transmission is not in the "park" position (automatic transmission) or not in the reverse gear with the parking brake engaged (manual transmission), and increase the risk of a crash causing injury and/or property damage. Correction: Dealers will replace the ignition lock cylinder and/or ignition key.

Other

2014101 31 Mar 2014

A safety defect may exist in ignition switches sold as service replacement parts. The defect could allow the ignition switch to unintentionally move from the “run” position to the “accessory” or “off” position with a corresponding reduction or loss of power. This risk may be increased if the key ring is carrying added weight or the vehicle goes off road or experiences some other jarring event. The timing of the key movement out of the “run” position, relative to the activation of the sensing algorithm of the crash event, may result in the airbags not deploying, increasing the potential for occupant injury in certain kinds of crashes. General Motors Canada will notify owners of all vehicles not affected by recalls 2014038 (GM number 13454) and 2014060 (GM number 14063) that could potentially have had the affected ignition switches installed during service or repair work. Owners will be instructed to take their vehicle to a dealer for inspection and repair if required. Note: Until the inspection is performed, all items should be removed from the key ring.

Steering

2010059 2 Mar 2010

Certain vehicles equipped with electric power steering may experience a sudden loss of power steering assist that could occur at any time while driving. If the power steering assist is lost, a message is displayed on the Driver Information Centre and a chime sounds to inform the driver. Steering control can be maintained, as the vehicle will revert to a manual steering mode, but will require greater driver effort. The sudden change in steering may increase the risk of a crash causing property damage, personal injury or death. Correction: Dealers will replace the electric power steering motor.

> Listed for the model year, not checked against your VIN. Pontiac confirms which apply.
> Check your VIN with GM Canada or call a Pontiac dealer with your VIN.
> experience.gm.ca/en/ownercenter/recalls

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $3,898[5], $550 under the median of $4,448[4].



Lowest ask	$3,898
Middle half	$4,173 – $4,724
Median ask	$4,448
This car	$3,898

Same model year · 2 live listings · as of 23 Nov 2026

OTHER 2010 PONTIAC G5 LISTINGS [5]

Windsor, ON · 183,000 km	$4,999

§4 EVENTS

2010	Model year 2010[1] Assembly plant Lordstown, Ohio, United States
2 Mar 2010	Transport Canada recall 2010059[2] Issued for the model year · Steering
31 Mar 2014	Transport Canada recall 2014101[2] Issued for the model year · Other
10 Apr 2014	Transport Canada recall 2014126[2] Issued for the model year · Other
9 Jan 2015	Transport Canada recall 2015010[2] Issued for the model year · Steering
9 Nov 2026	Listed for sale, Kitchener, ON[5] WENDELL MOTORS · asking $3,898
22 Nov 2026	Listing last updated[5] asking $3,898

§5 DOCUMENTS

Window sticker	This VIN reads as model year 1980 or 2010, before our coverage for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 2 live listings, as of 23 Nov 2026

[5] Live public dealer listings on Cardog, as of 24 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.