Register entry, as of 28 October 2026 Listed for sale Record ID 32390aebc73a

# 2007 Pontiac Solstice

2.4 L, 4 cylinders · Convertible · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 1G2 | MB35B | 0 | 7 | Y | 136720 |
|---|---|---|---|---|---|
| WMI 1-3 | DESCRIPTOR 4-8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12-17 |
| Pontiac · GENERAL MOTO… | Solstice · 2.4 L | Verified | 2007 | Wilmington | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2007 | Engine | 2.4 L, 4 cylinders |
| Make | Pontiac | Fuel | Gasoline |
| Model | Solstice | Drive | Not in the decode |
| Trim | Not in the decode | Maker | GENERAL MOTORS LLC |
| Body | Convertible | Plant | Wilmington, Delaware, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/pontiac/solstice/2007

**4** recalls listed by Transport Canada for this model year

### Airbag

2017044 27 Jan 2017

On certain vehicles, over time, the flexible sensor mat of passenger airbag suppression system (PPS) within the passenger seat can bend and become damaged. If this were to occur, the damage can potentially cause the PPS module to suppress the front passenger airbag during a crash. If fault exists in the PPS system and the vehicle is involved in a crash where airbag deployment is warranted, the front passenger airbag may not deploy, which if an adult is occupying the passenger seat, could increase the risk of injury to the occupant. Correction: Dealers will inspect the PPS sensor mat for damage and add a reinforcement strip to the sensor mat if no damage is found. If damage is found, the PPS sensor mat will be replaced and reinforcement strips added. Note: If an active fault exists in the PPS system, the airbag malfunction-indicator lamp will illuminate and the passenger airbag telltale will indicate that the airbag is off. Additionally, the driver information center will display a “Service Airbag” message, and the audio system will play an audible warning chime.

### Other

2014126 10 Apr 2014

On certain vehicles, a defect may allow the ignition key to be removed from the ignition switch when the key is not in the "Off" position. This could result in unintended vehicle movement if the transmission is not in the "park" position (automatic transmission) or not in the reverse gear with the parking brake engaged (manual transmission), and increase the risk of a crash causing injury and/or property damage. Correction: Dealers will replace the ignition lock cylinder and/or ignition key.

### Electrical

2014060 26 Feb 2014

On certain vehicles, a defect in the ignition switch could allow the switch to move out of the "run" position if the key ring is carrying added weight and the vehicle goes off-road or is subjected to some other jarring event. The timing of the key movement out of the “run” position, relative to the activation of the sensing algorithm of the crash event, may result in the airbags not deploying, increasing the risk of injury. Correction: Dealers will replace the ignition switch. Note: Until the correction is performed, all items should be removed from the key ring. Note: This is an expansion of recall 2014-038.

### Powertrain

2007417 19 Dec 2007

On certain vehicles, the drive axle differential seal may leak (note that all-wheel drive vehicles have two seals). Reduced lubrication may cause the differential to become noisier. Continued use may cause damage to bearings and other differential components. Three conditions could occur: 1). When the vehicle is stopped and shifted to reverse, the differential may jam and prevent vehicle movement. 2). the damage can cause drag that will feel like the parking brake is applied; or 3) the differential could jam and lock the drive wheels while the vehicle is underway. Should the latter occur, it could result in a loss of vehicle control and a crash, causing injury or death. Correction: Dealers will replace the drive axle differential seal(s).

Listed for the model year, not checked against your VIN. Pontiac confirms which apply.
Check your VIN with GM Canada or call a Pontiac dealer with your VIN.
experience.gm.ca/en/ownercenter/recalls

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $10,999[5], $502 over the median of $10,497[4].

| | |
|---|---|
| Lowest ask | $4,995 |
| Middle half | $8,122 – $11,982 |
| Median ask | $10,497 |
| This car | $10,999 |

Same model year · 8 live listings · as of 28 Oct 2026

OTHER 2007 PONTIAC SOLSTICE LISTINGS [5]

| | |
|---|---|
| Victoriaville, QC · 91,457 km | $9,995 |
| Victoriaville, QC · 91,457 km | $9,995 |
| Wyoming, ON · 59,609 km | $11,995 |
| Victoriaville, QC · 91,457 km | $9,995 |
| Victoriaville, QC · 91,457 km | $9,995 |
| Lévis, QC · 165,000 km | $4,995 |

## §4 EVENTS

| | |
|---|---|
| 2007 | Model year 2007[1]<br>Assembly plant Wilmington, Delaware, United States |
| 19 Dec 2007 | Transport Canada recall 2007417[2]<br>Issued for the model year · Powertrain |
| 26 Feb 2014 | Transport Canada recall 2014060[2]<br>Issued for the model year · Electrical |
| 10 Apr 2014 | Transport Canada recall 2014126[2]<br>Issued for the model year · Other |
| 27 Jan 2017 | Transport Canada recall 2017044[2]<br>Issued for the model year · Airbag |

| | |
|---|---|
| 25 Oct 2026 | Listed for sale, Val-David, QC[5]<br>Mazda Val-David Inc. · asking $10,999 |
| 27 Oct 2026 | Listing last updated[5]<br>asking $10,999 |

## §5 DOCUMENTS

Window sticker — This VIN reads as model year 2007, before our coverage for this manufacturer.

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 8 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.