Register entry, as of 26 October 2026 Listed for sale Record ID f271853d7331

2007 Pontiac G6 SE1

3.5 L, 6 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1G2	ZG58N	8	7	4	247015
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Pontiac · GENERAL MOTO…	G6 · 3.5 L	Verified	2007	Orion	Build sequence

§1 IDENTITY [1]

Model year	2007	Engine	3.5 L, 6 cylinders
Make	Pontiac	Fuel	Gasoline
Model	G6	Drive	Not in the decode
Trim	SE1	Maker	GENERAL MOTORS LLC
Body	Sedan	Plant	Orion, Michigan, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/pontiac/g6/2007

4 recalls listed by Transport Canada for this model year

Steering

2015048 4 Feb 2015

Certain vehicles equipped with electric power steering may experience a sudden loss of power steering assist that could occur at any time while driving. If the power steering assist is lost, a message is displayed on the Driver Information Centre and a chime sounds to inform the driver. Steering control can be maintained, as the vehicle will revert to a manual steering mode, but will require greater driver effort. The sudden change in steering may increase the risk of a crash causing injury and/or property damage. Correction: Dealers will replace the torque sensor assembly with a redesigned one. Note: This recall is an expansion of recalls 2012-331 and 2014-104. Vehicles having already been repaired under the previous campaigns do not require re-inspection.

Electrical

2014173 16 May 2014

On certain vehicles, intermittent electrical connection faults may cause the brake lamps to illuminate without the brake pedal being depressed, or not illuminate when the brake pedal is depressed. This could also interfere with cruise control, ABS and/or vehicle stability control function. Failure of the brake lights to illuminate when the brake pedal is depressed or erratic brake lamp function could increase the risk of a crash causing property damage and/or personal injury. Correction: Dealers will affect repairs.

Powertrain

2014160 1 May 2014

On certain vehicles equipped with 4 speed automatic transmissions, the shift cable could fracture without warning. If this occurs, the driver may not be able to select a different gear position, remove the key from the ignition, or place the transmission in the PARK position. If the driver cannot place the vehicle in the PARK position and exits the vehicle without applying the parking brake, the vehicle could roll away, which could result in a crash causing injury and/or damage to property. Correction: Dealers will install a revised shift cable and mounting bracket.

Airbag

2007103 29 Mar 2007

On certain vehicles, incorrect airbag passenger sensing system calibration could cause the right front airbag to deploy when not intended. This system is designed to turn the right front airbag off when a child occupies that seating position. If the passenger sensing system misclassifies a child or child restraint seat as an adult, the frontal airbag would deploy in a crash and the child could be killed or seriously injured by the airbag. Correction: Dealers will replace the passenger sensing system.

> Listed for the model year, not checked against your VIN. Pontiac confirms which apply.
> Check your VIN with GM Canada or call a Pontiac dealer with your VIN.
> experience.gm.ca/en/ownercenter/recalls

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $3,495[5], $523 over the median of $2,972[4].



Lowest ask	$2,450
Middle half	$2,711 – $3,234
Median ask	$2,972
This car	$3,495

Same model year · 2 live listings · as of 26 Oct 2026

OTHER 2007 PONTIAC G6 LISTINGS [5]

Belmont, ON · 208,041 km	$2,450

§4 EVENTS

2007	Model year 2007[1] Assembly plant Orion, Michigan, United States
29 Mar 2007	Transport Canada recall 2007103[2] Issued for the model year · Airbag
1 May 2014	Transport Canada recall 2014160[2] Issued for the model year · Powertrain
16 May 2014	Transport Canada recall 2014173[2] Issued for the model year · Electrical
4 Feb 2015	Transport Canada recall 2015048[2] Issued for the model year · Steering
25 Oct 2026	Listed for sale, St. Catharines, ON[5] Eastway Auto Service Ltd · asking $3,495
26 Oct 2026	Listing last updated[5] asking $3,495

§5 DOCUMENTS

Window sticker	This VIN reads as model year 2007, before our coverage for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 2 live listings, as of 26 Oct 2026
[5] Live public dealer listings on Cardog, as of 26 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.