Register entry, as of 29 October 2026 Listed for sale Record ID 17b82807b4ad

2006 Pontiac G6 GT

3.5 L, 6 cylinders · Convertible · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1G2	ZH358	0	6	4	262459
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Pontiac · GENERAL MOTO…	G6 · 3.5 L	Verified	2006	Orion	Build sequence

§1 IDENTITY [1]

Model year	2006	Engine	3.5 L, 6 cylinders
Make	Pontiac	Fuel	Gasoline
Model	G6	Drive	Not in the decode
Trim	GT	Maker	GENERAL MOTORS LLC
Body	Convertible	Plant	Orion, Michigan, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/pontiac/g6/2006

6 recalls listed by Transport Canada for this model year

Steering

2015048 4 Feb 2015

Certain vehicles equipped with electric power steering may experience a sudden loss of power steering assist that could occur at any time while driving. If the power steering assist is lost, a message is displayed on the Driver Information Centre and a chime sounds to inform the driver. Steering control can be maintained, as the vehicle will revert to a manual steering mode, but will require greater driver effort. The sudden change in steering may increase the risk of a crash causing injury and/or property damage. Correction: Dealers will replace the torque sensor assembly with a redesigned one. Note: This recall is an expansion of recalls 2012-331 and 2014-104. Vehicles having already been repaired under the previous campaigns do not require re-inspection.

Electrical

2014173 16 May 2014

On certain vehicles, intermittent electrical connection faults may cause the brake lamps to illuminate without the brake pedal being depressed, or not illuminate when the brake pedal is depressed. This could also interfere with cruise control, ABS and/or vehicle stability control function. Failure of the brake lights to illuminate when the brake pedal is depressed or erratic brake lamp function could increase the risk of a crash causing property damage and/or personal injury. Correction: Dealers will affect repairs.

Powertrain

2014160 1 May 2014

On certain vehicles equipped with 4 speed automatic transmissions, the shift cable could fracture without warning. If this occurs, the driver may not be able to select a different gear position, remove the key from the ignition, or place the transmission in the PARK position. If the driver cannot place the vehicle in the PARK position and exits the vehicle without applying the parking brake, the vehicle could roll away, which could result in a crash causing injury and/or damage to property. Correction: Dealers will install a revised shift cable and mounting bracket.

Steering

2014104 1 Apr 2014

Certain vehicles equipped with electric power steering may experience a sudden loss of power steering assist that could occur at any time while driving. If the power steering assist is lost, a message is displayed on the Driver Information Centre and a chime sounds to inform the driver. Steering control can be maintained, as the vehicle will revert to a manual steering mode, but will require greater driver effort. The sudden change in steering may increase the risk of a crash causing injury and/or property damage. Correction: Dealers will affect repairs as necessary. Note: This recall supersedes recalls 2010447 and 2012331. Vehicles having already been repaired under the previous campaigns do not require re-inspection.

Steering

2012331 1 Oct 2012

Certain vehicles equipped with electric power steering may experience a sudden loss of power steering assist that could occur at any time while driving. If the power steering assist is lost, a message is displayed on the Driver Information Centre and a chime sounds to inform the driver. Steering control can be maintained, as the vehicle will revert to a manual steering mode, but requires greater driver effort at low vehicle speeds. Unless a driver compensates for this additional steering effort, loss of power steering assist may increase the risk of a crash causing property damage and/or personal injury. Correction: Vehicles will receive a special extended warranty coverage for a period of 10 years/240,000 km, whichever occurs first, from the date the vehicle was originally placed in service, regardless of ownership. Under this special coverage program, for 2005 & 2006 model year vehicles, dealers will replace the steering column. For 2008 model year vehicles, dealers will replace the power steering motor control module.

Lights and instruments

2009023 27 Jan 2009

On certain vehicles, the brake lamps may not operate properly due to fretting corrosion in the Body Control Module (BCM) C2 wiring connector. Corrosion in the connector could cause the brake lamps to illuminate when the brake pedal has not been depressed, or cause them to not illuminate at all. Failure of the brake lamps to illuminate when the brake pedal is depressed may result in the following road users being unaware of the driver's intentions, as well as reducing vehicle conspicuity during hours of darkness. This could result in a vehicle crash causing personal injury or death. Correction: Dealers will apply a dielectric lubricant to repair and prevent corrosion inside the wiring connector.

> Listed for the model year, not checked against your VIN. Pontiac confirms which apply.
> Check your VIN with GM Canada or call a Pontiac dealer with your VIN.
> experience.gm.ca/en/ownercenter/recalls

United States: 7 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $3,966[5], $736 over the median of $3,230[4].

Lowest ask	$1,654
Middle half	$2,285 – $3,974
Median ask	$3,230
This car	$3,966

Same model year · 4 live listings · as of 29 Oct 2026

OTHER 2006 PONTIAC G6 LISTINGS [5]

Grande Prairie, AB · 288,780 km	$1,854
Prince George, BC · 188,625 km	$3,999
Grande Prairie, AB · 288,780 km	$1,654
Grande Prairie, AB · 288,780 km	$1,654
Grande Prairie, AB · 288,780 km	$1,854
Grande Prairie, AB · 288,780 km	$1,854

§4 EVENTS

2006	Model year 2006[1] Assembly plant Orion, Michigan, United States
27 Jan 2009	Transport Canada recall 2009023[2] Issued for the model year · Lights and instruments
1 Oct 2012	Transport Canada recall 2012331[2] Issued for the model year · Steering
1 Apr 2014	Transport Canada recall 2014104[2] Issued for the model year · Steering
1 May 2014	Transport Canada recall 2014160[2] Issued for the model year · Powertrain
16 May 2014	Transport Canada recall 2014173[2] Issued for the model year · Electrical
4 Feb 2015	Transport Canada recall 2015048[2] Issued for the model year · Steering
28 Oct 2026	Listed for sale, Longueuil, QC[5] Les Specialistes du Financement · asking $3,966

§5 DOCUMENTS

Window sticker	This VIN reads as model year 2006, before our coverage for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 4 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.