

Register entry, as of 27 October 2026

Listed for sale

Record ID 38638cbd3b89

2012 Buick LaCrosse Convenience

3.6 L, 6 cylinders · FWD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1G4 GB5E3 4 C F 131440

WMI 1-3

Buick · GENERAL MOTORS...

DESCRIPTOR 4-8

LaCrosse · 3.6 L

CHECK 9

Verified

YEAR 10

2012

PLANT 11

Kansas City

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2012	Engine	3.6 L, 6 cylinders
Make	Buick	Fuel	Gasoline
Model	LaCrosse	Drive	FWD
Trim	Convenience	Maker	GENERAL MOTORS LLC
Body	Sedan	Plant	Kansas City, Kansas, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/buick/lacrosse/2012

4 recalls listed by Transport Canada for this model year

Suspension

2020615 10 Dec 2020

Issue: On certain vehicles, the protective coating on the rear suspension toe links may chip away. If this happens, the metal can rust and the toe link could break. A broken toe link can affect vehicle stability and could cause a loss of directional control. Note: This recall only affects vehicles that were originally sold or ever registered in areas of heavy road salt usage (Manitoba, Ontario, Quebec, New Brunswick, Nova Scotia, Prince Edward Island, and Newfoundland & Labrador). Safety Risk: A loss of vehicle stability could cause a loss of control and increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and instruct you to take your vehicle to a dealer to replace the rear suspension toe links and adjuster fasteners.

Seats and restraints

2014311 23 Jul 2014

On certain vehicles equipped with power height adjustable front seats, a bolt securing the adjuster mechanism may loosen and fall out. This would cause the seat to drop to the lowest vertical adjustment position, which could affect the driver's ability to safely operate vehicle controls as well as cause reduced driver visibility. These issues could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the bolt.

Electrical

2013149 6 May 2013

On certain vehicles equipped with eAssist, the Generator Control Module (GCM) may not function correctly. This could cause a gradual loss of battery charge, which would illuminate the malfunction indicator lamp. Eventually, the engine may stall. In conjunction with traffic and road conditions, and the driver's reactions, this could increase the risk of a crash. In addition, there may be a burning or melting odour, smoke and possibly a fire in the trunk. These issues could result in property damage and/or personal injury. Correction: Dealers will inspect and, if necessary, replace the Generator Control Module.



Electrical

2011284 4 Aug 2011

On certain vehicles, the StabiliTrak System may have been incorrectly calibrated during the manufacturing process. As a result, the system may not properly detect a malfunctioning sensor, and the warning lamp (indicating that the system is not operating) may not illuminate. Failure to properly diagnose a malfunctioning sensor may cause the Electronic Control System (ESC) to falsely activate, resulting in sudden changes in vehicle handling and deceleration, particularly at higher speeds, which may cause the driver difficulty in maintaining the vehicle's desired path of travel and speed. This could result in a crash causing property damage and/or personal injury. Correction: Dealers will reprogram the electronic brake control module.

Listed for the model year, not checked against your VIN. Buick confirms which apply.
Check your VIN with Buick Canada or call a Buick dealer with your VIN.

www.buick.ca/en/ownercenter/recalls

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$12,995^[5], \$2,495 over the median of \$10,500^[4].



Lowest ask	\$9,999
Middle half	\$10,250 – \$11,748
Median ask	\$10,500
This car	\$12,995

Same model year · 3 live listings · as of 27 Oct 2026

OTHER 2012 BUICK LACROSSE LISTINGS [5]

Ingersoll, ON · 99,811 km	\$10,500
Oshawa, ON · 84,170 km	\$9,999

§4 EVENTS

2012	Model year 2012 ^[1] Assembly plant Kansas City, Kansas, United States
4 Aug 2011	Transport Canada recall 2011284 ^[2] Issued for the model year · Electrical
6 May 2013	Transport Canada recall 2013149 ^[2] Issued for the model year · Electrical
23 Jul 2014	Transport Canada recall 2014311 ^[2] Issued for the model year · Seats and restraints
10 Dec 2020	Transport Canada recall 2020615 ^[2] Issued for the model year · Suspension
25 Oct 2026	Listed for sale, Perth, ON ^[5] Callan Motors · asking \$12,995



27 Oct 2026 Listing last updated^[5]
asking \$12,995

§5 DOCUMENTS

Window sticker This VIN reads as model year 1982 or 2012, before our coverage for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 3 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

