

Register entry, as of 28 October 2026

Listed for sale

Record ID cd69c502acfb

2007 Buick Lucerne CXL

3.8 L, 6 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1G4 **HD572** **2** **7** **U** **123213**

WMI 1-3

Buick · GENERAL MOTORS...

DESCRIPTOR 4-8

Lucerne · 3.8 L

CHECK 9

Verified

YEAR 10

2007

PLANT 11

Detroit Hamtramck

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2007	Engine	3.8 L, 6 cylinders
Make	Buick	Fuel	Gasoline
Model	Lucerne	Drive	Not in the decode
Trim	CXL	Maker	GENERAL MOTORS LLC
Body	Sedan	Plant	Detroit Hamtramck, Michigan, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/buick/lucerne/2007

4 recalls listed by Transport Canada for this model year

Electrical

2014246 23 Jun 2014

On certain vehicles, a defect in the ignition switch could allow the switch to move out of the "run" position if the key ring is carrying added weight or the vehicle goes off-road or is subjected to some other jarring event. If this were to occur, engine power, power steering and power braking would be affected, increasing the risk of a crash causing injury and/or damage to property. The timing of the key movement out of the "run" position, relative to the activation of the sensing algorithm of the crash event, may also result in the airbags not deploying in a subsequent collision, increasing the risk of injury. Correction: For each key, dealers will install two key rings and modify the key ring opening shape. Note: Until the correction is performed, all items should be removed from the key ring.

Accessories

2010189 7 Jun 2010

On certain vehicles equipped with a Heated Washer Fluid System (HWFS), a short circuit on the printed circuit board for the washer fluid heater may overheat the control-circuit ground wire. A repair was implemented in a recall in 2008, however, there have been new reports of thermal incidents on heated washer fluid system modules after this improvement was installed. This situation may cause some minor distortion, but also could lead to melting of the plastic around the heated washer fluid system, or cause a fire. Correction: Dealers will permanently disable and remove the heated washer fluid module. An updated page will be provided and inserted in the Owner Manual to document the removal of the feature.

Other

2008313 29 Aug 2008

On certain vehicles equipped with a heated washer fluid system, a short circuit on the printed circuit board for the washer fluid heater may overheat the control-circuit ground wire. This situation may cause other electrical features to malfunction which could cause smoke and in some cases a fire. Correction: Dealer will install a wire harness with an in-line fuse.



Other

2007321 4 Oct 2007

Certain vehicles fail to conform with CMVSS 118 – Power-operated Roof Panels. The subject vehicles may exhibit a condition where the sunroof can be closed after the ignition is turned off and the doors are opened. Occupants could receive personal injury as a result of improper sunroof operation. Correction: Dealers will install a wire harness.

Listed for the model year, not checked against your VIN. Buick confirms which apply.
Check your VIN with Buick Canada or call a Buick dealer with your VIN.
www.buick.ca/en/ownercenter/recalls

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$4,995^[5], \$496 under the median of \$5,491^[4].



Lowest ask	\$4,995
Middle half	\$5,243 – \$5,739
Median ask	\$5,491
This car	\$4,995

Same model year · 2 live listings · as of 28 Oct 2026

OTHER 2007 BUICK LUCERNE LISTINGS [5]

Levis, QC · 170,000 km	\$5,987
Levis, QC · 170,000 km	\$5,987

§4 EVENTS

2007	Model year 2007 ^[1] Assembly plant Detroit Hamtramck, Michigan, United States
4 Oct 2007	Transport Canada recall 2007321 ^[2] Issued for the model year · Other
29 Aug 2008	Transport Canada recall 2008313 ^[2] Issued for the model year · Other
7 Jun 2010	Transport Canada recall 2010189 ^[2] Issued for the model year · Accessories
23 Jun 2014	Transport Canada recall 2014246 ^[2] Issued for the model year · Electrical
26 Oct 2026	Listed for sale, Powell River, BC ^[5] Massullo Motors Ltd. · asking \$4,995
28 Oct 2026	Listing last updated ^[5] asking \$4,995



§5 DOCUMENTS

Window sticker This VIN reads as model year 2007, before our coverage for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 2 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

