Register entry, as of 29 October 2026 Listed for sale Record ID 68793850e0db

2014 Buick Verano Base

2.4 L, 4 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1G4	PP5SK	1	E	4	121069
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Buick · GENERAL MOTORS…	Verano · 2.4 L	Verified	2014	Orion	Build sequence

§1 IDENTITY [1]

Model year	2014	Engine	2.4 L, 4 cylinders
Make	Buick	Fuel	Gasoline
Model	Verano	Drive	Not in the decode
Trim	Base	Maker	GENERAL MOTORS LLC
Body	Sedan	Plant	Orion, Michigan, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/buick/verano/2014

6 recalls listed by Transport Canada for this model year

Airbag

2025615 6 Nov 2025

Issue: On certain vehicles, the inflator for the side curtain airbag could rupture at the inflator weld joint and cause the side curtain airbag to inflate without a crash. Note: This is an expansion of Transport Canada recall nos. 2023-520 and 2023-693. Certain vehicles that were repaired under those recalls, also require this repair. Safety Risk: A side curtain airbag that inflates without a crash could create a risk of injury. Corrective Actions: General Motors will notify owners by mail and advise you to take your vehicle to a dealership to replace the left and/or right-side curtain airbag(s).

Airbag

2023693 21 Dec 2023

Issue: On certain vehicles, the inflator for the side curtain airbag could rupture at the inflator weld joint and cause the side curtain airbag to inflate without a crash. Note: This is an expansion of Transport Canada recall no. 2023-520. Safety Risk: A side curtain airbag that inflates without a crash could create a risk of injury. Corrective Actions: General Motors will notify owners by mail and advise you to take your vehicle to a dealership to replace the left and/or right-side curtain airbag(s).

Airbag

2023520 20 Sep 2023

Issue: On certain vehicles, the inflator for the side curtain airbag could rupture at the inflator weld joint and cause the side curtain airbag to inflate without a crash. Safety Risk: A side curtain airbag that inflates without a crash could create a risk of injury. Corrective Actions: General Motors will notify owners by mail and advise you to take your vehicle to a dealership to replace the left and/or right-side curtain airbag(s).

Electrical

2014480 29 Oct 2014

Certain vehicles may fail to conform to Canada Motor Vehicle Safety Standard (CMVSS) 114 - Theft Protection and Rollaway Prevention. An intermittent ground electrical connection could cause the vehicle to continue to run for a limited time period after the ignition is turned off if the brake lamps, park lamps or trunk lamp are on. This would also cause delayed arming of the immobilization system, contrary to the requirements of the standard. Correction: A production change has been undertaken to remedy this technical non-compliance condition. No corrective recall action is required as the technical non-compliance conditions are deemed to be non-safety related.

Accessories

2014274 3 Jul 2014

On certain vehicles, insulation on the engine block heater power cord may become damaged if the cord is handled during very cold days (temperatures below -25C). This could create an electrical shock hazard, which could result in personal injury. Correction: Dealers will replace the block heater cord.

Powertrain

2014054 25 Feb 2014

Certain vehicles equipped with automatic transmissions may fail to conform to Canada Motor Vehicle Safety Standard (CMVSS) 102 - Transmission Control Functions and CMVSS 114 - Theft Protection and Rollaway Prevention. The shift cable adjuster may have been damaged at time of assembly and could disengage, causing the transmission to remain in a gear position different from the one indicated in the instrument panel. If the shift cable were to disengage while driving, upon stopping the vehicle, a driver could move the transmission range selector lever to the PARK position and remove the key, without the transmission being in PARK. If the parking brake is not set, the vehicle could roll, potentially resulting in a crash increasing the risk of injury and/or property damage. Correction: Dealers will inspect and install a revised adjuster and clip if necessary.

> Listed for the model year, not checked against your VIN. Buick confirms which apply.
> Check your VIN with Buick Canada or call a Buick dealer with your VIN.
> www.buick.ca/en/ownercenter/recalls

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $6,995[5], $699 under the median of $7,694[4].



Lowest ask	$5,995
Middle half	$7,492 – $8,718
Median ask	$7,694
This car	$6,995

Same model year · 6 live listings · as of 29 Oct 2026

OTHER 2014 BUICK VERANO LISTINGS [5]

Newmarket, ON · 182,164 km	$7,490
London, ON · 179,100 km	$7,888
Montreal, QC · 161,905 km	$7,500
Cambridge, ON · 147,509 km	$8,999
Amos, QC · 125,276 km	$8,995
Ottawa, ON · 170,900 km	$5,995

§4 EVENTS

2014	Model year 2014[1] Assembly plant Orion, Michigan, United States
25 Feb 2014	Transport Canada recall 2014054[2] Issued for the model year · Powertrain
3 Jul 2014	Transport Canada recall 2014274[2] Issued for the model year · Accessories
29 Oct 2014	Transport Canada recall 2014480[2] Issued for the model year · Electrical
20 Sep 2023	Transport Canada recall 2023520[2] Issued for the model year · Airbag
21 Dec 2023	Transport Canada recall 2023693[2] Issued for the model year · Airbag
6 Nov 2025	Transport Canada recall 2025615[2] Issued for the model year · Airbag
24 Oct 2026	Listed for sale, Stoney Creek, ON[5] Xpress Auto Sales · asking $6,995
25 Oct 2026	Listing last updated[5] asking $6,995

§5 DOCUMENTS

Window sticker	This VIN reads as model year 1984 or 2014, before our coverage for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 6 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.