Register entry, as of 28 October 2026 Listed for sale Record ID 1bc8c100e1a0

2016 Buick Verano Leather (1SL)

2.4 L, 4 cylinders · Sedan · Flexible Fuel Vehicle (FFV)

VEHICLE IDENTIFICATION NUMBER [1]

1G4	PS5SK	3	G	4	128459
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Buick · GENERAL MOTORS…	Verano · 2.4 L	Verified	2016	Orion	Build sequence

§1 IDENTITY [1]

Model year	2016	Engine	2.4 L, 4 cylinders
Make	Buick	Fuel	Flexible Fuel Vehicle (FFV)
Model	Verano	Drive	Not in the decode
Trim	Leather (1SL)	Maker	GENERAL MOTORS LLC
Body	Sedan	Plant	Orion, Michigan, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/buick/verano/2016

2 recalls listed by Transport Canada for this model year

Fuel system

2016396 10 Aug 2016

On certain vehicles equipped with a 2.0 litre turbocharged engine, the fuel line assembly may not have been routed properly due to a manufacturing error. This could cause the fuel lines to contact hot surfaces which could, over time, degrade the fuel lines and cause a leak. A fuel leak in the presence of an ignition source could result in a fire causing injury and/or damage to property. Correction : Dealers will replace the fuel line assembly.

Powertrain

2016341 30 Jun 2016

Certain vehicles may fail to conform to Canada Motor Vehicle Safety Standard (CMVSS) 114 - Theft Protection and Rollaway Prevention. The Electronic Park Lock (EPL) lever in the steering column electrical assembly may have been damaged during manufacturing. As a result, the ignition key could be removed when the vehicle's transmission is in a position other than park. This could cause unintended vehicle movement, increasing the risk of injury and/or property damage. Correction: Dealers will inspect the vehicle and, if necessary, replace the key cylinder lock housing.

> Listed for the model year, not checked against your VIN. Buick confirms which apply.
> Check your VIN with Buick Canada or call a Buick dealer with your VIN.
> www.buick.ca/en/ownercenter/recalls

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $7,900[5], $3,095 under the median of $10,995[4].

Lowest ask	$7,900
Middle half	$8,844 – $12,175
Median ask	$10,995
This car	$7,900

Same model year · 8 live listings · as of 28 Oct 2026

OTHER 2016 BUICK VERANO LISTINGS [5]

Québec, QC · 79,987 km	$10,995
North York, ON · 56,000 km	$11,900
Toronto, ON · 191,025 km	$8,999
Ottawa, ON · 53,381 km	$12,999
Mirabel, QC · 111,883 km	$8,377
Terrebonne, QC · 111,883 km	$8,677

§4 EVENTS

2016	Model year 2016[1] Assembly plant Orion, Michigan, United States
30 Jun 2016	Transport Canada recall 2016341[2] Issued for the model year · Powertrain
10 Aug 2016	Transport Canada recall 2016396[2] Issued for the model year · Fuel system
27 Oct 2026	Listed for sale, Whitby, ON[5] Whitby Oshawa Honda · asking $7,900

§5 DOCUMENTS

Window sticker	This VIN reads as model year 1986 or 2016, before our coverage for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 8 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.