

Register entry, as of 27 October 2026

Listed for sale

Record ID 9cf9874aaf1c

2014 Buick Verano Leather

2.4 L, 4 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1G4 PS5SK 4 E 4 119573

WMI 1-3

Buick · GENERAL MOTORS...

DESCRIPTOR 4-8

Verano · 2.4 L

CHECK 9

Verified

YEAR 10

2014

PLANT 11

Orion

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2014	Engine	2.4 L, 4 cylinders
Make	Buick	Fuel	Gasoline
Model	Verano	Drive	Not in the decode
Trim	Leather	Maker	GENERAL MOTORS LLC
Body	Sedan	Plant	Orion, Michigan, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/buick/verano/2014

6 recalls listed by Transport Canada for this model year

Airbag	2025615	6 Nov 2025
Issue: On certain vehicles, the inflator for the side curtain airbag could rupture at the inflator weld joint and cause the side curtain airbag to inflate without a crash. Note: This is an expansion of Transport Canada recall nos. 2023-520 and 2023-693. Certain vehicles that were repaired under those recalls, also require this repair. Safety Risk: A side curtain airbag that inflates without a crash could create a risk of injury. Corrective Actions: General Motors will notify owners by mail and advise you to take your vehicle to a dealership to replace the left and/or right-side curtain airbag(s).		
Airbag	2023693	21 Dec 2023
Issue: On certain vehicles, the inflator for the side curtain airbag could rupture at the inflator weld joint and cause the side curtain airbag to inflate without a crash. Note: This is an expansion of Transport Canada recall no. 2023-520. Safety Risk: A side curtain airbag that inflates without a crash could create a risk of injury. Corrective Actions: General Motors will notify owners by mail and advise you to take your vehicle to a dealership to replace the left and/or right-side curtain airbag(s).		
Airbag	2023520	20 Sep 2023
Issue: On certain vehicles, the inflator for the side curtain airbag could rupture at the inflator weld joint and cause the side curtain airbag to inflate without a crash. Safety Risk: A side curtain airbag that inflates without a crash could create a risk of injury. Corrective Actions: General Motors will notify owners by mail and advise you to take your vehicle to a dealership to replace the left and/or right-side curtain airbag(s).		



Electrical

2014480 29 Oct 2014

Certain vehicles may fail to conform to Canada Motor Vehicle Safety Standard (CMVSS) 114 – Theft Protection and Rollaway Prevention. An intermittent ground electrical connection could cause the vehicle to continue to run for a limited time period after the ignition is turned off if the brake lamps, park lamps or trunk lamp are on. This would also cause delayed arming of the immobilization system, contrary to the requirements of the standard. Correction: A production change has been undertaken to remedy this technical non-compliance condition. No corrective recall action is required as the technical non-compliance conditions are deemed to be non-safety related.

Accessories

2014274 3 Jul 2014

On certain vehicles, insulation on the engine block heater power cord may become damaged if the cord is handled during very cold days (temperatures below -25C). This could create an electrical shock hazard, which could result in personal injury. Correction: Dealers will replace the block heater cord.

Powertrain

2014054 25 Feb 2014

Certain vehicles equipped with automatic transmissions may fail to conform to Canada Motor Vehicle Safety Standard (CMVSS) 102 – Transmission Control Functions and CMVSS 114 – Theft Protection and Rollaway Prevention. The shift cable adjuster may have been damaged at time of assembly and could disengage, causing the transmission to remain in a gear position different from the one indicated in the instrument panel. If the shift cable were to disengage while driving, upon stopping the vehicle, a driver could move the transmission range selector lever to the PARK position and remove the key, without the transmission being in PARK. If the parking brake is not set, the vehicle could roll, potentially resulting in a crash increasing the risk of injury and/or property damage. Correction: Dealers will inspect and install a revised adjuster and clip if necessary.

Listed for the model year, not checked against your VIN. Buick confirms which apply.


Check your VIN with Buick Canada or call a Buick dealer with your VIN.

www.buick.ca/en/ownercenter/recalls

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$7,490^[5], \$398 under the median of \$7,888^[4].



Lowest ask	\$5,995
Middle half	\$7,242 – \$8,448
Median ask	\$7,888
This car	\$7,490

Same model year · 7 live listings · as of 27 Oct 2026

OTHER 2014 BUICK VERANO LISTINGS ^[5]

London, ON · 179,100 km	\$7,888
Montreal, QC · 161,905 km	\$7,900
Windsor, ON · 89,000 km	\$13,999
Stoney Creek, ON · 0 km	\$6,995
Cambridge, ON · 147,509 km	\$8,999
Amos, QC · 125,276 km	\$8,995



§4 EVENTS

2014	Model year 2014 ^[1] Assembly plant Orion, Michigan, United States
25 Feb 2014	Transport Canada recall 2014054 ^[2] Issued for the model year · Powertrain
3 Jul 2014	Transport Canada recall 2014274 ^[2] Issued for the model year · Accessories
29 Oct 2014	Transport Canada recall 2014480 ^[2] Issued for the model year · Electrical
20 Sep 2023	Transport Canada recall 2023520 ^[2] Issued for the model year · Airbag
21 Dec 2023	Transport Canada recall 2023693 ^[2] Issued for the model year · Airbag
6 Nov 2025	Transport Canada recall 2025615 ^[2] Issued for the model year · Airbag
26 Oct 2026	Listed for sale, Newmarket, ON ^[5] Auto House Newmarket · asking \$7,490
27 Oct 2026	Listing last updated ^[5] asking \$7,490

§5 DOCUMENTS

Window sticker This VIN reads as model year 1984 or 2014, before our coverage for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 7 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

