Register entry, as of 29 October 2026 Listed for sale Record ID 2e6966322e05

2017 Buick LaCrosse Essence

3.6 L, 6 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1G4	ZP5SS	X	H	U	164760
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Buick · GENERAL MOTORS…	LaCrosse · 3.6 L	Verified	2017	Detroit Hamtramck	Build sequence

§1 IDENTITY [1]

Model year	2017	Engine	3.6 L, 6 cylinders
Make	Buick	Fuel	Gasoline
Model	LaCrosse	Drive	Not in the decode
Trim	Essence	Maker	GENERAL MOTORS LLC
Body	Sedan	Plant	Detroit Hamtramck, Michigan, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/buick/lacrosse/2017

2 recalls listed by Transport Canada for this model year

Suspension

2017222 21 Apr 2017

On certain vehicles, the rear-suspension toe-links may have been installed incorrectly (i.e., in the reverse direction). If a toe-link is installed in this incorrect direction, the bolt at the outboard attachment could come loose and fall out over time, which could cause the toe-link to disconnect from the rear-suspension system. If a rear-suspension toe-link becomes disconnected, the driver may lose the ability to control the vehicle, which could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will inspect and reorient the toe-links as required.

Steering

2017097 24 Feb 2017

On certain vehicles, the cable seal of one or both of the electric power steering (EPS) connectors may not be properly seated which could allow water to enter and corrode the connections. This could lead to increased resistance in the EPS circuit which could result in intermittent or permanent loss of the steering assist. A loss of power steering assist could unexpectedly increase steering effort which would increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will ensure the connector is fully seated and secure it in place.

> Listed for the model year, not checked against your VIN. Buick confirms which apply.
> Check your VIN with Buick Canada or call a Buick dealer with your VIN.
> www.buick.ca/en/ownercenter/recalls

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $17,968[5], $1,473 over the median of $16,495[4].

Lowest ask	$11,988
Middle half	$14,425 – $18,156
Median ask	$16,495
This car	$17,968

Same model year · 8 live listings · as of 29 Oct 2026

OTHER 2017 BUICK LACROSSE LISTINGS [5]

Port Perry, ON · 72,572 km	$18,721
Sherbrooke, QC · 112,673 km	$11,988
Edmonton, AB · 185,000 km	$20,800
Dieppe, NB · 172,682 km	$14,900
Komoka, ON · 130,823 km	$16,995
Dunnville, ON · 141,319 km	$15,995

§4 EVENTS

2017	Model year 2017[1] Assembly plant Detroit Hamtramck, Michigan, United States
24 Feb 2017	Transport Canada recall 2017097[2] Issued for the model year · Steering
21 Apr 2017	Transport Canada recall 2017222[2] Issued for the model year · Suspension
28 Oct 2026	Listed for sale, Ajax, ON[5] Boyer Chevrolet Buick GMC Ajax Ltd · asking $17,968

§5 DOCUMENTS

Window sticker — This VIN reads as model year 1987 or 2017, before our coverage for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 8 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.