

Register entry, as of 28 October 2026

Listed for sale

Record ID 2ac44e4edc72

2019 Buick LaCrosse Avenir

3.6 L, 6 cylinders · AWD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1G4 **ZV5SS** **7** **K** **U** **124763**

WMI 1-3

Buick · GENERAL MOTORS...

DESCRIPTOR 4-8

LaCrosse · 3.6 L

CHECK 9

Verified

YEAR 10

2019

PLANT 11

Detroit Hamtramck

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2019	Engine	3.6 L, 6 cylinders
Make	Buick	Fuel	Gasoline
Model	LaCrosse	Drive	AWD
Trim	Avenir	Maker	GENERAL MOTORS LLC
Body	Sedan	Plant	Detroit Hamtramck, Michigan, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/buick/lacrosse/2019

2 recalls listed by Transport Canada for this model year

Powertrain 2020520 29 Oct 2020

Issue: On certain vehicles, the start-stop accumulator in the transmission may be missing bolts. As a result, transmission fluid could leak and eventually cause the transmission to stop working. If this happens, there could be a loss of power to the wheels. Safety Risk: A transmission fluid leak onto a hot surface can create the risk of a fire. Additionally, a loss of power to the wheels could increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the transmission start-stop accumulator. It will be replaced if any bolts are found missing.

Brakes 2018461 30 Aug 2018

On certain vehicles, a problem with the rear brake system may cause gas bubbles to form in the brake fluid. This could cause a soft brake pedal feel and a reduction in brake performance, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will bleed the rear brakes.

Listed for the model year, not checked against your VIN. Buick confirms which apply.

Check your VIN with Buick Canada or call a Buick dealer with your VIN.

www.buick.ca/en/ownercenter/recalls

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.^[3]



§3 VALUE [4]

Median ask \$32,888^[4] for same model year.



Lowest ask \$29,999

Middle half \$31,444 – \$33,385

Median ask \$32,888

This car US\$33,882

Same model year · 3 live listings · as of 28 Oct 2026

OTHER 2019 BUICK LACROSSE LISTINGS [5]

Ottawa, ON · 20,444 km	\$29,999
St Albert, AB · 57,291 km	\$32,888

§4 EVENTS

2019	Model year 2019 ^[1] Assembly plant Detroit Hamtramck, Michigan, United States
30 Aug 2018	Transport Canada recall 2018461 ^[2] Issued for the model year · Brakes
29 Oct 2020	Transport Canada recall 2020520 ^[2] Issued for the model year · Powertrain
4 Sep 2026	Listed for sale, Red Deer, AB ^[5] Red Deer Motors · asking US\$33,882
28 Oct 2026	Listing last updated ^[5] asking US\$33,882

§5 DOCUMENTS

Window sticker This VIN reads as model year 1989 or 2019, before our coverage for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN	[4] Cardog market quote, same model year, 3 live listings, as of 28 Oct 2026
[2] Transport Canada recall database, listed for the model year	[5] Live public dealer listings on Cardog, as of 28 Oct 2026
[3] NHTSA recall records (United States), listed for the model year	

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

