Register entry, as of 27 October 2026 Listed for sale Record ID 0f759c68c8a0

2006 Cadillac CTS

3.6 L, 6 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1G6	DP577	0	6	0	111141
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Cadillac · GENERAL MOTO…	CTS · 3.6 L	Verified	2006	Lansing - Grand River	Build sequence

§1 IDENTITY [1]

Model year	2006	Engine	3.6 L, 6 cylinders
Make	Cadillac	Fuel	Gasoline
Model	CTS	Drive	Not in the decode
Trim	Not in the decode	Maker	GENERAL MOTORS LLC
Body	Sedan	Plant	Lansing - Grand River, Michigan, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/cadillac/cts/2006

7 recalls listed by Transport Canada for this model year

Brakes

2015157 14 Apr 2015

On certain vehicles, originally sold, or currently registered in areas of heavy road salt usage during winter months (Ontario, Quebec, New Brunswick, Nova Scotia, Prince Edward Island, and Newfoundland & Labrador), the front brake hose fitting at the caliper may corrode. If the fitting corrodes significantly, the internal brake hose-tube interface may develop a leak or in some cases break, causing a sudden increase in braking distances which may lead to a crash causing injury and/or property damage. Correction: Dealers will replace both front brake hose assemblies. Note: This recall is an expansion of recall 2010-080.

Fuel system

2014381 9 Sep 2014

On certain vehicles, an electrical terminal on the fuel pump module may overheat and melt, potentially allowing fuel to leak and/or affecting fuel system pressure. Fuel leakage, in the presence of an ignition source, could result in a fire. Low fuel pressure as a result of the leak could also affect engine performance which could result in reduced engine power and/or stalling. These issues could increase the risk of injury and/or property damage. Correction: Dealers will replace the fuel module and fuel tank jumper harness.

Electrical

2014273 2 Jul 2014

On certain vehicles, there is a risk that some drivers may bump the ignition key with their knee and unintentionally move the key from out of the "run" position. If this were to occur, engine power, power braking and power steering would be affected, which would unexpectedly increase steering and brake pedal effort, potentially increasing stopping distances and the risk of a crash causing injury and/or damage to property. The timing of the key movement out of the "run" position, relative to the activation of the sensing algorithm of the crash event, may also result in the airbags not deploying in a subsequent collision, increasing the risk of injury. Correction: Dealers are to remove the key blade from the original flip key/transmitter assemblies provided with the vehicle, and provide two new keys and two key rings for every original key. Important note: Until the correction is performed, drivers should adjust their seat and steering column to allow clearance between their knee and the ignition key.

Airbag

2010458 20 Dec 2010

On certain vehicles, repeated flexing of the Passenger Sensing System mat in the front passenger seat may cause the mat to kink, bend, or fold. This flexing can break the connections in the mat. If this occurs, the front passenger airbag could become disabled. If the airbag becomes disabled, the passenger airbag status indicator on the rearview mirror will show that the airbag is OFF, the AIR BAG indicator will be illuminated, and a SERVICE AIR BAG message will appear in the Driver Information Centre. Failure of the passenger airbag to deploy during a crash (where deployment is warranted) could increase the risk of personal injuries to the seat occupant. Correction: Dealers will replace the Passenger Sensing System mat and the seat cushion in the front passenger seat of vehicles built between December 8, 2003 and August 31, 2004, as well as those built from June 6, 2005 to Feb 18, 2007. Owners of other 2005-2007 Cadillac CTS vehicles will be provided with a "special warranty coverage". Should this issue occur, GM will repair these vehicle free of charge up to 10 years or 192,000 km from first vehicle registration.

Brakes

2010080 16 Mar 2010

On certain vehicles, originally sold, or currently registered in areas of heavy road salt usage during winter months (Ontario, Quebec, New Brunswick, Nova Scotia, Prince Edward Island, and Newfoundland & Labrador), the front brake hose fitting at the caliper may corrode. If the fitting corrodes significantly, the internal brake hose-tube interface may develop a leak or in some cases break, causing a sudden increase in braking distances which may lead to a crash causing property damage, personal injury or death. Correction: Dealers will replace both front brake hose assemblies.

Powertrain

2007417 19 Dec 2007

On certain vehicles, the drive axle differential seal may leak (note that all-wheel drive vehicles have two seals). Reduced lubrication may cause the differential to become noisier. Continued use may cause damage to bearings and other differential components. Three conditions could occur: 1). When the vehicle is stopped and shifted to reverse, the differential may jam and prevent vehicle movement. 2). the damage can cause drag that will feel like the parking brake is applied; or 3) the differential could jam and lock the drive wheels while the vehicle is underway. Should the latter occur, it could result in a loss of vehicle control and a crash, causing injury or death. Correction: Dealers will replace the drive axle differential seal(s).

1 more on the model-year record, cardog.app/tools/recalls/cadillac/cts/2006

> Listed for the model year, not checked against your VIN. Cadillac confirms which apply.
> Check your VIN with Cadillac Canada or call a Cadillac dealer with your VIN.
> www.cadillaccanada.ca/en/ownercenter/recalls

United States: 7 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $9,977[5], the median[4].



Lowest ask	$9,977
Middle half	$9,977 – $9,977
Median ask	$9,977
This car	$9,977

Same model year · 1 live listings · as of 27 Oct 2026

§4 EVENTS

2006	Model year 2006[1] Assembly plant Lansing - Grand River, Michigan, United States
23 Jan 2006	Transport Canada recall 2006016[2] Issued for the model year · Fuel system

19 Dec 2007	Transport Canada recall 2007417[2] Issued for the model year · Powertrain
16 Mar 2010	Transport Canada recall 2010080[2] Issued for the model year · Brakes
20 Dec 2010	Transport Canada recall 2010458[2] Issued for the model year · Airbag
2 Jul 2014	Transport Canada recall 2014273[2] Issued for the model year · Electrical
9 Sep 2014	Transport Canada recall 2014381[2] Issued for the model year · Fuel system
14 Apr 2015	Transport Canada recall 2015157[2] Issued for the model year · Brakes
1 Aug 2026	Listed for sale, Kelowna, BC[5] Russo Auto Sales · asking $9,977
25 Oct 2026	Listing last updated[5] asking $9,977

§5 DOCUMENTS

Window sticker This VIN reads as model year 2006, before our coverage for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 1 live listings, as of 27 Oct 2026

[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.