Register entry, as of 27 October 2026 Listed for sale Record ID 62c1fae79d8f

2009 Cadillac CTS NAV

3.6 L, 6 cylinders · AWD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1G6	DT57V	0	9	0	112417
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Cadillac · GENERAL MOTO…	CTS · 3.6 L	Verified	2009	Lansing	Build sequence

§1 IDENTITY [1]

Model year	2009	Engine	3.6 L, 6 cylinders
Make	Cadillac	Fuel	Gasoline
Model	CTS	Drive	AWD
Trim	NAV	Maker	GENERAL MOTORS LLC
Body	Sedan	Plant	Lansing, Michigan, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/cadillac/cts/2009

4 recalls listed by Transport Canada for this model year

Electrical

2014273 2 Jul 2014

On certain vehicles, there is a risk that some drivers may bump the ignition key with their knee and unintentionally move the key from out of the "run" position. If this were to occur, engine power, power braking and power steering would be affected, which would unexpectedly increase steering and brake pedal effort, potentially increasing stopping distances and the risk of a crash causing injury and/or damage to property. The timing of the key movement out of the "run" position, relative to the activation of the sensing algorithm of the crash event, may also result in the airbags not deploying in a subsequent collision, increasing the risk of injury. Correction: Dealers are to remove the key blade from the original flip key/transmitter assemblies provided with the vehicle, and provide two new keys and two key rings for every original key. Important note: Until the correction is performed, drivers should adjust their seat and steering column to allow clearance between their knee and the ignition key.

Suspension

2011064 11 Feb 2011

On certain vehicles, a wax coating applied to the rear suspension toe link jam nuts may allow the nut(s) to loosen. Should this occur, a metallic clanking noise may be heard coming from the rear of the vehicle. Ignoring this warning could result in a further loosened toe link, which could eventually separate, allowing the rear wheel to turn inboard or outboard. If this were to happen, sudden changes in vehicle handling could occur, which could result in a crash causing property damage and/or personal injury. Correction: Dealers will clean all wax residue from the rear suspension toe link and install two new jam nuts. If required, the rear suspension toe link will be replaced.

Accessories

2010189 7 Jun 2010

On certain vehicles equipped with a Heated Washer Fluid System (HWFS), a short circuit on the printed circuit board for the washer fluid heater may overheat the control-circuit ground wire. A repair was implemented in a recall in 2008, however, there have been new reports of thermal incidents on heated washer fluid system modules after this improvement was installed. This situation may cause some minor distortion, but also could lead to melting of the plastic around the heated washer fluid system, or cause a fire. Correction: Dealers will permanently disable and remove the heated washer fluid module. An updated page will be provided and inserted in the Owner Manual to document the removal of the feature.

Airbag

2008403 10 Nov 2008

On certain vehicles, the software within the Passenger Sensing System may disable the front passenger airbag when it should be enabled or vice versa. Malfunction of the airbag system will increase the risk of personal injuries or death in certain crash conditions. Correction: Dealers will reprogram the passenger sensing module.

> Listed for the model year, not checked against your VIN. Cadillac confirms which apply.
> Check your VIN with Cadillac Canada or call a Cadillac dealer with your VIN.
> www.cadillaccanada.ca/en/ownercenter/recalls

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $10,995[5], $6,953 under the median of $17,948[4].

Lowest ask	$10,995
Middle half	$14,471 – $21,424
Median ask	$17,948
This car	$10,995

Same model year · 2 live listings · as of 27 Oct 2026

§4 EVENTS

2009	Model year 2009[1] Assembly plant Lansing, Michigan, United States
10 Nov 2008	Transport Canada recall 2008403[2] Issued for the model year · Airbag
7 Jun 2010	Transport Canada recall 2010189[2] Issued for the model year · Accessories
11 Feb 2011	Transport Canada recall 2011064[2] Issued for the model year · Suspension
2 Jul 2014	Transport Canada recall 2014273[2] Issued for the model year · Electrical
24 Oct 2026	Listed for sale, Calgary, AB[5] Fine Auto Zone · asking $10,995

27 Oct 2026	Listing last updated[5] asking $10,995

§5 DOCUMENTS

Window sticker	This VIN reads as model year 2009, before our coverage for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 2 live listings, as of 27 Oct 2026

[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.