

Register entry, as of 27 October 2026

Listed for sale

Record ID a8b9f265b75e

2000 Cadillac Deville Luxury (DHS)

4.6 L, 8 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1G6 KE54Y 9 Y U 308699

WMI 1-3

Cadillac · GENERAL MOTO...

DESCRIPTOR 4-8

Deville · 4.6 L

CHECK 9

Verified

YEAR 10

2000

PLANT 11

Hamtramck

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2000	Engine	4.6 L, 8 cylinders
Make	Cadillac	Fuel	Gasoline
Model	Deville	Drive	Not in the decode
Trim	Luxury (DHS)	Maker	GENERAL MOTORS LLC
Body	Sedan	Plant	Hamtramck, Michigan, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/cadillac/deville/2000

7 recalls listed by Transport Canada for this model year

Electrical	2014246	23 Jun 2014
On certain vehicles, a defect in the ignition switch could allow the switch to move out of the "run" position if the key ring is carrying added weight or the vehicle goes off-road or is subjected to some other jarring event. If this were to occur, engine power, power steering and power braking would be affected, increasing the risk of a crash causing injury and/or damage to property. The timing of the key movement out of the "run" position, relative to the activation of the sensing algorithm of the crash event, may also result in the airbags not deploying in a subsequent collision, increasing the risk of injury. Correction: For each key, dealers will install two key rings and modify the key ring opening shape. Note: Until the correction is performed, all items should be removed from the key ring.		
Seats and restraints	2002157	6 Sep 2002
On certain vehicles, the driver and/or front passenger lap and/or shoulder belt retractors may not lock up or remain locked up as designed during a crash in which the belt pretensioners deploy. In such a crash, this could result in an increased chance of injury for that occupant. Correction: The dealers will replace the driver and passenger pretensioners.		
Other	2001061	9 Mar 2001
Certain vehicles do not comply with the requirements of CMVSS 110 - Tire Selection and Rims. On the tire placard, the tire size designation is incomplete and the tire speed rating is wrong. Correction: Dealers will install a new tire pressure label on affected vehicles.		



Seats and restraints

2000272 20 Nov 2000

Certain vehicles do not comply with the requirements of CMVSS 209 – Seat Belt Assemblies. The push button release effort for the front outboard seat belts exceeds the maximum of 14 kilograms (30 pounds). After a crash, the higher release efforts could make it more difficult for an occupant to release the belt and exit the vehicle. Correction: Dealer will add "snap on" latch clips to eliminate the potential of inverted latch plate insertion. Dealers will inspect the seat belts and, if necessary, modify the latch plates with a special tool or replace the retractor.

Brakes

2000104 17 Apr 2000

Certain vehicles may have internal fluid leaks in the brake hydraulic control unit. When the rear brake proportioning, antilock brake, traction control, or stability control feature is activated in some driving situations, the feature may not perform as designed and the driver could lose vehicle control. Correction: ABS hydraulic modulator unit will be inspected and replaced if necessary.

Brakes

2000072 17 Mar 2000

On certain hearse and limousine vehicles, the right front brake hose may contact the wheel resulting in damage to the brake hose. A damaged hose can result in loss of brake fluid and a half system failure which in turn will cause a low brake pedal and increased stopping distances. Correction: Dealers will replace the right front brake hose assembly. The left front brake hose assembly will also be replaced to prevent the possibility of incorrect positioning of the hose during any future service.

1 more on the model-year record, cardog.app/tools/recalls/cadillac/deville/2000

Listed for the model year, not checked against your VIN. Cadillac confirms which apply.

Check your VIN with Cadillac Canada or call a Cadillac dealer with your VIN.

www.cadillaccanada.ca/en/ownercenter/recalls

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$9,888^[5], the median^[4].



Lowest ask	\$9,888
Middle half	\$9,888 – \$9,888
Median ask	\$9,888
This car	\$9,888

Same model year · 1 live listings · as of 27 Oct 2026

§4 EVENTS

2000	Model year 2000 ^[1] Assembly plant Hamtramck, Michigan, United States
16 Mar 2000	Transport Canada recall 2000067 ^[2] Issued for the model year · Engine
17 Mar 2000	Transport Canada recall 2000072 ^[2] Issued for the model year · Brakes
17 Apr 2000	Transport Canada recall 2000104 ^[2] Issued for the model year · Brakes



20 Nov 2000	Transport Canada recall 2000272 ^[2] Issued for the model year · Seats and restraints
9 Mar 2001	Transport Canada recall 2001061 ^[2] Issued for the model year · Other
6 Sep 2002	Transport Canada recall 2002157 ^[2] Issued for the model year · Seats and restraints
23 Jun 2014	Transport Canada recall 2014246 ^[2] Issued for the model year · Electrical
22 Feb 2026	Listed for sale, Scarborough, ON ^[5] SCARVIEW CHRYSLER DODGE JEEP · asking \$9,888
26 Oct 2026	Listing last updated ^[5] asking \$9,888

§5 DOCUMENTS

Window sticker This VIN reads as model year 2000, before our coverage for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 1 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

