

Register entry, as of 28 October 2026

Listed for sale

Record ID 001959825166

2004 Cadillac XLR

4.6 L, 8 cylinders · Convertible · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1G6 YV34A 3 4 5 601259

WMI 1-3

Cadillac · GENERAL MOTO...

DESCRIPTOR 4-8

XLR · 4.6 L

CHECK 9

Verified

YEAR 10

2004

PLANT 11

Bowling Green

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2004	Engine	4.6 L, 8 cylinders
Make	Cadillac	Fuel	Gasoline
Model	XLR	Drive	Not in the decode
Trim	Not in the decode	Maker	GENERAL MOTORS LLC
Body	Convertible	Plant	Bowling Green, Kentucky, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/cadillac/xlr/2004

4 recalls listed by Transport Canada for this model year

Lights and instruments 2006172 17 Jul 2006

On certain vehicles the bulb used for the Daytime Running Lights (DRL), turn signals, and parking lamps may burn out prematurely. Correction: Dealers will replace the socket and bulb in both lamps.

Other 2005034 15 Feb 2005

Certain vehicles do not comply with the requirements of CMVSS 124 - Accelerator Control Systems. The Electronic Throttle Control (ETC) accelerator pedal assembly may not return the engine to idle in three seconds or less at low ambient temperatures if either of the two throttle return springs is broken. Correction: Dealers will replace the ETC pedal assembly.

Brakes 2004389 29 Oct 2004

Certain vehicles were produced with one or both rear brake hydraulic lines that can come in contact with or be affected by heat from the left engine exhaust manifold and the left exhaust pipe. Also, on some 2005 vehicles, the crossover brake line to the right rear brake can come in contact with the rear differential case. In both cases, a half system brake failure could occur, resulting in increased stopping distances. Correction: Dealers will repair/reposition the rear brake lines.



Suspension

2004206 7 Jun 2004

Certain vehicles were produced with lower control arm ball stud nut/washer assemblies with washers made of the wrong steel material. The washers may fracture and become loose or fall away from the vehicle, reducing clamp load. Separation of the control arm ball stud and steering knuckle, due to disengagement of the tapered attachment and retaining nut, is possible and may occur without prior indication to the vehicle operator. If the control arm separates from the knuckle, the affected corner of the vehicle will drop and the control arm would be forced downward, contacting the wheel. The affected wheel could tilt outward and create a dragging action that would tend to slow the vehicle and create a tendency for the vehicle to turn in the direction of the affected wheel. In extreme situations, the affected wheel assembly could separate from the vehicle. Separation of the wheel assembly would also sever that wheel's hydraulic brake hose and result in diminished braking performance of the vehicle, which could result in a crash. Correction: Dealers will install a new nut and washer, and if required, replace the ball stud and/or steering knuckle.

Listed for the model year, not checked against your VIN. Cadillac confirms which apply.
Check your VIN with Cadillac Canada or call a Cadillac dealer with your VIN.
www.cadillaccanada.ca/en/ownercenter/recalls

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$32,995^[5], \$3,997 over the median of \$28,998^[4].



Lowest ask	\$25,000
Middle half	\$26,999 – \$30,996
Median ask	\$28,998
This car	\$32,995

Same model year · 2 live listings · as of 28 Oct 2026

OTHER 2004 CADILLAC XLR LISTINGS ^[5]

Moncton, NB · 96,304 km \$25,000

§4 EVENTS

2004	Model year 2004 ^[1] Assembly plant Bowling Green, Kentucky, United States
7 Jun 2004	Transport Canada recall 2004206 ^[2] Issued for the model year · Suspension
29 Oct 2004	Transport Canada recall 2004389 ^[2] Issued for the model year · Brakes
15 Feb 2005	Transport Canada recall 2005034 ^[2] Issued for the model year · Other
17 Jul 2006	Transport Canada recall 2006172 ^[2] Issued for the model year · Lights and instruments
29 Jul 2026	Listed for sale, Victoriaville, QC ^[5] Dubois Et Frères & Méthot GM · asking \$32,995



27 Oct 2026 Listing last updated^[5]
asking \$32,995

§5 DOCUMENTS

Window sticker This VIN reads as model year 2004, before our coverage for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 2 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

