

2007 Chevrolet Colorado Work Truck

3.7 L, 5 cylinders · 4WD · Pickup · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1GC DT19E 0 7 8 204581

WMI 1-3

Chevrolet · GENERAL MOT...

DESCRIPTOR 4-8

Colorado · 3.7 L

CHECK 9

Verified

YEAR 10

2007

PLANT 11

Shreveport

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2007	Engine	3.7 L, 5 cylinders
Make	Chevrolet	Fuel	Gasoline
Model	Colorado	Drive	4WD
Trim	Work Truck	Maker	GENERAL MOTORS LLC
Body	Pickup	Plant	Shreveport, Louisiana, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/chevrolet/colorado/2007

3 recalls listed by Transport Canada for this model year

Accessories

2014492 30 Oct 2014

*** This notice is provided for information purposes only as the subject equipment is not regulated under the Motor Vehicle Safety Act *** A safety defect may exist in aftermarket ACDelco brake shoes manufactured between April 1st 2013 to April 19 2014, sold and/or installed as service replacement parts. The lining of the rear brake shoe may detach from the steel shoe during normal service, causing the affected brake to fail. If the lining detaches from the steel shoe, it could cause rear-wheel lockup and it will reduce the available braking force which could lengthen the required stopping distance, and increase the risk of a crash without prior warning. Correction: GM Dealers, ACDelco warehouse distributors and their professional installer customers are to inspect the manufacture date of the rear brake shoes and, if necessary, replace the shoes. Customers of the 125 vehicles that were serviced by GM Dealers with the suspect parts will be notified by first class letter.

Seats and restraints

2010418 18 Nov 2010

Certain vehicles with regular or extended cab without a rear seat, and equipped with a front 60/40 split bench seat, fail to conform to Canada Motor Vehicle Safety Standard 210.1 – User-ready Tether Anchorages for Restraint Systems. The child restraint top tether anchor for the front centre seat position in these vehicles is not accessible as required by the Standard. Without the top tether anchor, a child restraint may not be properly secured in the vehicle. Correction: If requested by the customers, dealers will modify the back panel trim cover to allow access to the top tether anchor. In addition, owner letters will include an Owner Manual Supplement that describes how to install a child restraint using a top tether in the centre seating position.



Wheels

2006197 9 Aug 2006

Certain vehicles fail to comply with the requirements of CMVSS 120 – Tire rim designation. These vehicles have an incomplete tire rim designation indicated on the compliance label. If a customer replaces a wheel with one that has a rim contour that is inappropriate for use with the tires on the vehicle, the mounting of the tire to the wheel and/or the tire/wheel assembly may not perform as designed/intended. In addition, certain vehicles are also missing the tire load rating on the label. If a tire of a lesser load rating than the original tire is installed, the tire may not be able to sustain the loads encountered during use. Correction: Dealers will install a new partial label over the existing label. Corrected labels and application instructions will be mailed to customers. Dealers will receive labels for installation on the vehicles in inventory.

Listed for the model year, not checked against your VIN. Chevrolet confirms which apply.
Check your VIN with Chevrolet Canada or call a Chevrolet dealer with your VIN.

www.chevrolet.ca/en/ownercenter/recalls

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$4,995^[5], the median^[4].



Lowest ask	\$4,995
Middle half	\$4,995 – \$4,995
Median ask	\$4,995
This car	\$4,995

Same model year · 1 live listings · as of 28 Oct 2026

§4 EVENTS

2007	Model year 2007 ^[1] Assembly plant Shreveport, Louisiana, United States
9 Aug 2006	Transport Canada recall 2006197 ^[2] Issued for the model year · Wheels
18 Nov 2010	Transport Canada recall 2010418 ^[2] Issued for the model year · Seats and restraints
30 Oct 2014	Transport Canada recall 2014492 ^[2] Issued for the model year · Accessories
26 Oct 2026	Listed for sale, Trois-Rivières, QC ^[5] automobilesdenislefebvre.com · asking \$4,995
28 Oct 2026	Listing last updated ^[5] asking \$4,995

§5 DOCUMENTS

Window sticker This VIN reads as model year 2007, before our coverage for this manufacturer.



SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 1 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 29 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

