

Register entry, as of 28 October 2026

Listed for sale

Record ID 0132ac4fac5a

2010 Chevrolet Express

4.3 L, 6 cylinders · 4x2 · Cargo Van · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1GC **UGADX** **3** **A** **1** **102382**

WMI 1-3

Chevrolet · GENERAL MOT...

DESCRIPTOR 4-8

Express · 4.3 L

CHECK 9

Verified

YEAR 10

2010

PLANT 11

Wentzville

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2010	Engine	4.3 L, 6 cylinders
Make	Chevrolet	Fuel	Gasoline
Model	Express	Drive	4x2
Trim	Not in the decode	Maker	GENERAL MOTORS LLC
Body	Cargo Van	Plant	Wentzville, Missouri, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/chevrolet/express/2010

5 recalls listed by Transport Canada for this model year

Electrical

2023210 6 Apr 2023

Issue: On certain vehicles, an unused wiring harness for a rear HVAC blower motor, located in the left B-pillar area, could become damaged if exposed to moisture or contaminants. If this happens, the wires could short circuit. Note: This recall only affects cutaway chassis incomplete vehicles. Safety Risk: A short circuit can create the risk of a fire. Corrective Actions: General Motors will notify owners by mail and instruct you to bring your vehicle to a dealership to seal the wiring for the rear HVAC blower motor at the left B-pillar.

Seats and restraints

2014083 18 Mar 2014

Certain vehicles may not comply with the requirements of Canada Motor Vehicle Safety Standard 201 - Occupant Protection. During a frontal impact below the airbag deployment threshold, if an unbelted front passenger's head were to impact the instrument panel where the passenger airbag is located, it could decelerate at a rate higher than what is allowable by the standard. This could increase the risk of injury. Correction: Dealers will install energy absorbing trim pieces on the passenger side of the instrument panel, and on 2012-2014 model year 1500 series vehicles, dealers will also replace the front passenger seat belt retractor.

Electrical

2010231 15 Jul 2010

On certain Express and Savana 2500, 3500 and 4500 vehicles equipped with a 145 Amp alternator, a low resistance short could develop within the voltage regulator. In some cases, if the circuit does not open, the low resistance short could eventually generate enough heat to result in an engine compartment fire causing property damage or personal injury. Correction: Dealers will inspect and, if necessary, replace alternator. Note: This recall supersedes recall 2010106.



Electrical

2010106 6 Apr 2010

Certain vehicles equipped with a 145 amp alternator may develop a low resistance short within the voltage regulator. In some cases, if the circuit does not open, the low resistance short could eventually generate enough heat to result in an engine compartment fire causing property damage and/or personal injury. Correction: Dealers will inspect and, if necessary, replace the alternator. Note: This recall is superseded by recall 2010231.

Heater and defroster

2010072 11 Mar 2010

Certain vehicles were built with heating, ventilation, and air conditioning (HVAC) control knobs that may fracture and spin on the control shaft. If this happens, the driver may no longer be able to control the heating, cooling, and ventilation for the vehicle. This may affect the defrost system, decreasing driver visibility, and creating the risk of a crash causing property damage, personal injury or death. Correction: Dealers will replace all HVAC control knobs.

Listed for the model year, not checked against your VIN. Chevrolet confirms which apply.

Check your VIN with Chevrolet Canada or call a Chevrolet dealer with your VIN.

www.chevrolet.ca/en/ownercenter/recalls

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$12,800^[5], \$801 over the median of \$11,999^[4].



Lowest ask	\$7,800
Middle half	\$9,900 – \$12,400
Median ask	\$11,999
This car	\$12,800

Same model year · 3 live listings · as of 28 Oct 2026

OTHER 2010 CHEVROLET EXPRESS LISTINGS ^[5]

Surrey, BC · 269,685 km	\$7,800
Whitby, ON · 199,795 km	\$11,999

§4 EVENTS

2010	Model year 2010 ^[1] Assembly plant Wentzville, Missouri, United States
11 Mar 2010	Transport Canada recall 2010072 ^[2] Issued for the model year · Heater and defroster
6 Apr 2010	Transport Canada recall 2010106 ^[2] Issued for the model year · Electrical
15 Jul 2010	Transport Canada recall 2010231 ^[2] Issued for the model year · Electrical
18 Mar 2014	Transport Canada recall 2014083 ^[2] Issued for the model year · Seats and restraints



6 Apr 2023 Transport Canada recall 2023210^[2]
Issued for the model year · Electrical

26 Oct 2026 Listed for sale, Surrey, BC^[5]
AFK Auto Wholesaler Ltd · asking \$12,800

§5 DOCUMENTS

Window sticker This VIN reads as model year 1980 or 2010, before our coverage for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 3 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

