

Register entry, as of 28 October 2026

Listed for sale

Record ID 1e2fa2bc9bb2

2019 GMC Yukon SLT

6.2 L, 8 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER ^[1]**1GK**

WMI 1-3

GMC · GENERAL MOTORS...

S2BKJ

DESCRIPTOR 4-8

Yukon · 6.2 L

0

CHECK 9

Verified

K

YEAR 10

2019

R

PLANT 11

Arlington

359503

SERIAL 12-17

Build sequence

§1 IDENTITY ^[1]

Model year	2019	Engine	6.2 L, 8 cylinders
Make	GMC	Fuel	Gasoline
Model	Yukon	Drive	4WD
Trim	SLT	Maker	GENERAL MOTORS LLC
Body	Sport Utility Vehicle	Plant	Arlington, Texas, United States

§2 OBLIGATIONS ^[2]

cardog.app/tools/recalls/gmc/yukon/2019

1 recall listed by Transport Canada for this model year

Brakes

2019533 24 Oct 2019

Issue: On certain vehicles, there may be an error in the electronic-brake control module software. This could cause the driveline-protection system to activate when a wheel-speed sensor fails. If this happens, the brakes could apply and cause the vehicle to pull to one side. Note: This recall only affects vehicles equipped with four-wheel drive, a 5.3-L engine, and a 3.08 ratio rear axle. The problem can only occur when the vehicle is in four-wheel drive or automatic mode, and travelling at a speed between 66 and 97 km/h (41 and 60 mph). A wheel-speed sensor failure will cause the electronic stability control (ESC) and anti-lock braking system (ABS) warning lights to turn on, and a "Service StabiliTrak" message to display. Safety Risk: A vehicle that suddenly pulls to one side could increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and instruct you to take your vehicle to a dealer to update the electronic-brake control module software. General Motors advises that using two-wheel-drive mode can eliminate the risk until the recall repair is completed.

Listed for the model year, not checked against your VIN. GMC confirms which apply.

Check your VIN with GMC Canada or call a GMC dealer with your VIN.

www.gmccanada.ca/en/ownercenter/recalls

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.^[3]



§3 VALUE [4]

This car asks \$42,900^[5], \$1,641 over the median of \$41,259^[4].



Lowest ask	\$23,990
Middle half	\$36,121 – \$43,442
Median ask	\$41,259
This car	\$42,900

Same model year · 12 live listings · as of 28 Oct 2026

OTHER 2019 GMC YUKON LISTINGS [5]

Cranbrook, BC · 132,253 km	\$33,500
Saint John, NB · 187,893 km	\$31,995
Airdrie, AB · 98,140 km	\$43,900
Edmonton, AB · 421,129 km	\$24,999
Lethbridge, AB · 306,977 km	\$23,990
Calgary, AB · 98,140 km	\$43,900

§4 EVENTS

2019	Model year 2019 ^[1] Assembly plant Arlington, Texas, United States
24 Oct 2019	Transport Canada recall 2019533 ^[2] Issued for the model year · Brakes
26 Oct 2026	Listed for sale, Medicine Hat, AB ^[5] Davis GMC Buick Medicine Hat · asking \$42,900

§5 DOCUMENTS

Window sticker This VIN reads as model year 1989 or 2019, before our coverage for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN	[4] Cardog market quote, same model year, 12 live listings, as of 28 Oct 2026
[2] Transport Canada recall database, listed for the model year	[5] Live public dealer listings on Cardog, as of 28 Oct 2026
[3] NHTSA recall records (United States), listed for the model year	

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

