

# 2024 GMC Yukon XL Denali

6.2 L, 8 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

|                                    |                                    |                     |                 |                       |                                |
|------------------------------------|------------------------------------|---------------------|-----------------|-----------------------|--------------------------------|
| 1GK                                | S2JKL                              | 5                   | R               | R                     | 141322                         |
| WMI 1-3<br>GMC · GENERAL MOTORS... | DESCRIPTOR 4-8<br>Yukon XL · 6.2 L | CHECK 9<br>Verified | YEAR 10<br>2024 | PLANT 11<br>Arlington | SERIAL 12-17<br>Build sequence |

## §1 IDENTITY [1]

|            |                       |        |                                 |
|------------|-----------------------|--------|---------------------------------|
| Model year | 2024                  | Engine | 6.2 L, 8 cylinders              |
| Make       | GMC                   | Fuel   | Gasoline                        |
| Model      | Yukon XL              | Drive  | 4WD                             |
| Trim       | Denali                | Maker  | GENERAL MOTORS LLC              |
| Body       | Sport Utility Vehicle | Plant  | Arlington, Texas, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/gmc/yukon-xl/2024

### 3 recalls listed by Transport Canada for this model year

|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         |         |             |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|-------------|
| Engine                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  | 2025225 | 24 Apr 2025 |
| Issue: On certain vehicles, the connecting rods and/or crankshaft components may not have been manufactured properly. As a result, the engine could make abnormal noises and a warning light may turn on. If you continue to drive the vehicle with these symptoms, the engine could fail. Note: This recall only affects certain vehicles equipped with a 6.2 L V8 gas engine. Safety Risk: An engine failure could cause a sudden loss of power to the wheels and increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and advise you to take your vehicle to inspect and, if necessary, repair or replace the engine. For vehicles that pass the engine inspection, the dealer will replace the oil with a higher viscosity oil, install a new oil fill cap, replace the oil filter, and add an insert to the owner's manual. |         |             |
| Lights and instruments                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  | 2024519 | 12 Sep 2024 |
| Issue: On certain vehicles, a software problem could cause the low brake fluid warning lamp not to turn on if the brake fluid level gets too low. A low brake fluid level can cause reduced braking. Safety Risk: A driver that isn't aware of a low brake fluid level could experience reduced braking and an increased risk of a crash. Corrective Actions: General Motors will notify owners by mail and send a wireless over-the-air software update to eligible vehicles to update the electronic brake control module software. Alternatively, you may schedule an appointment to have the update performed at a GM dealership.                                                                                                                                                                                                                                   |         |             |
| Lights and instruments                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  | 2024060 | 1 Feb 2024  |
| Issue: On certain vehicles, a software problem could cause the lower beam headlamps not to turn on as it becomes dark outside if the multi-function switch is in the "OFF" or "PARKING LAMP" position. This could also cause the daytime running lamps (DRLs) to turn off when the vehicle is moving. As a result, the vehicles may not meet certain requirements of Canadian regulations. Safety Risk: Headlamps and/or DRLs that don't turn on could reduce visibility, make the vehicle less visible to others and increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and advise you to take your vehicle to a dealership to update the body control module (BCM) software.                                                                                                                                                 |         |             |



Listed for the model year, not checked against your VIN. GMC confirms which apply.  
Check your VIN with GMC Canada or call a GMC dealer with your VIN.  
[www.gmccanada.ca/en/ownercenter/recalls](http://www.gmccanada.ca/en/ownercenter/recalls)

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.<sup>[3]</sup>

### §3 VALUE <sup>[4]</sup>

This car asks \$84,900<sup>[5]</sup>, \$8,027 over the median of \$76,873<sup>[4]</sup>.



|             |                     |
|-------------|---------------------|
| Lowest ask  | \$55,998            |
| Middle half | \$70,745 – \$85,325 |
| Median ask  | \$76,873            |
| This car    | \$84,900            |

Same model year · 24 live listings · as of 28 Oct 2026

#### OTHER 2024 GMC YUKON XL LISTINGS <sup>[5]</sup>

|                           |          |
|---------------------------|----------|
| Windsor, ON · 71,142 km   | \$75,751 |
| Vancouver, BC · 45,994 km | \$89,999 |
| Renfrew, ON · 87,013 km   | \$68,691 |
| Grimsby, ON · 56,214 km   | \$74,995 |
| Brampton, ON · 68,232 km  | \$70,995 |
| Brampton, ON · 82,121 km  | \$69,995 |

### §4 EVENTS

|             |                                                                                                      |
|-------------|------------------------------------------------------------------------------------------------------|
| 2024        | Model year 2024 <sup>[1]</sup><br>Assembly plant Arlington, Texas, United States                     |
| 1 Feb 2024  | Transport Canada recall 2024060 <sup>[2]</sup><br>Issued for the model year · Lights and instruments |
| 12 Sep 2024 | Transport Canada recall 2024519 <sup>[2]</sup><br>Issued for the model year · Lights and instruments |
| 24 Apr 2025 | Transport Canada recall 2025225 <sup>[2]</sup><br>Issued for the model year · Engine                 |
| 25 Oct 2026 | Listed for sale, Squamish, BC <sup>[5]</sup><br>Greg Gardner GM · asking \$84,900                    |
| 28 Oct 2026 | Listing last updated <sup>[5]</sup><br>asking \$84,900                                               |

### §5 DOCUMENTS

Window sticker      We have not collected this label yet.



---

**SOURCES**

- |                                                                     |                                                                               |
|---------------------------------------------------------------------|-------------------------------------------------------------------------------|
| [1] Cardog identity register, decoded from the VIN                  | [4] Cardog market quote, same model year, 24 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year     |                                                                               |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026                  |

---

**STATEMENT OF SCOPE**

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

