Register entry, as of 29 October 2026 Listed for sale Record ID 1deea7a5f6a3

2009 Chevrolet Uplander LS APV

3.9 L, 6 cylinders · 4x2 · Van · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1GN	DU231	7	9	D	105332
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Chevrolet · GENERAL MOT…	Uplander · 3.9 L	Verified	2009	Doraville	Build sequence

§1 IDENTITY [1]

Model year	2009	Engine	3.9 L, 6 cylinders
Make	Chevrolet	Fuel	Gasoline
Model	Uplander	Drive	4x2
Trim	LS APV	Maker	GENERAL MOTORS LLC
Body	Van	Plant	Doraville, Georgia, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/chevrolet/uplander/2009

2 recalls listed by Transport Canada for this model year

Other

2019420 21 Aug 2019

Issue: This recall is for aftermarket replacement rear window glass produced by Vitro Automotriz. Certain rear window glass may not have been properly tempered. If the window breaks, the glass may separate into large pieces instead of very small ones. Note: This is a voluntary recall that is not being conducted under the requirements of the Motor Vehicle Safety Act. Safety Risk: Glass that breaks in to large pieces could create a risk of injury. Corrective Actions: The company will notify consumers by mail and instruct them to inspect the designation code marked on the rear window glass. Products affected by this recall have the designation “DOT 287” along with the lettering “VMR” (Replacement Market) and a date code that is before July 2019. This information is printed on the bottom corner of the glass. Consumers should contact Vitro's customer service at 1-412-995-6457 or argbacklites@vitro.com to arrange for replacement of the glass.

Brakes

2012161 17 May 2012

On certain vehicles, the left rear brake hose may contact the parking brake cable, causing the brake hose to wear. The resultant chafe damage could, over time, cause a brake fluid leak, which may result in a reduction of braking performance and increased stopping distance. This could result in a crash causing property damage and/or personal injury. Correction: Dealers will inspect the left rear brake hose to ensure sufficient clearance to the park brake cable. The brake hose will also be inspected for damage and, if necessary, replaced.

Listed for the model year, not checked against your VIN. Chevrolet confirms which apply.
Check your VIN with Chevrolet Canada or call a Chevrolet dealer with your VIN.
www.chevrolet.ca/en/ownercenter/recalls

§3 VALUE [3]

This car asks $5,995[4], $195 over the median of $5,800[3].

Lowest ask	$5,800
Middle half	$5,800 – $5,800
Median ask	$5,800
This car	$5,995

Same model year · 1 live listings · as of 29 Oct 2026

OTHER 2009 CHEVROLET UPLANDER LISTINGS [4]

Surrey, BC · 172,051 km	$5,800

§4 EVENTS

2009	Model year 2009[1] Assembly plant Doraville, Georgia, United States
17 May 2012	Transport Canada recall 2012161[2] Issued for the model year · Brakes
21 Aug 2019	Transport Canada recall 2019420[2] Issued for the model year · Other
25 Oct 2026	Listed for sale, Stoney Creek, ON[4] Xpress Auto Sales · asking $5,995

§5 DOCUMENTS

Window sticker — This VIN reads as model year 2009, before our coverage for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] Cardog market quote, same model year, 1 live listings, as of 29 Oct 2026
[4] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.