Register entry, as of 28 October 2026 Listed for sale Record ID f7c79cd41b32

2011 Chevrolet Traverse LS

3.6 L, 6 cylinders · FWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1GN	KREED	7	B	J	197020
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Chevrolet · GENERAL MOT…	Traverse · 3.6 L	Verified	2011	Lansing - Delta Township	Build sequence

§1 IDENTITY [1]

Model year	2011	Engine	3.6 L, 6 cylinders
Make	Chevrolet	Fuel	Gasoline
Model	Traverse	Drive	FWD
Trim	LS	Maker	GENERAL MOTORS LLC
Body	Sport Utility Vehicle	Plant	Lansing - Delta Township, Michigan, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/chevrolet/traverse/2011

5 recalls listed by Transport Canada for this model year

Airbag

2021213 8 Apr 2021

Issue: On a small number of vehicles, the right or left roof rail airbag may not be properly attached to the vehicle. As a result, the airbags may not work properly in a crash. Safety Risk: An airbag that does not work properly could create an increased risk of injury in a crash. Corrective Actions: General Motors will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the roof rail airbag attachments. The dealer will add or replace any attachments that are missing, damaged or out of position.

Structure

2015280 25 Jun 2015

On certain vehicles equipped with a power liftgate system, the gas-filled struts (which help to raise and support the liftgate) may prematurely wear. These vehicles have a Prop Rod Recovery system intended to accomplish a controlled, slow return of the liftgate to the closed position if the liftgate's gas struts are no longer capable of supporting the weight of the liftgate. The vehicle would provide audible warnings and flash the tail lamps to indicate there is a problem. However, the liftgate's Prop Rod Recovery system software may be unable to detect/stop a liftgate with prematurely worn gas struts from falling too quickly after the liftgate is opened. This could allow the liftgate to drop suddenly, placing anyone beneath or near the gate at risk of injury. Correction: Dealers will reprogram the power liftgate actuator motor ECU with a new software and will verify power liftgate operation following the reprogram.

Seats and restraints

2014181 21 May 2014

On certain vehicles, the flexible steel cable that connects the seat belt to the vehicle structure at the front outboard seating positions can fatigue over time and could separate, increasing the risk of injury in a crash. Correction: Dealers will inspect and repair or replace the lap pretensioner, as necessary.

Airbag

2014081 18 Mar 2014

On certain vehicles, side airbag wiring connections could develop high resistance, illuminating the airbag warning light. If the vehicle continues to be operated in this condition, resistance may continue to increase over time and eventually cause the seat side airbags and seat belt pretensioners to not deploy in the event of a crash, which could increase the risk of injury. Correction: Dealers will affect repairs.

Visual system

2012122 5 Apr 2012

On certain vehicles, if a buildup of snow or ice on the windshield or on the wipers restricts the movement of the wiper arm, the wiper arm nut may loosen and cause that wiper to become inoperative. Loss of windshield wiping capability, should it occur during a rainy/snowy day, may compromise the driver's ability to see the road and its users, which could result in a crash causing property damage and/or personal injury. Correction: Dealers will tighten the wiper arm nuts.

> Listed for the model year, not checked against your VIN. Chevrolet confirms which apply.
> Check your VIN with Chevrolet Canada or call a Chevrolet dealer with your VIN.
> www.chevrolet.ca/en/ownercenter/recalls

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $3,495[5], $5,500 under the median of $8,995[4].



Lowest ask	$3,495
Middle half	$6,245 – $9,245
Median ask	$8,995
This car	$3,495

Same model year · 3 live listings · as of 28 Oct 2026

OTHER 2011 CHEVROLET TRAVERSE LISTINGS [5]

Sarnia, ON · 116,667 km	$9,495
Hamilton, ON · 167,000 km	$8,995

§4 EVENTS

2011	Model year 2011[1] Assembly plant Lansing - Delta Township, Michigan, United States
5 Apr 2012	Transport Canada recall 2012122[2] Issued for the model year · Visual system
18 Mar 2014	Transport Canada recall 2014081[2] Issued for the model year · Airbag
21 May 2014	Transport Canada recall 2014181[2] Issued for the model year · Seats and restraints
25 Jun 2015	Transport Canada recall 2015280[2] Issued for the model year · Structure

8 Apr 2021	Transport Canada recall 2021213[2] Issued for the model year · Airbag
25 Oct 2026	Listed for sale, London, ON[5] Tiger Auto Sales Ltd. · asking $3,495
28 Oct 2026	Listing last updated[5] asking $3,495

§5 DOCUMENTS

Window sticker — This VIN reads as model year 1981 or 2011, before our coverage for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 3 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.