Register entry, as of 27 October 2026 Listed for sale Record ID c176abd0e009

2015 Chevrolet Tahoe

5.3 L, 8 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1GN	SK3EC	2	F	R	689655
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Chevrolet · GENERAL MOT…	Tahoe · 5.3 L	Verified	2015	Arlington	Build sequence

§1 IDENTITY [1]

Model year	2015	Engine	5.3 L, 8 cylinders
Make	Chevrolet	Fuel	Gasoline
Model	Tahoe	Drive	4WD
Trim	Not in the decode	Maker	GENERAL MOTORS LLC
Body	Sport Utility Vehicle	Plant	Arlington, Texas, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/chevrolet/tahoe/2015

11 recalls listed by Transport Canada for this model year

Brakes

2019533 24 Oct 2019

Issue: On certain vehicles, there may be an error in the electronic-brake control module software. This could cause the driveline-protection system to activate when a wheel-speed sensor fails. If this happens, the brakes could apply and cause the vehicle to pull to one side. Note: This recall only affects vehicles equipped with four-wheel drive, a 5.3-L engine, and a 3.08 ratio rear axle. The problem can only occur when the vehicle is in four-wheel drive or automatic mode, and travelling at a speed between 66 and 97 km/h (41 and 60 mph). A wheel-speed sensor failure will cause the electronic stability control (ESC) and anti-lock braking system (ABS) warning lights to turn on, and a "Service StabiliTrak" message to display. Safety Risk: A vehicle that suddenly pulls to one side could increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and instruct you to take your vehicle to a dealer to update the electronic-brake control module software. General Motors advises that using two-wheel-drive mode can eliminate the risk until the recall repair is completed.

Other

2019420 21 Aug 2019

Issue: This recall is for aftermarket replacement rear window glass produced by Vitro Automotriz. Certain rear window glass may not have been properly tempered. If the window breaks, the glass may separate into large pieces instead of very small ones. Note: This is a voluntary recall that is not being conducted under the requirements of the Motor Vehicle Safety Act. Safety Risk: Glass that breaks in to large pieces could create a risk of injury. Corrective Actions: The company will notify consumers by mail and instruct them to inspect the designation code marked on the rear window glass. Products affected by this recall have the designation “DOT 287” along with the lettering “VMR” (Replacement Market) and a date code that is before July 2019. This information is printed on the bottom corner of the glass. Consumers should contact Vitro's customer service at 1-412-995-6457 or argbacklites@vitro.com to arrange for replacement of the glass.

Brakes

2019324 28 Jun 2019

Issue: On certain vehicles, there could be a reduction in power brake assist due to a decrease in output from the vacuum pump. This could cause a hard brake pedal and an increase in brake pedal effort to stop the vehicle. Safety Risk: A sudden increase in brake pedal force could lead to an increase in stopping distance. This could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct them to take their vehicle to a dealer to reprogram the electronic brake control module.

Steering

2018482 7 Sep 2018

Certain vehicles may experience a temporary loss of electric power steering (EPS) assist followed by a sudden return of EPS assist, particularly during low-speed turning manoeuvres due to an electrical/software issue. If EPS assist is lost and suddenly returned, the unexpected change in steering effort could affect vehicle control, which would increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will update the EPS module software. Note: If power steering assist is lost and the vehicle reverts to manual steering, a dash message would be displayed stating there is an EPS problem. Additionally, this issue could also affect radio, stabilitrak, the driver information centre, chime, door-lock, air conditioning, and/or cruise control function.

Airbag

2017342 10 Jul 2017

On certain vehicles, the sensing and diagnostic module (SDM), which controls airbag and pretensioner deployment, contains a software defect which may prevent the deployment of frontal airbags and pretensioners in certain circumstances. Failure of frontal airbags and seatbelt pretensioners to deploy in a crash (when warranted) could increase the risk of injury. Correction: Dealers will reflash the SDM with new software. In vehicles with any previous deployment events recorded in the SDM, the dealers will replace the existing SDM with a new SDM containing the latest software.

Tires

2016502 12 Oct 2016

On certain vehicles equipped with Continental P275/55R20 CrossContact LX20 tires, a manufacturing defect could cause a lack of adhesion between belts in the tire. Affected tires may exhibit localized tread wear, excessive vibration, noise and bulging in the tread area. Continued use could cause the belts to separate, which could lead to full belt/tread loss. This could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will inspect tire date code markings to determine whether they are from the affected date code. Affected tires will be replaced.

5 more on the model-year record, cardog.app/tools/recalls/chevrolet/tahoe/2015

> Listed for the model year, not checked against your VIN. Chevrolet confirms which apply.
> Check your VIN with Chevrolet Canada or call a Chevrolet dealer with your VIN.
> www.chevrolet.ca/en/ownercenter/recalls

United States: 14 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $19,900[5], $1,045 under the median of $20,945[4].

Lowest ask	$13,000
Middle half	$18,471 – $23,494
Median ask	$20,945
This car	$19,900

Same model year · 6 live listings · as of 27 Oct 2026

OTHER 2015 CHEVROLET TAHOE LISTINGS [5]

Scarborough, ON · 147,621 km	$13,000
North York, ON · 174,627 km	$23,995
Wetaskiwin, AB · 170,469 km	$21,990
Prince Albert, SK · 279,985 km	$12,030

Wilkie, SK · 279,985 km	$12,030
Mississauga, ON · 262,095 km	$17,995

§4 EVENTS

2015	Model year 2015[1] Assembly plant Arlington, Texas, United States
31 Mar 2014	Transport Canada recall 2014102[2] Issued for the model year · Powertrain
6 Jun 2014	Transport Canada recall 2014216[2] Issued for the model year · Accessories
27 Jun 2014	Transport Canada recall 2014254[2] Issued for the model year · Powertrain
25 Sep 2015	Transport Canada recall 2015431[2] Issued for the model year · Lights and instruments
9 Sep 2016	Transport Canada recall 2016439[2] Issued for the model year · Airbag
12 Oct 2016	Transport Canada recall 2016502[2] Issued for the model year · Tires
10 Jul 2017	Transport Canada recall 2017342[2] Issued for the model year · Airbag
7 Sep 2018	Transport Canada recall 2018482[2] Issued for the model year · Steering
28 Jun 2019	Transport Canada recall 2019324[2] Issued for the model year · Brakes
21 Aug 2019	Transport Canada recall 2019420[2] Issued for the model year · Other
24 Oct 2019	Transport Canada recall 2019533[2] Issued for the model year · Brakes
16 Sep 2026	Listed for sale, Toronto, ON[5] COLISEUM AUTO SALES · asking $19,900
26 Oct 2026	Listing last updated[5] asking $19,900

§5 DOCUMENTS

Window sticker — This VIN reads as model year 1985 or 2015, before our coverage for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 6 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.