Register entry, as of 29 October 2026 Listed for sale Record ID 649e6df19140

2022 Chevrolet Tahoe Z71

5.3 L, 8 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1GN	SKPKD	3	N	R	315834
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Chevrolet · GENERAL MOT…	Tahoe · 5.3 L	Verified	2022	Arlington	Build sequence

§1 IDENTITY [1]

Model year	2022	Engine	5.3 L, 8 cylinders
Make	Chevrolet	Fuel	Gasoline
Model	Tahoe	Drive	4WD
Trim	Z71	Maker	GENERAL MOTORS LLC
Body	Sport Utility Vehicle	Plant	Arlington, Texas, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/chevrolet/tahoe/2022

7 recalls listed by Transport Canada for this model year

Powertrain

2026061 12 Feb 2026

Issue: On certain vehicles, the transmission control valve body could wear and lose pressure. If this happens, the transmission could shift harshly and cause the wheels to lock up. Note: This recall only affects vehicles equipped with a 10-speed automatic transmission. Safety Risk: Wheels that lock suddenly could cause a loss of control and increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and advise you to take your vehicle to a dealership to update the transmission control module software to detect excess wear in advance of a wheel lock up. If detected, a service engine light would turn on, a message would display in the instrument panel and the vehicle would be limited to fifth gear.

Engine

2025225 24 Apr 2025

Issue: On certain vehicles, the connecting rods and/or crankshaft components may not have been manufactured properly. As a result, the engine could make abnormal noises and a warning light may turn on. If you continue to drive the vehicle with these symptoms, the engine could fail. Note: This recall only affects certain vehicles equipped with a 6.2 L V8 gas engine. Safety Risk: An engine failure could cause a sudden loss of power to the wheels and increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and advise you to take your vehicle to inspect and, if necessary, repair or replace the engine. For vehicles that pass the engine inspection, the dealer will replace the oil with a higher viscosity oil, install a new oil fill cap, replace the oil filter, and add an insert to the owner's manual.

Powertrain

2024637 24 Oct 2024

Issue: Over time, the transmission control valve could wear and lose pressure. If this happens, the transmission could shift harshly and could cause the rear wheels to lock up. Note: This recall only affects vehicles equipped with a diesel engine. Safety Risk: Rear wheels that lock suddenly could cause a loss of control and increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and advise you to take your vehicle to a dealership to update the transmission control module software to detect excess wear in advance of a wheel lock up. If detected, a service engine light would turn on, a message would display in the instrument panel and the vehicle would be limited to fifth gear.

Lights and instruments

2024060 1 Feb 2024

Issue: On certain vehicles, a software problem could cause the lower beam headlamps not to turn on as it becomes dark outside if the multi-function switch is in the "OFF" or "PARKING LAMP" position. This could also cause the daytime running lamps (DRLs) to turn off when the vehicle is moving. As a result, the vehicles may not meet certain requirements of Canadian regulations. Safety Risk: Headlamps and/or DRLs that don't turn on could reduce visibility, make the vehicle less visible to others and increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and advise you to take your vehicle to a dealership to update the body control module (BCM)software.

Lights and instruments

2023472 24 Aug 2023

Issue: On certain vehicles, the automatic headlamps may not turn on soon enough as it becomes dark outside. Canadian regulations require automatic headlamps to turn on when the ambient light level drops below a certain point (1000 lux). Safety Risk: Headlamps that don't turn on as it becomes dark outside could reduce visibility and increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and send a wireless over-the-air software update to eligible vehicles to update the body control module (BCM) software. Alternatively, you may schedule an appointment to have the update performed at a GM dealership.

Lights and instruments

2022700 8 Dec 2022

Issue: On certain vehicles, the daytime running lamps (DRLs) may stay on when the headlamps are on. Canadian regulations require the DRLs to turn off when the headlamps are on. Safety Risk: Daytime running lamps that stay on could cause glare for oncoming drivers and increase the risk of a crash. Corrective Action: General Motors will notify owners by mail and instruct you to take your vehicle to a dealership to update the body control module (BCM) software.

1 more on the model-year record, cardog.app/tools/recalls/chevrolet/tahoe/2022

> Listed for the model year, not checked against your VIN. Chevrolet confirms which apply.
> Check your VIN with Chevrolet Canada or call a Chevrolet dealer with your VIN.
> www.chevrolet.ca/en/ownercenter/recalls

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $59,990[5], $447 under the median of $60,437[4].

Lowest ask	$45,999
Middle half	$56,888 – $63,911
Median ask	$60,437
This car	$59,990

Same model year · 17 live listings · as of 29 Oct 2026

OTHER 2022 CHEVROLET TAHOE LISTINGS [5]

Drayton Valley, AB · 57,000 km	$70,704
Edmonton, AB · 118,050 km	$60,497
Winnipeg, MB · 118,050 km	$60,497
Regina, SK · 118,050 km	$60,497
Winnipeg, MB · 118,050 km	$60,497
Moncton, NB · 92,465 km	$60,437

§4 EVENTS

2022	Model year 2022[1] Assembly plant Arlington, Texas, United States
11 Aug 2022	Transport Canada recall 2022456[2] Issued for the model year · Seats and restraints
8 Dec 2022	Transport Canada recall 2022700[2] Issued for the model year · Lights and instruments
24 Aug 2023	Transport Canada recall 2023472[2] Issued for the model year · Lights and instruments
1 Feb 2024	Transport Canada recall 2024060[2] Issued for the model year · Lights and instruments
24 Oct 2024	Transport Canada recall 2024637[2] Issued for the model year · Powertrain
24 Apr 2025	Transport Canada recall 2025225[2] Issued for the model year · Engine
12 Feb 2026	Transport Canada recall 2026061[2] Issued for the model year · Powertrain
26 Oct 2026	Listed for sale, Moose Jaw, SK[5] Knight Honda · asking $59,990
29 Oct 2026	Listing last updated[5] asking $59,990

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 17 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.