Register entry, as of 29 October 2026 Listed for sale Record ID 53412eeb84a0

2019 GMC Sierra HD SLT

6.6 L, 8 cylinders · 4WD · Pickup · Diesel

VEHICLE IDENTIFICATION NUMBER [1]

1GT	12REY	3	K	F	229662
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
GMC · GENERAL MOTORS…	Sierra HD · 6.6 L	Verified	2019	Flint	Build sequence

§1 IDENTITY [1]

Model year	2019	Engine	6.6 L, 8 cylinders
Make	GMC	Fuel	Diesel
Model	Sierra HD	Drive	4WD
Trim	SLT	Maker	GENERAL MOTORS LLC
Body	Pickup	Plant	Flint, Michigan, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/gmc/sierra-hd/2019

8 recalls listed by Transport Canada for this model year

Airbag

2026245 21 May 2026

Issue: On certain trucks, the side curtain airbag inflators could be defective. As a result, the driver and/or passenger side curtain airbag inflator(s) could deploy without a crash. If this happens, parts could be propelled toward vehicle occupants. Note: This recall is an expansion of Transport Canada recall no. 2026-129. Safety Risk: An airbag inflator that ruptures can create a risk of injury. Corrective Actions: General Motors will notify owners by mail and advise you to take your truck to a dealership to replace both side curtain airbag modules.

Airbag

2026129 19 Mar 2026

Issue: On certain trucks, the side curtain airbag inflators could be defective. As a result, the driver and/or passenger side curtain airbag inflator(s) could deploy without a crash. If this happens, parts could be propelled toward vehicle occupants. Safety Risk: An airbag inflator that ruptures can create a risk of injury. Corrective Actions: General Motors will notify owners by mail and advise you to take your truck to a dealership to replace both side curtain airbag modules.

Airbag

2025352 25 Jun 2025

Issue: On certain trucks, the side curtain airbag inflators could be defective. As a result, the driver and/or passenger side curtain airbag inflator(s) could deploy without a crash. If this happens, parts could be propelled toward vehicle occupants. Safety Risk: An airbag inflator that ruptures can create a risk of injury. Corrective Actions: General Motors will notify owners by mail and advise you to take your truck to a dealership to replace both side curtain airbag modules.

Electrical

2024294 24 May 2024

Issue: On certain trucks, the repairs completed by a General Motors dealer during recall N192220470 (Transport Canada recall no. 2019-325) or customer satisfaction program no. N192270330 may not have been completed properly. As a result, a second repair is required. Additionally, certain trucks may not have had the updated parts installed during production. On certain trucks equipped with a power sliding rear window, the rear defroster wiring could overheat and melt. Safety Risk: Wiring that overheats and melts can create the risk of a fire. Corrective Actions: General Motors will notify owners by mail and advise you to take your truck to a dealership to replace the contact cover for the sliding rear window. The dealer will also update the heating, ventilation, and air conditioning (HVAC) software, if necessary. If the rear window or sliding glass assembly are damaged, they will be replaced.

Fuel system

2023040 2 Feb 2023

Issue: On certain trucks equipped with a diesel engine and dual fuel tanks, the rear fuel pump may not transfer enough fuel to the front tank. If this happens, you may notice an engine hesitation and the check engine light may turn on. The engine could also stall suddenly while driving, and you may not be able to restart it. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and instruct you to take your truck to a dealership to inspect the rear fuel tank and fuel pump module, and replace them if necessary. The dealer will also add a fuel tank vent hose.

Electrical

2021407 1 Jul 2021

Issue: On certain vehicles, a small coolant leak could cause the engine block-heater cable to short circuit while plugged in. Note: This recall only affects trucks equipped with a 6.6 L diesel engine and an optional block-heater power cable. This recall replaces Transport Canada Recall # 2019-204. All vehicles repaired under that recall require a second repair. Safety Risk: A short circuit could cause damage to engine components and create the risk of a fire. Corrective Action: General Motors will notify owners by mail. The corrective actions for this recall are under development. Do not use your engine-block heater until the repairs are performed.

2 more on the model-year record, cardog.app/tools/recalls/gmc/sierra-hd/2019

> Listed for the model year, not checked against your VIN. GMC confirms which apply.
> Check your VIN with GMC Canada or call a GMC dealer with your VIN.
> www.gmccanada.ca/en/ownercenter/recalls

§3 VALUE [3]

This car asks $47,995[4], $4,000 over the median of $43,995[3].

Lowest ask	$27,988
Middle half	$34,896 – $48,665
Median ask	$43,995
This car	$47,995

Same model year · 18 live listings · as of 29 Oct 2026

OTHER 2019 GMC SIERRA HD LISTINGS [4]

Orangeville, ON · 41,559 km	$42,769
Orangeville, ON · 34,311 km	$43,769
Orangeville, ON · 135,245 km	$19,960
Orangeville, ON · 265,799 km	$9,590
Orangeville, ON · 72,893 km	$32,960
Québec, QC · 144,228 km	$23,494

§4 EVENTS

2019	Model year 2019[1] Assembly plant Flint, Michigan, United States
26 Apr 2019	Transport Canada recall 2019204[2] Issued for the model year · Electrical
28 Jun 2019	Transport Canada recall 2019325[2] Issued for the model year · Electrical
1 Jul 2021	Transport Canada recall 2021407[2] Issued for the model year · Electrical
2 Feb 2023	Transport Canada recall 2023040[2] Issued for the model year · Fuel system
24 May 2024	Transport Canada recall 2024294[2] Issued for the model year · Electrical
25 Jun 2025	Transport Canada recall 2025352[2] Issued for the model year · Airbag
19 Mar 2026	Transport Canada recall 2026129[2] Issued for the model year · Airbag
21 May 2026	Transport Canada recall 2026245[2] Issued for the model year · Airbag
28 Sep 2026	Listed for sale, Tracadie-Sheila, NB[4] Toner GMC Chevrolet Buick Ltee · asking $47,995
29 Oct 2026	Listing last updated[4] asking $47,995

§5 DOCUMENTS

Window sticker — This VIN reads as model year 1989 or 2019, before our coverage for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] Cardog market quote, same model year, 18 live listings, as of 29 Oct 2026
[4] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.