

Register entry, as of 26 October 2026

Listed for sale

Record ID 2abe7770df60

2019 GMC Sierra Denali

5.3 L, 8 cylinders · 4WD · Pickup · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1GT U9FED 1 K Z 427496

WMI 1-3

GMC · GENERAL MOTORS...

DESCRIPTOR 4-8

Sierra · 5.3 L

CHECK 9

Verified

YEAR 10

2019

PLANT 11

Fort Wayne

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2019	Engine	5.3 L, 8 cylinders
Make	GMC	Fuel	Gasoline
Model	Sierra	Drive	4WD
Trim	Denali	Maker	GENERAL MOTORS LLC
Body	Pickup	Plant	Fort Wayne, Indiana, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/gmc/sierra/2019

15 recalls listed by Transport Canada for this model year

Accessories

2022160 31 Mar 2022

Issue: This recall is a new notification for owners that purchased a soft or hard tri-fold tonneau cover from a General Motors dealer. On certain trucks, the bed-cover could come loose while driving and detach from the truck. This problem affects soft and hard tri-fold tonneau covers that were sold as an accessory by General Motors dealers. Note: This recall is related to Transport Canada recalls 2019-494 and 2020-165. If your truck was previously repaired under either of those recalls, it does not require further repair under the new recall. Safety Risk: A tonneau cover that separates from a moving vehicle could create a hazard for other drivers and nearby people. Corrective Actions: General Motors will notify owners by mail and instruct you to take your truck to a dealer to perform the recall repairs, including adding a tether to prevent the tonneau cover from detaching. Note: Until the recall repairs are completed, you can prevent the chance of the tonneau cover detaching by removing it from your truck and storing it.

Tires

2021767 17 Dec 2021

Issue: This recall affects certain trucks equipped with optional 18", 20", or 22" wheels and tires. The spare tire has a smaller diameter than the tires on the truck. As a result, the antilock brake system (ABS) may not work properly on certain road surfaces when the spare tire is installed on a rear wheel position. This could lead to an increase in stopping distance or a loss of control. Safety Risk: Reduced braking or a loss of control could increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and advise you to bring your truck to a dealer to replace the spare tire and wheel. The dealer will also apply a new spare tire information label over the existing tire label. You will be provided an owner's manual insert that says which spare tire should be used with the wheels and tires on your truck.



Tires

2021347 3 Jun 2021

Issue: On certain vehicles, recall 2021-103 may not have been properly completed. As a result, a second inspection is necessary. Certain vehicles were built with tires that may have been cured too long. As a result, the sidewall could crack or the tread and belts could separate. This could lead to a sudden loss of air pressure and could cause a tire failure. Note: This recall only affects certain Continental tires, with specific date codes and mold numbers. Vehicles subject to this recall were previously inspected under GM recall N212329050 (TC 2021-103) and require subsequent inspection. Safety Risk: A tire failure could cause a loss of control and increase the risk of a crash. Corrective Actions: General Motors will notify the owners by mail and instruct them to take the vehicle to a dealer to inspect and replace the tires, if necessary.

Tires

2021103 26 Feb 2021

Issue: Certain vehicles were built with tires that may have been cured too long. As a result, the sidewall could crack or the tread and belts could separate. This could lead to a sudden loss of air pressure and could cause a tire failure. Note: This recall only affects certain Continental tires, with specific date codes and mold numbers. Safety Risk: A tire failure could cause a loss of control and increase the risk of a crash. Corrective Actions: General Motors will notify the owners by mail and instruct them to take the vehicle to a dealer to inspect and replace the tires, if necessary.

Seats and restraints

2020624 17 Dec 2020

Issue: On certain trucks, the seat belt brackets for the front-row centre seat may not be properly attached to the seat frame. As a result, the seat belt could detach, and may not work as designed in a crash. Safety Risk: A seat belt that detaches in a crash could create an increased risk of injury. Corrective Actions: General Motors will notify owners by mail and instruct you to take your truck to a dealer to inspect the front-row centre seat belt bracket attachments. The dealer will reassemble the brackets correctly, if necessary.

Powertrain

2020505 23 Oct 2020

Issue: On a small number of trucks, the driveshaft may not have been properly welded. As a result, the driveshaft could break while driving and cause a loss of power to the wheels. Safety Risk: A loss of power to the wheels could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your truck to a dealer to replace the driveshaft.


9 more on the model-year record, cardog.app/tools/recalls/gmc/sierra/2019

Listed for the model year, not checked against your VIN. GMC confirms which apply.
Check your VIN with GMC Canada or call a GMC dealer with your VIN.
www.gmccanada.ca/en/ownercenter/recalls

United States: 17 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$44,680^[5], \$11,685 over the median of \$32,995^[4].



Lowest ask	\$15,300
Middle half	\$29,846 – \$39,097
Median ask	\$32,995
This car	\$44,680

Same model year · 80 live listings · as of 26 Oct 2026

OTHER 2019 GMC SIERRA LISTINGS [5]

North Battleford, SK · 206,761 km	\$21,994
Carignan, QC · 79,160 km	\$27,998
Brossard, QC · 79,160 km	\$27,998
Watrous, SK · 142,753 km	\$42,995



§4 EVENTS

2019	Model year 2019 ^[1] Assembly plant Fort Wayne, Indiana, United States
7 Dec 2018	Transport Canada recall 2018688 ^[2] Issued for the model year · Airbag
26 Apr 2019	Transport Canada recall 2019205 ^[2] Issued for the model year · Accessories
21 Aug 2019	Transport Canada recall 2019420 ^[2] Issued for the model year · Other
3 Oct 2019	Transport Canada recall 2019494 ^[2] Issued for the model year · Accessories
14 Nov 2019	Transport Canada recall 2019575 ^[2] Issued for the model year · Seats and restraints
12 Dec 2019	Transport Canada recall 2019631 ^[2] Issued for the model year · Electrical
12 Dec 2019	Transport Canada recall 2019630 ^[2] Issued for the model year · Brakes
30 Jan 2020	Transport Canada recall 2020034 ^[2] Issued for the model year · Brakes
16 Apr 2020	Transport Canada recall 2020165 ^[2] Issued for the model year · Accessories
23 Oct 2020	Transport Canada recall 2020505 ^[2] Issued for the model year · Powertrain
17 Dec 2020	Transport Canada recall 2020624 ^[2] Issued for the model year · Seats and restraints
26 Feb 2021	Transport Canada recall 2021103 ^[2] Issued for the model year · Tires
3 Jun 2021	Transport Canada recall 2021347 ^[2] Issued for the model year · Tires
17 Dec 2021	Transport Canada recall 2021767 ^[2] Issued for the model year · Tires
31 Mar 2022	Transport Canada recall 2022160 ^[2] Issued for the model year · Accessories
26 Oct 2026	Listed for sale, Edmonton, AB ^[5] Lakewood Chevrolet · asking \$44,680



§5 DOCUMENTS

Window sticker This VIN reads as model year 1989 or 2019, before our coverage for this manufacturer.

SOURCES

- | | |
|---|---|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 80 live listings, as of 26 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 26 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

