

Register entry, as of 28 October 2026

Listed for sale

Record ID e0368f883c24

2018 GMC Savana Cargo Ext

6.0 L, 8 cylinders · RWD · Cargo Van · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1GT **Z7HFG** **3** **J** **1** **190331**

WMI 1-3

GMC · GENERAL MOTORS...

DESCRIPTOR 4-8

Savana · 6.0 L

CHECK 9

Verified

YEAR 10

2018

PLANT 11

Wentzville

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2018	Engine	6.0 L, 8 cylinders
Make	GMC	Fuel	Gasoline
Model	Savana	Drive	RWD
Trim	Cargo Ext	Maker	GENERAL MOTORS LLC
Body	Cargo Van	Plant	Wentzville, Missouri, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/gmc/savana/2018

5 recalls listed by Transport Canada for this model year

Brakes

2024543 19 Sep 2024

Issue: On certain vehicles, the brake lines could become damaged by contact with the body mounts. This could lead to a brake fluid leak and cause reduced braking. Note: This recall only affects certain cutaway chassis vehicles. Safety Risk: Reduced braking can cause extended stopping distances and increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the brake lines.

Electrical

2023210 6 Apr 2023

Issue: On certain vehicles, an unused wiring harness for a rear HVAC blower motor, located in the left B-pillar area, could become damaged if exposed to moisture or contaminants. If this happens, the wires could short circuit. Note: This recall only affects cutaway chassis incomplete vehicles. Safety Risk: A short circuit can create the risk of a fire. Corrective Actions: General Motors will notify owners by mail and instruct you to bring your vehicle to a dealership to seal the wiring for the rear HVAC blower motor at the left B-pillar.

Tires

2021103 26 Feb 2021

Issue: Certain vehicles were built with tires that may have been cured too long. As a result, the sidewall could crack or the tread and belts could separate. This could lead to a sudden loss of air pressure and could cause a tire failure. Note: This recall only affects certain Continental tires, with specific date codes and mold numbers. Safety Risk: A tire failure could cause a loss of control and increase the risk of a crash. Corrective Actions: General Motors will notify the owners by mail and instruct them to take the vehicle to a dealer to inspect and replace the tires, if necessary.



Other

2020479 7 Oct 2020

Issue: Certain vehicles may have incorrect body control module software. As a result, the immobilization system is not active during the learning procedure for a new "unlearned" blank replacement key could be used during a 30 minute reprogramming procedure to disable the immobilization system. During this time, the vehicle cannot be driven. Safety Risk: This small error does not affect vehicle safety. Corrective Actions: This is not a recall. General Motors has made changes to vehicle software to ensure that all unsold and new vehicles have the correct body control module software.

Heater and defroster

2018525 21 Sep 2018

On certain vehicles equipped with a single manual rear climate control module (CCM), the CCM could overheat when the temperature is set to maximum heat or the knob is set to maximum floor vent. If this occurs, the insulation material used on the CCM terminal connectors could catch fire, increasing the risk of injury and/or damage to property. Correction: Dealers will remove the insulation from the CCM terminal connectors.

Listed for the model year, not checked against your VIN. GMC confirms which apply.

Check your VIN with GMC Canada or call a GMC dealer with your VIN.

www.gmccanada.ca/en/ownercenter/recalls

United States: 7 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$13,898^[5], \$4,872 under the median of \$18,770^[4].



Lowest ask	\$10,995
Middle half	\$13,598 – \$26,439
Median ask	\$18,770
This car	\$13,898

Same model year · 11 live listings · as of 28 Oct 2026

OTHER 2018 GMC SAVANA LISTINGS [5]

Surrey, BC · 322,148 km	\$11,800
Toronto, ON · 134,000 km	\$18,770
Pickering, ON · 169,055 km	\$13,299
Edmonton, AB · 197,544 km	\$18,995
Calgary, AB · 167,236 km	\$27,990

§4 EVENTS

2018	Model year 2018 ^[1] Assembly plant Wentzville, Missouri, United States
21 Sep 2018	Transport Canada recall 2018525 ^[2] Issued for the model year · Heater and defroster
7 Oct 2020	Transport Canada recall 2020479 ^[2] Issued for the model year · Other
26 Feb 2021	Transport Canada recall 2021103 ^[2] Issued for the model year · Tires



6 Apr 2023	Transport Canada recall 2023210 ^[2] Issued for the model year · Electrical
19 Sep 2024	Transport Canada recall 2024543 ^[2] Issued for the model year · Brakes
26 Oct 2026	Listed for sale, Port Alberni, BC ^[5] Cash For Cars Ltd (Port Alberni) · asking \$13,898
27 Oct 2026	Listing last updated ^[5] asking \$13,898

§5 DOCUMENTS

Window sticker This VIN reads as model year 1988 or 2018, before our coverage for this manufacturer.

SOURCES

- | | |
|---|---|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 11 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

