

Register entry, as of 27 October 2026

Listed for sale

Record ID c8d39278a73d

2015 Cadillac Escalade Premium

6.2 L, 8 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1GY S4NKJ 2 F R 511675

WMI 1-3

Cadillac · GENERAL MOTO...

DESCRIPTOR 4-8

Escalade · 6.2 L

CHECK 9

Verified

YEAR 10

2015

PLANT 11

Arlington

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2015	Engine	6.2 L, 8 cylinders
Make	Cadillac	Fuel	Gasoline
Model	Escalade	Drive	4WD
Trim	Premium	Maker	GENERAL MOTORS LLC
Body	Sport Utility Vehicle	Plant	Arlington, Texas, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/cadillac/escalade/2015

10 recalls listed by Transport Canada for this model year

Airbag	2026246	21 May 2026
Issue: On certain vehicles, the driver-front airbag inflator could rupture when the airbag deploys in a crash. If this happens, the airbag may not properly inflate and metal fragments could be propelled toward vehicle occupants. Safety Risk: An airbag inflator that ruptures can create a risk of injury or death. Corrective Actions: General Motors will notify owners by mail and advise you to take your vehicle to a dealership to replace the driver-front airbag module.		
Other	2019420	21 Aug 2019
Issue: This recall is for aftermarket replacement rear window glass produced by Vitro Automotriz. Certain rear window glass may not have been properly tempered. If the window breaks, the glass may separate into large pieces instead of very small ones. Note: This is a voluntary recall that is not being conducted under the requirements of the Motor Vehicle Safety Act. Safety Risk: Glass that breaks in to large pieces could create a risk of injury. Corrective Actions: The company will notify consumers by mail and instruct them to inspect the designation code marked on the rear window glass. Products affected by this recall have the designation "DOT 287" along with the lettering "VMR" (Replacement Market) and a date code that is before July 2019. This information is printed on the bottom corner of the glass. Consumers should contact Vitro's customer service at 1-412-995-6457 or argbacklites@vitro.com to arrange for replacement of the glass.		
Brakes	2019324	28 Jun 2019
Issue: On certain vehicles, there could be a reduction in power brake assist due to a decrease in output from the vacuum pump. This could cause a hard brake pedal and an increase in brake pedal effort to stop the vehicle. Safety Risk: A sudden increase in brake pedal force could lead to an increase in stopping distance. This could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct them to take their vehicle to a dealer to reprogram the electronic brake control module.		



Steering

2018482 7 Sep 2018

Certain vehicles may experience a temporary loss of electric power steering (EPS) assist followed by a sudden return of EPS assist, particularly during low-speed turning manoeuvres due to an electrical/software issue. If EPS assist is lost and suddenly returned, the unexpected change in steering effort could affect vehicle control, which would increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will update the EPS module software. Note: If power steering assist is lost and the vehicle reverts to manual steering, a dash message would be displayed stating there is an EPS problem. Additionally, this issue could also affect radio, stabilitrak, the driver information centre, chime, door-lock, air conditioning, and/or cruise control function.

Airbag

2017342 10 Jul 2017

On certain vehicles, the sensing and diagnostic module (SDM), which controls airbag and pretensioner deployment, contains a software defect which may prevent the deployment of frontal airbags and pretensioners in certain circumstances. Failure of frontal airbags and seatbelt pretensioners to deploy in a crash (when warranted) could increase the risk of injury. Correction: Dealers will reflash the SDM with new software. In vehicles with any previous deployment events recorded in the SDM, the dealers will replace the existing SDM with a new SDM containing the latest software.

Tires

2016502 12 Oct 2016

On certain vehicles equipped with Continental P275/55R20 CrossContact LX20 tires, a manufacturing defect could cause a lack of adhesion between belts in the tire. Affected tires may exhibit localized tread wear, excessive vibration, noise and bulging in the tread area. Continued use could cause the belts to separate, which could lead to full belt/tread loss. This could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will inspect tire date code markings to determine whether they are from the affected date code. Affected tires will be replaced.

4 more on the model-year record, cardog.app/tools/recalls/cadillac/escalade/2015

Listed for the model year, not checked against your VIN. Cadillac confirms which apply.
Check your VIN with Cadillac Canada or call a Cadillac dealer with your VIN.
www.cadillaccanada.ca/en/ownercenter/recalls

United States: 9 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$29,760^[5], \$1,212 over the median of \$28,548^[4].



Lowest ask	\$21,495
Middle half	\$23,499 – \$33,463
Median ask	\$28,548
This car	\$29,760

Same model year · 16 live listings · as of 27 Oct 2026

OTHER 2015 CADILLAC ESCALADE LISTINGS ^[5]

St-Eustache, QC · 186,973 km	\$21,888
Grande Prairie, AB · 148,454 km	\$28,209
Grande Prairie, AB · 148,454 km	\$28,709
Grande Prairie, AB · 148,454 km	\$28,709
Grande Prairie, AB · 148,454 km	\$28,209
Winnipeg, MB · 181,000 km	\$24,980



§4 EVENTS

2015	Model year 2015 ^[1] Assembly plant Arlington, Texas, United States
21 May 2014	Transport Canada recall 2014180 ^[2] Issued for the model year · Airbag
7 Oct 2014	Transport Canada recall 2014437 ^[2] Issued for the model year · Seats and restraints
18 Dec 2014	Transport Canada recall 2014577 ^[2] Issued for the model year · Engine
9 Sep 2016	Transport Canada recall 2016439 ^[2] Issued for the model year · Airbag
12 Oct 2016	Transport Canada recall 2016502 ^[2] Issued for the model year · Tires
10 Jul 2017	Transport Canada recall 2017342 ^[2] Issued for the model year · Airbag
7 Sep 2018	Transport Canada recall 2018482 ^[2] Issued for the model year · Steering
28 Jun 2019	Transport Canada recall 2019324 ^[2] Issued for the model year · Brakes
21 Aug 2019	Transport Canada recall 2019420 ^[2] Issued for the model year · Other
21 May 2026	Transport Canada recall 2026246 ^[2] Issued for the model year · Airbag
24 Oct 2026	Listed for sale, North Vancouver, BC ^[5] North Shore Acura · asking \$29,760
25 Oct 2026	Listing last updated ^[5] asking \$29,760

§5 DOCUMENTS

Window sticker This VIN reads as model year 1985 or 2015, before our coverage for this manufacturer.

SOURCES

- | | |
|---|---|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 16 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |



STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

