Register entry, as of 26 November 2026 Listed for sale Record ID 359e36a62361

2025 Chevrolet Express

6.6 L, 8 cylinders · Incomplete - Cutaway · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1HA	0GSF7	X	S	N	014534
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Chevrolet · INTERNATIONA…	Express · 6.6 L	Verified	2025	Springfield	Build sequence

§1 IDENTITY [1]

Model year	2025	Engine	6.6 L, 8 cylinders
Make	Chevrolet	Fuel	Gasoline
Model	Express	Drive	Not in the decode
Trim	Not in the decode	Maker	INTERNATIONAL MOTORS, LLC
Body	Incomplete - Cutaway	Plant	Springfield, Ohio, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/chevrolet/express/2025

4 recalls listed by Transport Canada for this model year

Steering

2026307 23 Jun 2026

Issue: On certain vehicles, a nut in the steering gear assembly may not have been tightened properly. As a result, the nut could loosen and separate. If this happens, there could be a loss of steering control. Safety Risk: A loss of steering control could increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the steering gear assembly.

Tires

2026104 5 Mar 2026

Issue: On certain vehicles, the sidewall of the tire(s) may have been damaged during manufacturing. As a result, the sidewall could fail and cause a sudden loss of air pressure. Note: This recall only affects certain cutaway chassis vehicles equipped with General Grabber HTS LT225/75R16E or Bridgestone V-Steel RIB R265 LT245/75R16E tires. Safety Risk: A tire failure could cause a loss of control and increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the affected tire(s).

Seats and restraints

2025250 8 May 2025

Issue: On a small number of vehicles, the head restraint on the front passenger seat may not have been properly welded. As a result, the head restraint could move or detach from the seat in a crash. Safety Risk: A head restraint that moves or detaches in a crash could increase the risk of an injury. Corrective Actions: General Motors will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the front passenger seat frame.

Structure 2025072 13 Feb 2025

Issue: On certain vehicles, a beam inside the driver's door may not have been welded properly. As a result, side impact protection may be reduced in a crash. Safety Risk: Reduced side impact protection could increase the risk of injuries in a crash. Corrective Actions: General Motors will notify owners by mail and advise you to take your vehicle to a dealership to replace the driver's door.

Listed for the model year, not checked against your VIN. Chevrolet confirms which apply.
Check your VIN with Chevrolet Canada or call a Chevrolet dealer with your VIN.
www.chevrolet.ca/en/ownercenter/recalls

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $49,995[5], $7,143 under the median of $57,138[4].



Lowest ask	$44,790
Middle half	$51,934 – $61,495
Median ask	$57,138
This car	$49,995

Same model year · 78 live listings · as of 26 Nov 2026

OTHER 2025 CHEVROLET EXPRESS LISTINGS [5]

Dartmouth, NS · 663 km	$51,985
Laval, QC · 65 km	$62,995
Barrie, ON · 1,033 km	$70,799
Barrie, ON · 3,179 km	$70,604
Quebec, QC · 39,520 km	$65,000
Quebec, QC · 50,768 km	$55,000

§4 EVENTS

2025	Model year 2025[1] Assembly plant Springfield, Ohio, United States
13 Feb 2025	Transport Canada recall 2025072[2] Issued for the model year · Structure
8 May 2025	Transport Canada recall 2025250[2] Issued for the model year · Seats and restraints
5 Mar 2026	Transport Canada recall 2026104[2] Issued for the model year · Tires
23 Jun 2026	Transport Canada recall 2026307[2] Issued for the model year · Steering
24 Nov 2026	Listed for sale, Laval, QC[5] Pronto Automobile Inc · asking $49,995

25 Nov 2026 **Listing last updated**[5]
asking $49,995

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 78 live listings, as of 26 Nov 2026
[5] Live public dealer listings on Cardog, as of 26 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.