

Register entry, as of 29 October 2026

Listed for sale

Record ID 3458e8901d77

2007 Honda Accord EX

2.4 L, 4 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1HG

WMI 1-3

American Honda Motor Co...

CM567

DESCRIPTOR 4-8

Accord · 2.4 L

3

CHECK 9

Verified

7

YEAR 10

2007

A

PLANT 11

Marysville

813891

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2007	Engine	2.4 L, 4 cylinders
Make	Honda	Fuel	Gasoline
Model	Accord	Drive	Not in the decode
Trim	EX	Maker	AMERICAN HONDA MOTOR CO., INC.
Body	Sedan	Plant	Marysville, Ohio, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/honda/accord/2007

7 recalls listed by Transport Canada for this model year

Airbag

2019323 28 Jun 2019

Issue: On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, may eventually degrade the propellant contained in the airbag. This could cause the airbag to deploy with more force than normal. If the airbag inflator ruptures, fragments could be propelled toward vehicle occupants or cause damage to the airbag assembly, preventing its proper function. Note: This is a new recall campaign that includes vehicles that had an airbag inflator replaced under a previous recall or had a replacement airbag installed. The previous recall provided an interim (short-term) repair. Interim repair parts must be replaced with the final repair parts provided in this recall. Safety Risk: If the vehicle is involved in a crash requiring an airbag deployment, the airbag inflator could rupture and create a risk of injury. Corrective Action: Owners will be notified by mail and instructed to take their vehicle to a dealer to replace the driver and/or passenger-front airbag inflator. Note: The Canadian climate results in the propellant degrading slowly. This recall is being conducted as a precaution to address future risk. It is expected that all airbag inflators will be replaced before their function would be affected.

Airbag

2019117 7 Mar 2019

Issue: On certain vehicles, there could be a problem with the driver-front airbag inflator. This could cause the airbag to deploy with more force than normal. If the airbag inflator ruptures, pieces could be propelled toward the occupants. This could also cause damage to the airbag assembly and prevent it from inflating properly. Note: This recall only affects certain vehicles that had a Takata airbag inflator installed during a previous airbag recall or collision repair. Safety Risk: In a crash where the airbag deploys, there could be an increased risk of injury. Corrective Action: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to have the driver-front airbag inflator replaced.



Airbag

2015261 15 Jun 2015

On certain vehicles, the passenger frontal airbag inflator could produce excessive internal pressure during airbag deployment. Increased pressure may cause the inflator to rupture, which could allow fragments to be propelled toward vehicle occupants, increasing the risk of injury. This could also damage the airbag module, which could prevent proper deployment. Failure of the passenger airbag to fully deploy during a crash (where deployment is warranted) could increase the risk of personal injury to the seat occupant. Correction: Dealers will replace airbag inflator. Note: Honda Canada has created a special Airbag Inflator Hotline for immediate assistance. For more information, please contact: For Honda Owners: 1-877-445-7754 For Acura Owners: 1-877-445-9844

Airbag

2015225 27 May 2015

On certain vehicles, the driver frontal airbag inflator could produce excessive internal pressure during airbag deployment. Increased pressure may cause the inflator to rupture, which could allow fragments to be propelled toward vehicle occupants, increasing the risk of injury. This could also damage the airbag module, which could prevent proper deployment. Failure of the airbag to fully deploy during a crash (where deployment is warranted) could increase the risk of personal injury to the seat occupant. Note: This recall supersedes special service campaign 2014567. Correction: Dealers will inspect/replace the driver's frontal airbag inflator. All vehicles having received a replacement inflator as part of any previous driver's inflator campaign will have a replacement inflator installed. Note: Honda Canada has created a special Airbag Inflator Hotline for immediate assistance. For more information, please contact: For Honda Owners: 1-877-445-7754 For Acura Owners: 1-877-445-9844

Airbag

2014567 15 Dec 2014

Honda Canada is conducting a voluntary Safety Improvement Campaign concerning the driver's airbag inflator on certain vehicles equipped with Takata airbags. Honda will replace the driver's inflator on affected vehicles. This action is not being conducted under the requirements of the Motor Vehicle Safety Act. Note: This special service campaign was replaced by recall 2015225. Please see recall 2015225 for more information: [Click here for more information](http://wwwapps.tc.gc.ca/Saf-Sec-Sur/7/VRDB-BDRV/search-recherche/detail.aspx?lang=eng&&rn=2015225)

Steering

2012326 28 Sep 2012

On certain vehicles, due to prolonged exposure to high heat, the power steering hose could crack and leak power steering fluid. Fluid leaking onto a hot surface could cause smoke and could potentially result in an underhood fire. Correction: Dealers will replace the power steering hose.

1 more on the model-year record, cardog.app/tools/recalls/honda/accord/2007

Listed for the model year, not checked against your VIN. Honda confirms which apply.

Check your VIN with Honda Canada or call a Honda dealer with your VIN.

www.honda.ca/en/recalls

United States: 10 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$14,500^[5], \$9,859 over the median of \$4,641^[4].



Lowest ask	\$1,495
Middle half	\$2,598 – \$7,298
Median ask	\$4,641
This car	\$14,500

Same model year · 6 live listings · as of 29 Oct 2026

OTHER 2007 HONDA ACCORD LISTINGS ^[5]

Hamilton, ON · 179,941 km	\$3,790
Mississauga, ON · 161,746 km	\$7,900



§4 EVENTS

2007	Model year 2007 ^[1] Assembly plant Marysville, Ohio, United States
5 Aug 2011	Transport Canada recall 2011286 ^[2] Issued for the model year · Powertrain
28 Sep 2012	Transport Canada recall 2012326 ^[2] Issued for the model year · Steering
15 Dec 2014	Transport Canada recall 2014567 ^[2] Issued for the model year · Airbag
27 May 2015	Transport Canada recall 2015225 ^[2] Issued for the model year · Airbag
15 Jun 2015	Transport Canada recall 2015261 ^[2] Issued for the model year · Airbag
7 Mar 2019	Transport Canada recall 2019117 ^[2] Issued for the model year · Airbag
28 Jun 2019	Transport Canada recall 2019323 ^[2] Issued for the model year · Airbag
27 Oct 2026	Listed for sale, Notre-Dame-des-Prairies, QC ^[5] RD Autos · asking \$14,500
28 Oct 2026	Listing last updated ^[5] asking \$14,500

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 6 live listings, as of 29 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 29 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

