Register entry, as of 28 October 2026 Listed for sale Record ID 936f80232fe6

# 2014 Honda Accord SPORT

2.4 L, 4 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 1HG | CR2F5 | 0 | E | A | 806439 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| American Honda Motor Co... | Accord · 2.4 L | Verified | 2014 | Marysville | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2014 | Engine | 2.4 L, 4 cylinders |
| Make | Honda | Fuel | Gasoline |
| Model | Accord | Drive | Not in the decode |
| Trim | SPORT | Maker | AMERICAN HONDA MOTOR CO., INC. |
| Body | Sedan | Plant | Marysville, Ohio, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/honda/accord/2014

**2** recalls listed by Transport Canada for this model year

### Powertrain

2020609 10 Dec 2020

Issue: On certain vehicles, the paint on the front axle shafts could delaminate or become damaged by road debris. As a result the axle shaft could corrode. If this happens, the axle shafts could break and cause a loss of power to the wheels. Also, if this happens and the vehicle is parked without the parking brake applied, the vehicle could roll away. Safety Risk: A loss of power to the wheels or a vehicle rollaway could increase the risk of a crash. Corrective Actions: Honda will notify owners by mail and instruct you to take your vehicle to a dealer to inspect, and if necessary, replace both axle shafts.

### Electrical

2017327 30 Jun 2017

On certain vehicles, the case for the battery sensor may have been improperly manufactured with gaps that could allow for moisture intrusion. If moisture or road salt were to enter the battery sensor case, it could result in corrosion to the sensor, which could cause an electrical short, increasing the risk of a fire causing injury and/or property damage. Correction: Dealers will inspect, and replace the battery sensor as necessary.

> Listed for the model year, not checked against your VIN. Honda confirms which apply.
> Check your VIN with Honda Canada or call a Honda dealer with your VIN.
> www.honda.ca/en/recalls

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $12,995[5], $4 under the median of $12,999[4].

| | |
|---|---|
| Lowest ask | $6,995 |
| Middle half | $11,942 – $14,992 |
| Median ask | $12,999 |
| This car | $12,995 |

Same model year · 27 live listings · as of 28 Oct 2026

### OTHER 2014 HONDA ACCORD LISTINGS [5]

| | |
|---|---|
| Guelph, ON · 167,413 km | $13,998 |
| London, ON · 224,000 km | $10,991 |
| Regina, OH · 136,325 km | $20,995 |
| Regina, SK · 136,325 km | $20,995 |
| Regina, OH · 136,325 km | $20,995 |
| Regina, SK · 136,325 km | $20,995 |

## §4 EVENTS

| | |
|---|---|
| 2014 | Model year 2014[1]<br>Assembly plant Marysville, Ohio, United States |
| 30 Jun 2017 | Transport Canada recall 2017327[2]<br>Issued for the model year · Electrical |
| 10 Dec 2020 | Transport Canada recall 2020609[2]<br>Issued for the model year · Powertrain |
| 24 Nov 2025 | Listed for sale, Toronto, ON[5]<br>11 MOTORS · asking $12,995 |
| 25 Oct 2026 | Listing last updated[5]<br>asking $12,995 |

## §5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

### SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 27 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.