Register entry, as of 28 October 2026 Listed for sale Record ID ce718b8015c1

2013 Honda Accord SPORT

2.4 L, 4 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1HG	CR2F5	9	D	A	801058
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
American Honda Motor Co...	Accord · 2.4 L	Verified	2013	Marysville	Build sequence

§1 IDENTITY [1]

Model year	2013	Engine	2.4 L, 4 cylinders
Make	Honda	Fuel	Gasoline
Model	Accord	Drive	Not in the decode
Trim	SPORT	Maker	AMERICAN HONDA MOTOR CO., INC.
Body	Sedan	Plant	Marysville, Ohio, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/honda/accord/2013

4 recalls listed by Transport Canada for this model year

Powertrain

2025340 19 Jun 2025

Issue: On certain vehicles, the paint on the front axle shafts could become damaged. As a result, the axle shaft(s) could corrode. If this happens, the axle shaft(s) could break and cause a loss of power to the wheels. Additionally, if the vehicle is parked and the parking brake isn't applied, the vehicle could roll away. Note: This recall is an expansion of recall HO54 (Transport Canada recall no. 2020-609). Safety Risk: A loss of power to the wheels could increase the risk of a crash. A parked vehicle that moves suddenly could create a risk of a crash or an injury. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the axle shaft(s).

Powertrain

2020609 10 Dec 2020

Issue: On certain vehicles, the paint on the front axle shafts could delaminate or become damaged by road debris. As a result the axle shaft could corrode. If this happens, the axle shafts could break and cause a loss of power to the wheels. Also, if this happens and the vehicle is parked without the parking brake applied, the vehicle could roll away. Safety Risk: A loss of power to the wheels or a vehicle rollaway could increase the risk of a crash. Corrective Actions: Honda will notify owners by mail and instruct you to take your vehicle to a dealer to inspect, and if necessary, replace both axle shafts.

Electrical

2017327 30 Jun 2017

On certain vehicles, the case for the battery sensor may have been improperly manufactured with gaps that could allow for moisture intrusion. If moisture or road salt were to enter the battery sensor case, it could result in corrosion to the sensor, which could cause an electrical short, increasing the risk of a fire causing injury and/or property damage. Correction: Dealers will inspect, and replace the battery sensor as necessary.

Fuel system

2013240 5 Jul 2013

On certain vehicles, the fuel tank may have been manufactured incorrectly and could leak. Fuel leakage, in the presence of an ignition source, could result in a fire causing property damage and/or personal injury. Correction: Dealers will replace the fuel tank.

> Listed for the model year, not checked against your VIN. Honda confirms which apply.
> Check your VIN with Honda Canada or call a Honda dealer with your VIN.
> www.honda.ca/en/recalls

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $14,850[5], $1,603 over the median of $13,247[4].

Lowest ask	$9,991
Middle half	$12,222 – $14,895
Median ask	$13,247
This car	$14,850

Same model year · 18 live listings · as of 28 Oct 2026

OTHER 2013 HONDA ACCORD LISTINGS [5]

Kitchener, ON · 158,133 km	$13,499
Montréal, QC · 120,038 km	$12,995
Montreal, QC · 179,974 km	$10,495
Guelph, ON · 90,079 km	$15,998
Toronto, ON · 159,875 km	$11,999
Duncan, BC · 81,254 km	$15,845

§4 EVENTS

2013	Model year 2013[1] Assembly plant Marysville, Ohio, United States
5 Jul 2013	Transport Canada recall 2013240[2] Issued for the model year · Fuel system
30 Jun 2017	Transport Canada recall 2017327[2] Issued for the model year · Electrical
10 Dec 2020	Transport Canada recall 2020609[2] Issued for the model year · Powertrain
19 Jun 2025	Transport Canada recall 2025340[2] Issued for the model year · Powertrain
24 Nov 2025	Listed for sale, Mississauga, ON[5] VAULT MOTORS · asking $14,850

25 Oct 2026	Listing last updated[5] asking $14,850

§5 DOCUMENTS

Window sticker	We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 18 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.