Register entry, as of 28 October 2026 Listed for sale Record ID 70118e9ade56

2015 Honda Accord EX-L

2.4 L, 4 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1HG	CR2F8	6	F	A	805484
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
American Honda Motor Co...	Accord · 2.4 L	Verified	2015	Marysville	Build sequence

§1 IDENTITY [1]

Model year	2015	Engine	2.4 L, 4 cylinders
Make	Honda	Fuel	Gasoline
Model	Accord	Drive	Not in the decode
Trim	EX-L	Maker	AMERICAN HONDA MOTOR CO., INC.
Body	Sedan	Plant	Marysville, Ohio, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/honda/accord/2015

4 recalls listed by Transport Canada for this model year

Powertrain

2020609 10 Dec 2020

Issue: On certain vehicles, the paint on the front axle shafts could delaminate or become damaged by road debris. As a result the axle shaft could corrode. If this happens, the axle shafts could break and cause a loss of power to the wheels. Also, if this happens and the vehicle is parked without the parking brake applied, the vehicle could roll away. Safety Risk: A loss of power to the wheels or a vehicle rollaway could increase the risk of a crash. Corrective Actions: Honda will notify owners by mail and instruct you to take your vehicle to a dealer to inspect, and if necessary, replace both axle shafts.

Electrical

2017327 30 Jun 2017

On certain vehicles, the case for the battery sensor may have been improperly manufactured with gaps that could allow for moisture intrusion. If moisture or road salt were to enter the battery sensor case, it could result in corrosion to the sensor, which could cause an electrical short, increasing the risk of a fire causing injury and/or property damage. Correction: Dealers will inspect, and replace the battery sensor as necessary.

High voltage

2015426 25 Sep 2015

On certain vehicles, the Cell Voltage Sensor (CVS) could incorrectly interpret electrical noise, which could cause the vehicle to switch to a fail-safe Electric Vehicle (EV) mode. If this were to occur while driving at highway speed, the internal combustion engine would shut off and the vehicle would experience a sudden loss of power, and the maximum speed limited to about 60 km/h. In fail-safe EV mode, visual and audible warnings would be displayed, and the vehicle may be able to travel for up to three kilometers before the high voltage battery discharges. If the battery were to completely discharge while the vehicle is still in operation, the vehicle will stall, resulting in a loss of motive power, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will update the CVS software.

Engine

2015091 27 Feb 2015

On certain vehicles, during assembly, some of the connecting rod bolts may not have been torqued to the correct specification. If a connecting rod bolt was not torqued correctly, it could loosen and result in the engine making an unusual rattling/knocking noise, leaking oil, and/or engine failure. Engine failure would result in a loss of motive power, which would increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the engine short block.

Listed for the model year, not checked against your VIN. Honda confirms which apply.
Check your VIN with Honda Canada or call a Honda dealer with your VIN.
www.honda.ca/en/recalls

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $16,580[5], $2,581 over the median of $13,999[4].

Lowest ask	$8,995
Middle half	$12,980 – $15,999
Median ask	$13,999
This car	$16,580

Same model year · 37 live listings · as of 28 Oct 2026

OTHER 2015 HONDA ACCORD LISTINGS [5]

Anjou, QC · 200,696 km	$8,995
Brossard, QC · 68,662 km	$16,995
Montreal, QC · 177,843 km	$11,995
Scarborough, ON · 153,000 km	$12,972
Waterloo, ON · 263,742 km	$8,999
Toronto, ON · 139,744 km	$13,888

§4 EVENTS

2015	Model year 2015[1] Assembly plant Marysville, Ohio, United States
27 Feb 2015	Transport Canada recall 2015091[2] Issued for the model year · Engine
25 Sep 2015	Transport Canada recall 2015426[2] Issued for the model year · High voltage
30 Jun 2017	Transport Canada recall 2017327[2] Issued for the model year · Electrical
10 Dec 2020	Transport Canada recall 2020609[2] Issued for the model year · Powertrain

24 Nov 2025	Listed for sale, Surrey, BC[5] Daytona Auto Sales · asking $16,580
28 Oct 2026	Listing last updated[5] asking $16,580

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 37 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.