Register entry, as of 29 October 2026 Listed for sale Record ID 198b750b3486

# 2013 Honda Accord EX-L V6

3.5 L, 6 cylinders · Coupe · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 1HG | CT2B8 | 5 | D | A | 800569 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| American Honda Motor Co... | Accord · 3.5 L | Verified | 2013 | Marysville | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2013 | Engine | 3.5 L, 6 cylinders |
| Make | Honda | Fuel | Gasoline |
| Model | Accord | Drive | Not in the decode |
| Trim | EX-L V6 | Maker | AMERICAN HONDA MOTOR CO., INC. |
| Body | Coupe | Plant | Marysville, Ohio, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/honda/accord/2013

**4** recalls listed by Transport Canada for this model year

### Powertrain

2025340 19 Jun 2025

Issue: On certain vehicles, the paint on the front axle shafts could become damaged. As a result, the axle shaft(s) could corrode. If this happens, the axle shaft(s) could break and cause a loss of power to the wheels. Additionally, if the vehicle is parked and the parking brake isn't applied, the vehicle could roll away. Note: This recall is an expansion of recall HO54 (Transport Canada recall no. 2020-609). Safety Risk: A loss of power to the wheels could increase the risk of a crash. A parked vehicle that moves suddenly could create a risk of a crash or an injury. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the axle shaft(s).

### Powertrain

2020609 10 Dec 2020

Issue: On certain vehicles, the paint on the front axle shafts could delaminate or become damaged by road debris. As a result the axle shaft could corrode. If this happens, the axle shafts could break and cause a loss of power to the wheels. Also, if this happens and the vehicle is parked without the parking brake applied, the vehicle could roll away. Safety Risk: A loss of power to the wheels or a vehicle rollaway could increase the risk of a crash. Corrective Actions: Honda will notify owners by mail and instruct you to take your vehicle to a dealer to inspect, and if necessary, replace both axle shafts.

### Electrical

2017327 30 Jun 2017

On certain vehicles, the case for the battery sensor may have been improperly manufactured with gaps that could allow for moisture intrusion. If moisture or road salt were to enter the battery sensor case, it could result in corrosion to the sensor, which could cause an electrical short, increasing the risk of a fire causing injury and/or property damage. Correction: Dealers will inspect, and replace the battery sensor as necessary.

### Fuel system

2013240 5 Jul 2013

On certain vehicles, the fuel tank may have been manufactured incorrectly and could leak. Fuel leakage, in the presence of an ignition source, could result in a fire causing property damage and/or personal injury. Correction: Dealers will replace the fuel tank.

> Listed for the model year, not checked against your VIN. Honda confirms which apply.
> Check your VIN with Honda Canada or call a Honda dealer with your VIN.
> www.honda.ca/en/recalls

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $12,995[5], the median[4].




| | |
|---|---|
| Lowest ask | $9,991 |
| Middle half | $11,997 – $14,880 |
| Median ask | $12,995 |
| This car | $12,995 |

Same model year · 19 live listings · as of 29 Oct 2026

### OTHER 2013 HONDA ACCORD LISTINGS [5]

| | |
|---|---|
| Kitchener, ON · 158,133 km | $13,499 |
| Montreal, QC · 179,974 km | $10,495 |
| Guelph, ON · 90,079 km | $15,998 |
| Toronto, ON · 159,875 km | $11,999 |
| Duncan, BC · 81,254 km | $15,845 |
| Ajax, ON · 132,381 km | $11,995 |

## §4 EVENTS

| | |
|---|---|
| 2013 | Model year 2013[1]<br>Assembly plant Marysville, Ohio, United States |
| 5 Jul 2013 | Transport Canada recall 2013240[2]<br>Issued for the model year · Fuel system |
| 30 Jun 2017 | Transport Canada recall 2017327[2]<br>Issued for the model year · Electrical |
| 10 Dec 2020 | Transport Canada recall 2020609[2]<br>Issued for the model year · Powertrain |
| 19 Jun 2025 | Transport Canada recall 2025340[2]<br>Issued for the model year · Powertrain |
| 26 Oct 2026 | Listed for sale, Montréal, QC[5]<br>Toyota Gabriel Centre-Ville · asking $12,995 |

| | |
|---|---|
| 29 Oct 2026 | Listing last updated[5]<br>asking $12,995 |

## §5 DOCUMENTS

| | |
|---|---|
| Window sticker | We do not collect window stickers for this manufacturer. |

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 19 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.