Register entry, as of 26 October 2026 Listed for sale Record ID 55762424ae57

2019 Honda Accord TOURING

1.5 L, 4 cylinders · 4x2 · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1HG	CV1F9	2	K	A	804065
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
American Honda Motor Co...	Accord · 1.5 L	Verified	2019	Marysville	Build sequence

§1 IDENTITY [1]

Model year	2019	Engine	1.5 L, 4 cylinders
Make	Honda	Fuel	Gasoline
Model	Accord	Drive	4x2
Trim	TOURING	Maker	AMERICAN HONDA MOTOR CO., INC.
Body	Sedan	Plant	Marysville, Ohio, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/honda/accord/2019

7 recalls listed by Transport Canada for this model year

Seats and restraints

2026251 21 May 2026

Issue: On certain vehicles, the weight sensor for the front passenger seat may not have been manufactured properly. As a result, the passenger-front airbag and knee airbag could deploy in a crash that doesn't require them to. Note: This recall is an expansion of Transport Canada recall no. 2024-059. If the weight sensor fails, the SRS warning light would turn on in the instrument panel. Safety Risk: An airbag system that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the passenger-front seat weight sensor.

Fuel system

2024262 6 May 2024

Issue: This recall is for low-pressure fuel pumps installed on certain vehicles or sold at dealerships as a replacement part. On certain vehicles, the low-pressure fuel pump could fail. If this happens, the engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This recall replaces Transport Canada recall no. 2023-679. Vehicles that were repaired under that recall don't require this repair. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel pump motor.

Fuel system

2023679 18 Dec 2023

This recall was replaced by Transport Canada recall no. 2024-262. Issue: This recall is for low-pressure fuel pumps installed on certain vehicles or sold at dealerships as a replacement part. On certain vehicles, the low-pressure fuel pump could fail. If this happens, the engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This is an expansion of Transport Canada recall nos. 2020-236 and 2021-182. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel pump motor.

Seats and restraints

2023127 9 Mar 2023

Issue: On certain vehicles, the seat belt buckles for the driver and front-passenger seats could wear over time and may not latch securely. If this happens, the seat belt could unlatch unexpectedly. Safety Risk: A seat belt that doesn't latch securely could create an increased risk of injury in a crash. Corrective Actions: Honda will notify owners by mail and instruct you to take your vehicle to a dealership to inspect the driver and front-passenger seat belt assemblies. In most cases, the seat belt buckle release buttons will be replaced. If the dealer determines that a buckle can't be repaired, it will be replaced with a new part.

Fuel system

2021182 26 Mar 2021

Issue: On certain vehicles, the low-pressure fuel pump could fail. If this happens, then engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This is an expansion of Transport Canada Recall No. 2020-236. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump motor.

Electrical

2020611 10 Dec 2020

Issue: On certain vehicles, a software problem in the Body Control Module (BCM) could cause different systems and warnings to stop working. This can include: the window defrosting/defogging system, windshield wipers, turn signals and lights, rearview camera display, and power windows. Safety Risk: Vehicle systems that stop working suddenly could increase the risk of a crash or injury. Corrective Actions: Honda will notify owners by mail and instruct you to take your vehicle to a dealer to update the BCM software.

1 more on the model-year record, cardog.app/tools/recalls/honda/accord/2019

> Listed for the model year, not checked against your VIN. Honda confirms which apply.
> Check your VIN with Honda Canada or call a Honda dealer with your VIN.
> www.honda.ca/en/recalls

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $24,951[5], $2,727 over the median of $22,224[4].

Lowest ask	$16,595
Middle half	$18,745 – $24,092
Median ask	$22,224
This car	$24,951

Same configuration · 16 live listings · as of 26 Oct 2026

OTHER 2019 HONDA ACCORD LISTINGS [5]

Milton, ON · 110,797 km	$20,999
Oakville, ON · 208,275 km	$16,595
Hamilton, ON · 208,275 km	$16,595
Milton, ON · 110,797 km	$20,999
St Thomas, ON · 208,275 km	$16,595
Gatineau, QC · 142,555 km	$17,995

§4 EVENTS

2019	Model year 2019[1] Assembly plant Marysville, Ohio, United States
28 May 2020	Transport Canada recall 2020236[2] Issued for the model year · Fuel system
10 Dec 2020	Transport Canada recall 2020611[2] Issued for the model year · Electrical
26 Mar 2021	Transport Canada recall 2021182[2] Issued for the model year · Fuel system
9 Mar 2023	Transport Canada recall 2023127[2] Issued for the model year · Seats and restraints
18 Dec 2023	Transport Canada recall 2023679[2] Issued for the model year · Fuel system
6 May 2024	Transport Canada recall 2024262[2] Issued for the model year · Fuel system
21 May 2026	Transport Canada recall 2026251[2] Issued for the model year · Seats and restraints
25 Oct 2026	Listed for sale, Huntsvillle, ON[5] Edmonds GM · asking $24,951
26 Oct 2026	Listing last updated[5] asking $24,951

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 16 live listings, as of 26 Oct 2026

[5] Live public dealer listings on Cardog, as of 26 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.