

Register entry, as of 28 October 2026

Listed for sale

Record ID c4617b091af9

2021 Honda Accord Sport

2.0 L, 4 cylinders · 4x2 · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER ^[1]**1HG**

WMI 1-3

American Honda Motor Co...

CV2F3

DESCRIPTOR 4-8

Accord · 2.0 L

X

CHECK 9

Verified

M

YEAR 10

2021

A

PLANT 11

Marysville

801029

SERIAL 12-17

Build sequence

§1 IDENTITY ^[1]

Model year	2021	Engine	2.0 L, 4 cylinders
Make	Honda	Fuel	Gasoline
Model	Accord	Drive	4x2
Trim	Sport	Maker	AMERICAN HONDA MOTOR CO., INC.
Body	Sedan	Plant	Marysville, Ohio, United States

§2 OBLIGATIONS ^[2]

cardog.app/tools/recalls/honda/accord/2021

2 recalls listed by Transport Canada for this model year

Seats and restraints

2026251 21 May 2026

Issue: On certain vehicles, the weight sensor for the front passenger seat may not have been manufactured properly. As a result, the passenger-front airbag and knee airbag could deploy in a crash that doesn't require them to. Note: This recall is an expansion of Transport Canada recall no. 2024-059. If the weight sensor fails, the SRS warning light would turn on in the instrument panel. Safety Risk: An airbag system that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the passenger-front seat weight sensor.

Airbag

2024059 1 Feb 2024

Issue: On certain vehicles, the weight sensor for the front passenger seat may not have been manufactured properly. As a result, the passenger-front airbag and knee airbag could deploy in a crash that doesn't require them to. Note: If the weight sensor fails, the SRS warning light would turn on in the instrument panel. Safety Risk: An airbag system that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership for an inspection if the SRS warning light is on. If the SRS warning light is on due to a faulty weight sensor, the weight sensor will be replaced. When repair parts are available, Honda will send you a second letter. They will advise you to take your vehicle to a dealership to replace the passenger-front seat weight sensor.

Listed for the model year, not checked against your VIN. Honda confirms which apply.

Check your VIN with Honda Canada or call a Honda dealer with your VIN.


www.honda.ca/en/recalls

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.^[3]



§3 VALUE [4]

This car asks \$31,495^[5], \$5,506 over the median of \$25,989^[4].



Lowest ask	\$19,950
Middle half	\$23,745 – \$28,002
Median ask	\$25,989
This car	\$31,495

Same model year · 31 live listings · as of 28 Oct 2026

OTHER 2021 HONDA ACCORD LISTINGS [5]

Lévis, QC · 134,000 km	\$19,950
Toronto, ON · 40,590 km	\$27,995
Toronto, ON · 119,000 km	\$23,450
Toronto, ON · 108,000 km	\$25,950
Toronto, ON · 113,000 km	\$26,450
Richmond, BC · 91,957 km	\$23,995

§4 EVENTS

2021	Model year 2021 ^[1] Assembly plant Marysville, Ohio, United States
1 Feb 2024	Transport Canada recall 2024059 ^[2] Issued for the model year · Airbag
21 May 2026	Transport Canada recall 2026251 ^[2] Issued for the model year · Seats and restraints
27 Oct 2026	Listed for sale, Toronto, ON ^[5] Midtown Honda · asking \$31,495

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN	[4] Cardog market quote, same model year, 31 live listings, as of 28 Oct 2026
[2] Transport Canada recall database, listed for the model year	[5] Live public dealer listings on Cardog, as of 28 Oct 2026
[3] NHTSA recall records (United States), listed for the model year	



STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

