Register entry, as of 28 October 2026 Listed for sale Record ID 130f866c6ae1

# 2025 Honda Accord SE

1.5 L, 4 cylinders · 4x2 · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 1HG | CY1F4 | 6 | S | A | 800659 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| American Honda Motor Co... | Accord · 1.5 L | Verified | 2025 | Marysville | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2025 | Engine | 1.5 L, 4 cylinders |
| Make | Honda | Fuel | Gasoline |
| Model | Accord | Drive | 4x2 |
| Trim | SE | Maker | AMERICAN HONDA MOTOR CO., INC. |
| Body | Sedan | Plant | Marysville, Ohio, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/honda/accord/2025

**2** recalls listed by Transport Canada for this model year

### Other

2026274 4 Jun 2026

Issue: On certain vehicles, if the tire repair kit nozzle is not properly attached to the tire valve, pressure could build up in the sealant bottle. As a result, excessive pressure could cause the bottle cap to detach. Safety Risk: If the bottle cap detaches, it could increase the risk of injury. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to replace the nozzle on the tire repair kit. If the sealant bottle has been previously used, it will be replaced.

### Powertrain

2025625 14 Nov 2025

Issue: Under certain conditions, a software problem could cause the integrated control module to reset. If this happens, there would be a loss of power to the wheels. Safety Risk: A sudden loss of power to the wheels could increase the risk of a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to update the integrated control module software.

Listed for the model year, not checked against your VIN. Honda confirms which apply.
Check your VIN with Honda Canada or call a Honda dealer with your VIN.
www.honda.ca/en/recalls

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $40,760[5], $3,864 over the median of $36,896[4].




| | |
|---|---|
| Lowest ask | $28,950 |
| Middle half | $33,897 – $40,952 |
| Median ask | $36,896 |
| This car | $40,760 |

Same configuration · 36 live listings · as of 28 Oct 2026

### OTHER 2025 HONDA ACCORD LISTINGS [5]

| | |
|---|---|
| Markham, ON · 39,821 km | $33,999 |
| Regina, SK · 12,811 km | $46,000 |
| Regina, SK · 12,811 km | $46,000 |
| Regina, SK · 12,811 km | $46,000 |
| Regina, SK · 12,811 km | $46,000 |
| Regina, SK · 12,811 km | $46,000 |

## §4 EVENTS

| | |
|---|---|
| 2025 | Model year 2025[1]<br>Assembly plant Marysville, Ohio, United States |
| 16 Sep 2025 | Listed for sale, Vancouver, BC[5]<br>Kingsway Honda · asking $40,760 |
| 14 Nov 2025 | Transport Canada recall 2025625[2]<br>Issued for the model year · Powertrain |
| 4 Jun 2026 | Transport Canada recall 2026274[2]<br>Issued for the model year · Other |
| 28 Oct 2026 | Listing last updated[5]<br>asking $40,760 |

## §5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

### SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 36 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.