Register entry, as of 29 October 2026 Listed for sale Record ID 9d19af8ba6a5

2024 Honda Accord Sport Hybrid, Sport Hybrid w/Out BSI

2.0 L, 4 cylinders · 4x2 · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1HG	CY2F5	0	R	A	801265
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
American Honda Motor Co...	Accord · 2.0 L	Verified	2024	Marysville	Build sequence

§1 IDENTITY [1]

Model year	2024	Engine	2.0 L, 4 cylinders
Make	Honda	Fuel	Gasoline
Model	Accord	Drive	4x2
Trim	Sport Hybrid, Sport Hybrid w/Out BSI	Maker	AMERICAN HONDA MOTOR CO., INC.
Body	Sedan	Plant	Marysville, Ohio, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/honda/accord/2024

4 recalls listed by Transport Canada for this model year

Other

2026274 4 Jun 2026

Issue: On certain vehicles, if the tire repair kit nozzle is not properly attached to the tire valve, pressure could build up in the sealant bottle. As a result, excessive pressure could cause the bottle cap to detach. Safety Risk: If the bottle cap detaches, it could increase the risk of injury. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to replace the nozzle on the tire repair kit. If the sealant bottle has been previously used, it will be replaced.

Powertrain

2025625 14 Nov 2025

Issue: Under certain conditions, a software problem could cause the integrated control module to reset. If this happens, there would be a loss of power to the wheels. Safety Risk: A sudden loss of power to the wheels could increase the risk of a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to update the integrated control module software.

Fuel system

2024606 15 Oct 2024

Issue: On certain vehicles, the high-pressure fuel pump may not have been manufactured properly. As a result, the fuel pump could crack and leak fuel. Safety Risk: A fuel leak can create the risk of a fire. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the high-pressure fuel pump.

Seats and restraints

2023623 22 Nov 2023

Issue: On certain vehicles, the seat belt pretensioner(s) may be missing a rivet. As a result, the seat belt pretensioner(s) may not work properly in a crash. Note: On Accord models, only the driver's side pretensioner could be affected. On HR-V models, both the driver's and passenger's side pretensioners could be affected. Safety Risk: A seat belt pretensioner that doesn't work properly could increase the risk of injury in a crash. Corrective Action: Honda will notify owners by mail and advise you to bring your vehicle to a dealership to inspect the seat belt pretensioner(s). If a rivet is missing, the pretensioner will be replaced.

Listed for the model year, not checked against your VIN. Honda confirms which apply.
Check your VIN with Honda Canada or call a Honda dealer with your VIN.
www.honda.ca/en/recalls

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $32,995[5], $2,103 under the median of $35,098[4].

Lowest ask	$32,888
Middle half	$32,971 – $40,395
Median ask	$35,098
This car	$32,995

Same configuration · 8 live listings · as of 29 Oct 2026

OTHER 2024 HONDA ACCORD LISTINGS [5]

Stouffville, ON · 58,900 km	$29,000
Toronto, ON · 94,000 km	$31,950
Pickering, ON · 43,512 km	$28,571
Markham, ON · 30,205 km	$32,499
North Vancouver, BC · 118,663 km	$28,550
Vancouver, BC · 118,663 km	$28,550

§4 EVENTS

2024	Model year 2024[1] Assembly plant Marysville, Ohio, United States
22 Nov 2023	Transport Canada recall 2023623[2] Issued for the model year · Seats and restraints
15 Oct 2024	Transport Canada recall 2024606[2] Issued for the model year · Fuel system
14 Nov 2025	Transport Canada recall 2025625[2] Issued for the model year · Powertrain
4 Jun 2026	Transport Canada recall 2026274[2] Issued for the model year · Other

26 Oct 2026	Listed for sale, Montreal, QC[5] Excel Honda · asking $32,995
29 Oct 2026	Listing last updated[5] asking $32,995

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 8 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.