Register entry, as of 29 November 2026 Listed for sale Record ID c143b3e07bbd

# 2011 Jeep Wrangler X

3.8 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 1J4 | AA2D1 | 0 | B | L | 517794 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Jeep · FCA US LLC | Wrangler · 3.8 L | Verified | 2011 | United States | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2011 | Engine | 3.8 L, 6 cylinders |
| Make | Jeep | Fuel | Gasoline |
| Model | Wrangler | Drive | 4WD |
| Trim | X | Maker | FCA US LLC |
| Body | Sport Utility Vehicle | Plant | United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/jeep/wrangler/2011

**4** recalls listed by Transport Canada for this model year

### Airbag

2016265 27 May 2016

On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, could eventually degrade the propellant contained in the passenger frontal airbag. This could cause the airbag to deploy with more force than normal. As a result, if the vehicle were involved in a collision that warrants airbag deployment, fragments could be propelled toward vehicle occupants, and the airbag assembly could be damaged, preventing proper function. These issues could increase the risk of injury. Correction: Dealers will replace the airbag inflator. Note: Canadian climate results in the propellant degrading slowly. The recall is being conducted as a precaution to address future risk, and is expected to replace airbag inflators before their function would be affected.

### Electrical

2014447 9 Oct 2014

On certain vehicles equipped with power heated mirrors, an electrical connector within the door may corrode, potentially resulting in an electrical short. This could result in a burning odour, smoke, or fire, increasing the risk of injury and/or damage to property. Correction: Dealers will modify electrical wiring and install a water shield.

### Steering

2011224 10 Jun 2011

Certain vehicles may have been built with a missing or incorrectly installed steering column pivot rivet. A steering column with a miss-installed rivet may not perform as intended in the event of a crash, which may increase the risk of personal injury. Correction: Dealers will inspect for steering column rivet presence and alignment, and repair as required.

### Suspension

2011101 3 Mar 2011

On certain vehicles, fastener torque for various front and rear axle attachments may degrade over time, due to variability in the axle painting process. This could result in noise or cause a degradation in steering and handling characteristics. A loss of vehicle control could result in a crash causing property damage and/or personal injury. Correction: Dealers will re-torque nineteen fasteners to specifications.

> Listed for the model year, not checked against your VIN. Jeep confirms which apply.
> Check your VIN with Mopar Canada or call a Jeep dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 11 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $13,691[5], $348 over the median of $13,343[4].




| | |
|---|---|
| Lowest ask | $8,995 |
| Middle half | $9,978 – $14,996 |
| Median ask | $13,343 |
| This car | $13,691 |

Same model year · 20 live listings · as of 28 Nov 2026

### OTHER 2011 JEEP WRANGLER LISTINGS [5]

| | |
|---|---|
| Brantford, ON · 217,000 km | $9,490 |
| Cochrane, AB · 204,671 km | $14,888 |
| Cochrane, AB · 250,679 km | $10,888 |
| Waterloo, ON · 186,904 km | $9,929 |
| Woodstock, ON · 194,563 km | $9,995 |
| Surrey, BC · 117,000 km | $15,800 |

## §4 EVENTS

| | |
|---|---|
| 2011 | Model year 2011[1]<br>Assembly plant United States |
| 3 Mar 2011 | Transport Canada recall 2011101[2]<br>Issued for the model year · Suspension |
| 10 Jun 2011 | Transport Canada recall 2011224[2]<br>Issued for the model year · Steering |
| 9 Oct 2014 | Transport Canada recall 2014447[2]<br>Issued for the model year · Electrical |
| 27 May 2016 | Transport Canada recall 2016265[2]<br>Issued for the model year · Airbag |
| 14 Nov 2026 | Listed for sale, Moncton, NB[5]<br>MacDonald Buick GMC Cadillac Ltd · asking $13,691 |

28 Nov 2026 **Listing last updated**[5]
asking $13,691

## §5 DOCUMENTS

Window sticker This VIN reads as model year 1981 or 2011, before our coverage for this manufacturer.

### SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 20 live listings, as of 28 Nov 2026
[5] Live public dealer listings on Cardog, as of 29 Nov 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.