

Register entry, as of 27 October 2026

Listed for sale

Record ID 77431325817c

# 2007 Jeep Wrangler Unlimited X / Sport

3.8 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

**1J8 GA391 7 7 L 222027**

WMI 1-3

Jeep · FCA US LLC

DESCRIPTOR 4-8

Wrangler · 3.8 L

CHECK 9

Verified

YEAR 10

2007

PLANT 11

Toledo

SERIAL 12-17

Build sequence

## §1 IDENTITY [1]

|            |                       |        |                             |
|------------|-----------------------|--------|-----------------------------|
| Model year | 2007                  | Engine | 3.8 L, 6 cylinders          |
| Make       | Jeep                  | Fuel   | Gasoline                    |
| Model      | Wrangler              | Drive  | 4WD                         |
| Trim       | Unlimited X / Sport   | Maker  | FCA US LLC                  |
| Body       | Sport Utility Vehicle | Plant  | Toledo, Ohio, United States |

## §2 OBLIGATIONS [2]

[cardog.app/tools/recalls/jeep/wrangler/2007](https://cardog.app/tools/recalls/jeep/wrangler/2007)

## 7 recalls listed by Transport Canada for this model year

### Airbag 2016265 27 May 2016

On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, could eventually degrade the propellant contained in the passenger frontal airbag. This could cause the airbag to deploy with more force than normal. As a result, if the vehicle were involved in a collision that warrants airbag deployment, fragments could be propelled toward vehicle occupants, and the airbag assembly could be damaged, preventing proper function. These issues could increase the risk of injury. Correction: Dealers will replace the airbag inflator. Note: Canadian climate results in the propellant degrading slowly. The recall is being conducted as a precaution to address future risk, and is expected to replace airbag inflators before their function would be affected.

### Airbag 2016216 12 May 2016

Certain vehicles which are subjected to dusty environments and/or extensive usage with top/doors removed, the clockspring assembly for the driver's airbag may become damaged and fail due to dust ingress. This could compromise the airbag circuit, which would result in the illumination of the airbag warning lamp and possible non-deployment of the driver's frontal airbag during a crash where deployment is warranted, which could increase the risk of personal injury to the seat occupant. Correction: Dealers will replace the clockspring, wheel back cover, and column shroud with a design that will further reduce the amount of dirt/dust intrusion.

### Brakes 2010185 4 Jun 2010

On certain vehicles, the right and left front inner fender liners could contact the right front and left rear brake tubes respectively, which could cause a partial loss of braking at the affected wheel. A partial loss of braking could result in a crash causing property damage, personal injury or death. Correction: Dealers will trim the front inner fender liners and replace the retaining fasteners. In addition, the right front and left rear brake tubes will be inspected and brake tubes found to have the corrosion protection coating compromised will be replaced.



**Powertrain**

2009333 19 Nov 2009

On certain vehicles equipped with an automatic transmission, operating under rigorous off-road conditions could cause the transmission fluid temperature to elevate to the point of causing transmission failure. Should the transmission fluid boil over, it may come into contact with a hot engine or exhaust component and cause a fire which could result in property damage, personal injury or death. Correction: Dealers will install a "HOTOIL" message in the instrument cluster and a chime to indicate elevated transmission fluid temperature.

**Brakes**

2007305 17 Sep 2007

On certain vehicles, software programmed into the Antilock Brake System (ABS) electronic control module may allow a momentary delay in braking when coasting up a hill during certain conditions. This could cause a crash without warning. Correction: Dealers will reprogram the ABS electronic control module with updated software.

**Other**

2007221 5 Jul 2007

On certain vehicles, the Totally Integrated Power Module (TIPM) was programmed with software that may allow the engine to stall under certain operating conditions. This could cause a crash without warning. Correction: Dealers will reprogram the TIPM.

1 more on the model-year record, [cardog.app/tools/recalls/jeep/wrangler/2007](https://cardog.app/tools/recalls/jeep/wrangler/2007)

Listed for the model year, not checked against your VIN. Jeep confirms which apply.

Check your VIN with Mopar Canada or call a Jeep dealer with your VIN.

[www.mopar.com/en-ca/my-vehicle/recalls/search.html](https://www.mopar.com/en-ca/my-vehicle/recalls/search.html)

United States: 10 NHTSA records for this model year, kept apart from the Canadian listing.<sup>[3]</sup>

**§3 VALUE [4]**

This car asks \$9,995<sup>[5]</sup>, \$1,483 under the median of \$11,478<sup>[4]</sup>.



|             |                     |
|-------------|---------------------|
| Lowest ask  | \$9,995             |
| Middle half | \$10,736 – \$12,219 |
| Median ask  | \$11,478            |
| This car    | \$9,995             |

Same model year · 2 live listings · as of 27 Oct 2026

**OTHER 2007 JEEP WRANGLER LISTINGS [5]**

St Catharines, ON · 246,148 km \$12,960

**§4 EVENTS**

|             |                                                                                      |
|-------------|--------------------------------------------------------------------------------------|
| 2007        | Model year 2007 <sup>[1]</sup><br>Assembly plant Toledo, Ohio, United States         |
| 27 Dec 2006 | Transport Canada recall 2006373 <sup>[2]</sup><br>Issued for the model year · Brakes |
| 5 Jul 2007  | Transport Canada recall 2007221 <sup>[2]</sup><br>Issued for the model year · Other  |
| 17 Sep 2007 | Transport Canada recall 2007305 <sup>[2]</sup><br>Issued for the model year · Brakes |



|             |                                                                                          |
|-------------|------------------------------------------------------------------------------------------|
| 19 Nov 2009 | Transport Canada recall 2009333 <sup>[2]</sup><br>Issued for the model year · Powertrain |
| 4 Jun 2010  | Transport Canada recall 2010185 <sup>[2]</sup><br>Issued for the model year · Brakes     |
| 12 May 2016 | Transport Canada recall 2016216 <sup>[2]</sup><br>Issued for the model year · Airbag     |
| 27 May 2016 | Transport Canada recall 2016265 <sup>[2]</sup><br>Issued for the model year · Airbag     |
| 10 Mar 2026 | Listed for sale, Stoney Creek, ON <sup>[5]</sup><br>Xpress Auto Sales · asking \$9,995   |
| 25 Oct 2026 | Listing last updated <sup>[5]</sup><br>asking \$9,995                                    |

## §5 DOCUMENTS

Window sticker      This VIN reads as model year 2007, before our coverage for this manufacturer.

## SOURCES

- |                                                                     |                                                                              |
|---------------------------------------------------------------------|------------------------------------------------------------------------------|
| [1] Cardog identity register, decoded from the VIN                  | [4] Cardog market quote, same model year, 2 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year     |                                                                              |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026                 |

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

