Register entry, as of 29 October 2026 Listed for sale Record ID fd7163f86e2a

2017 Lincoln Continental Reserve

3.0 L, 6 cylinders · AWD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1LN	6L9NC	2	H	5	614941
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Lincoln · FORD MOTOR CO…	Continental · 3.0 L	Verified	2017	Flat Rock	Build sequence

§1 IDENTITY [1]

Model year	2017	Engine	3.0 L, 6 cylinders
Make	Lincoln	Fuel	Gasoline
Model	Continental	Drive	AWD
Trim	Reserve	Maker	FORD MOTOR COMPANY
Body	Sedan	Plant	Flat Rock, Michigan, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/lincoln/continental/2017

4 recalls listed by Transport Canada for this model year

Visual system

2022485 29 Aug 2022

Issue: Over time, the coating on the lens for the rearview camera could degrade. If this happens, the rearview camera image may appear foggy or cloudy. Note: This recall only affected vehicles equipped with 360-degree camera systems. Safety Risk: A rearview camera image that does not display correctly could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and instruct you to take your vehicle to a dealership to replace the rearview camera.

Structure

2019063 12 Feb 2019

Issue: On certain vehicles, the door latches may not fully latch when a door is closed. If a door is not properly latched, it could open while the vehicle is moving. Safety Risk: A door that opens while the vehicle is moving could create an increased risk of injury. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to have the latch assemblies replaced on all four doors.

Airbag

2017102 1 Mar 2017

Certain vehicles may fail to comply with the requirements of Canada Motor Vehicle Safety Standard (CMVSS) 208 - Occupant Protection in Frontal Impacts. Certain driver frontal airbag modules may have been assembled incorrectly. In the event of a crash warranting deployment of the driver's frontal airbag, the airbag may not completely fill, or the airbag cushion may detach from the airbag module, which would not protect the driver as expected, and could increase the risk of injury. Correction: Dealers will replace the driver's frontal airbag.

Lights and instruments

2016499 12 Oct 2016

Certain vehicles equipped with High Intensity Discharge (HID) headlamps may not comply with the requirements of Canada Motor Vehicle Safety Standard (CMVSS) 108 - Lighting System and Retroreflective Devices. The headlamps may have been built with an incorrect lens, which fails to meet the replaceable light source marking requirements of the standard. The incorrect lens is also missing optics required to meet the turn signal light output requirements of the standard. Missing lens optics can reduce turn signal visibility to other drivers and pedestrians, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will inspect and replace headlamps as necessary.

> Listed for the model year, not checked against your VIN. Lincoln confirms which apply.
> Check your VIN with Lincoln Canada or call a Lincoln dealer with your VIN.
> www.lincolncanada.com/support/recalls/

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $25,995[5], the median[4].

Lowest ask	$18,557
Middle half	$20,888 – $27,995
Median ask	$25,995
This car	$25,995

Same model year · 9 live listings · as of 29 Oct 2026

OTHER 2017 LINCOLN CONTINENTAL LISTINGS [5]

Taber, AB · 147,890 km	$18,557
Lethbridge, AB · 147,890 km	$18,557
Calgary, AB · 58,011 km	$41,990
Olds, AB · 150,075 km	$24,388
Brantford, ON · 49,537 km	$28,724
Brantford, ON · 49,537 km	$28,724

§4 EVENTS

2017	Model year 2017[1] Assembly plant Flat Rock, Michigan, United States
12 Oct 2016	Transport Canada recall 2016499[2] Issued for the model year · Lights and instruments
1 Mar 2017	Transport Canada recall 2017102[2] Issued for the model year · Airbag
12 Feb 2019	Transport Canada recall 2019063[2] Issued for the model year · Structure
29 Aug 2022	Transport Canada recall 2022485[2] Issued for the model year · Visual system

28 Oct 2026	Listed for sale, Acton, ON[5] MERAKI AUTO INC. · asking $25,995
29 Oct 2026	Listing last updated[5] asking $25,995

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 9 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.