Register entry, as of 27 October 2026 Listed for sale Record ID 1b0ebeb664f9

2015 Nissan Leaf

FWD · Hatchback · Electric

VEHICLE IDENTIFICATION NUMBER [1]

1N4	AZ0CP	0	F	C	323819
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Nissan North America, Inc.	Leaf	Verified	2015	Smyma	Build sequence

§1 IDENTITY [1]

Model year	2015	Engine	Not in the decode
Make	Nissan	Fuel	Electric
Model	Leaf	Drive	FWD
Trim	Not in the decode	Maker	NISSAN NORTH AMERICA, INC.
Body	Hatchback	Plant	Smyma, Tennessee, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/nissan/leaf/2015

5 recalls listed by Transport Canada for this model year

Heater and defroster

2023225 3 Apr 2023

Issue: When the temperature is below -10° C, the defroster may not work properly if you follow the instructions in the owner's manual and use the maximum fan speed. As a result, you may not be able to defrost the windshield. Note: This is an expansion of Transport Canada recall 2023-045. Safety Risk: A windshield that cannot be defogged or defrosted can reduce visibility and increase the risk of a crash. Corrective Actions: Nissan will notify owners by mail and supply an addendum to the owner's manual that provides the correct settings for using the defroster when the temperature is below -10° C.

Brakes

2019044 1 Feb 2019

Issue: When the car is parked in very cold temperatures for a long time, a relay in the brake system may freeze. If this happens, multiple brake warnings will stay on in the instrument cluster after the car is started. The driver may also notice a hard brake pedal. If the car is driven, this could cause an increase in stopping distance. Safety Risk: An increase in stopping distance could create the risk of a crash. Corrective Actions: The company will mail owners a letter explaining this problem. The letter will describe how the brake warnings work. Drivers should not drive the car if the warnings stay on. Nissan will provide a 4 year/80,000 km warranty extension to repair the problem with relay freezing.

Airbag

2017215 18 Apr 2017

On certain vehicles, the passenger's frontal airbag may not deploy correctly due to an issue in manufacturing. As a result of long-term storage, there could be insufficient compression strength of the coolant within the inflator housing of the passenger's frontal airbag, which may cause the airbag to fail to deploy properly in the event of a crash (where deployment is warranted), which could increase the risk of injury to the front passenger occupant. Correction: Dealers will replace the passenger's frontal airbag inflator.

Seats and restraints

2016179 25 Apr 2016

On certain vehicles, a defect in the occupant classification system could allow an adult sitting in the front passenger seat to be classified as a child or an “empty seat”. This would suppress the airbag, which could increase the risk of injury in a crash. Correction: For affected Altima, Maxima, Murano, Rogue and Sentra vehicles, dealers will reprogram the airbag control unit and the occupant classification system control unit. For affected Leaf, NV200, Pathfinder, Q50 and JX35/QX60 vehicles, dealers will replace the occupant classification system electronic control unit.

Brakes

2016096 29 Feb 2016

On certain vehicles, when the vehicle is parked in cold temperatures for a prolonged period of time, the relay inside the electronic brake booster may freeze. This may result in increased brake pedal effort, which could increase stopping distances, potentially resulting in a crash causing injury and/or damage property. Correction: An Electric Vehicle certified dealer will reprogram the electrically-driven Intelligent Brake Control Unit software. Note: If this condition were present, a brake warning lamp would illuminate when the vehicle is first started to alert the operator of the issue.

> Listed for the model year, not checked against your VIN. Nissan confirms which apply.
> Check your VIN with Nissan Canada or call a Nissan dealer with your VIN.
> www.nissan.ca/service/vin-recall.html

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $10,930[5], $3,431 over the median of $7,499[4].



Lowest ask	$3,750
Middle half	$5,487 – $9,182
Median ask	$7,499
This car	$10,930

Same configuration · 8 live listings · as of 27 Oct 2026

OTHER 2015 NISSAN LEAF LISTINGS [5]

Deschaillons-Sur-St-Laurent, QC · 92,000 km	$6,999
Longueuil, QC · 117,402 km	$5,999
Charlesbourg, QC · 171,293 km	$3,950
Montréal, QC · 138,616 km	$3,750
Scarborough, ON · 110,556 km	$8,599
Abbotsford, BC · 135,500 km	$7,999

§4 EVENTS

2015	Model year 2015[1] Assembly plant Smyma, Tennessee, United States
29 Feb 2016	Transport Canada recall 2016096[2] Issued for the model year · Brakes
25 Apr 2016	Transport Canada recall 2016179[2] Issued for the model year · Seats and restraints

18 Apr 2017	Transport Canada recall 2017215[2] Issued for the model year · Airbag
1 Feb 2019	Transport Canada recall 2019044[2] Issued for the model year · Brakes
3 Apr 2023	Transport Canada recall 2023225[2] Issued for the model year · Heater and defroster
26 Oct 2026	Listed for sale, Victoria, BC[5] Malibu Motors · asking $10,930
27 Oct 2026	Listing last updated[5] asking $10,930

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 8 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.