Register entry, as of 27 October 2026 Listed for sale Record ID 21b62681031f

2021 Nissan Leaf SV

4x2 · Hatchback · Electric

VEHICLE IDENTIFICATION NUMBER [1]

1N4	AZ1CV	X	M	C	555572
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Nissan North America, Inc.	Leaf	Verified	2021	Smyrna	Build sequence

§1 IDENTITY [1]

Model year	2021	Engine	Not in the decode
Make	Nissan	Fuel	Electric
Model	Leaf	Drive	4x2
Trim	SV	Maker	NISSAN NORTH AMERICA, INC.
Body	Hatchback	Plant	Smyrna, Tennessee, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/nissan/leaf/2021

4 recalls listed by Transport Canada for this model year

High voltage

2025523 1 Oct 2025

Issue: On certain vehicles, the high-voltage battery could overheat while using level 3 quick charging. As a result, the battery could create smoke or heat, which can melt or damage the battery and nearby parts. Note: This recall is an expansion of Transport Canada recall 2024-542. Safety Risk: A battery that overheats can create a fire risk. Corrective Actions: To reduce the safety risk, Nissan recommends not to use the level 3 quick charging until the recall repairs have been completed. Nissan will notify owners by mail and advise you to take your vehicle to a dealership to update the vehicle software.

Visual system

2024068 5 Feb 2024

Issue: On certain vehicles, the rearview camera wiring harness could be damaged by movement and vibrations. If this happens, the rearview camera image may not display correctly or may not display at all. Canadian regulations require the rearview image to display when reversing. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Nissan will notify owners by mail and advise you to take your vehicle to a dealership to inspect and secure the rearview camera wiring harness. The dealer will replace the rearview camera and wiring harness, if necessary.

Powertrain

2023397 18 Jul 2023

Issue: Under certain conditions, the vehicle may not slow down after you release the accelerator pedal. This problem can only happen after a specific series of actions is performed in a short period of time, including disengaging the cruise control, changing the drive mode, and applying and releasing the accelerator pedal. If this happens, and you don't apply the brakes, the vehicle may not slow down as expected. Safety Risk: A vehicle that doesn't slow down as expected could increase the risk of a crash. Corrective Actions: Nissan will notify owners by mail and advise you to bring your vehicle to a dealership to reprogram the vehicle control module (VCM).

Heater and defroster

2023045 8 Feb 2023

Issue: When the temperature is below -10° C, the defroster may not work properly if you follow the instructions in the owner's manual and use the maximum fan speed. As a result, you may not be able to defrost the windshield. Safety Risk: A windshield that cannot be defogged or defrosted can reduce visibility and increase the risk of a crash. Corrective Actions: Nissan will notify owners by mail and supply an addendum to the owner's manual that provides the correct settings for using the defroster when the temperature is below -10° C.

Listed for the model year, not checked against your VIN. Nissan confirms which apply.
Check your VIN with Nissan Canada or call a Nissan dealer with your VIN.
www.nissan.ca/service/vin-recall.html

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $20,995[5], $443 under the median of $21,438[4].



Lowest ask	$19,988
Middle half	$20,743 – $22,155
Median ask	$21,438
This car	$20,995

Same model year · 4 live listings · as of 27 Oct 2026

OTHER 2021 NISSAN LEAF LISTINGS [5]

Orleans, ON · 77,455 km	$20,588
Kelowna, BC · 70,709 km	$19,988
Burnaby, BC · 75,766 km	$22,980
Burnaby, BC · 75,766 km	$22,980
Gatineau, QC · 61,964 km	$21,880

§4 EVENTS

2021	Model year 2021[1] Assembly plant Smyrna, Tennessee, United States
8 Feb 2023	Transport Canada recall 2023045[2] Issued for the model year · Heater and defroster
18 Jul 2023	Transport Canada recall 2023397[2] Issued for the model year · Powertrain
5 Feb 2024	Transport Canada recall 2024068[2] Issued for the model year · Visual system
1 Oct 2025	Transport Canada recall 2025523[2] Issued for the model year · High voltage
26 Oct 2026	Listed for sale, Chilliwack, BC[5] Bannister Nissan Chilliwak · asking $20,995

27 Oct 2026	Listing last updated[5] asking $20,995

§5 DOCUMENTS

Window sticker	We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 4 live listings, as of 27 Oct 2026

[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.