Register entry, as of 28 October 2026 Listed for sale Record ID 917290af16d1

2021 Nissan Altima SR

2.5 L, 4 cylinders · 4WD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1N4	BL4CW	6	M	N	335883
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Nissan North America, Inc.	Altima · 2.5 L	Verified	2021	Canton	Build sequence

§1 IDENTITY [1]

Model year	2021	Engine	2.5 L, 4 cylinders
Make	Nissan	Fuel	Gasoline
Model	Altima	Drive	4WD
Trim	SR	Maker	NISSAN NORTH AMERICA, INC.
Body	Sedan	Plant	Canton, Mississippi, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/nissan/altima/2021

2 recalls listed by Transport Canada for this model year

Visual system

2023504 11 Sep 2023

Issue: On certain vehicles, the rearview camera wiring harness could be damaged by movement and vibrations. If this happens, the rearview camera image may not display correctly or may not display at all. Canadian regulations require the rearview image to display when reversing. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Nissan will notify owners by mail and advise you to bring your vehicle to a dealership to inspect the rearview camera wiring harness, apply a protective tape, and reroute it. If the wiring is damaged, the rearview camera and wiring harness will be replaced.

Steering

2021117 5 Mar 2021

Issue: On certain vehicles, the steering tie rod nut may not have been properly tightened. As a result, the tie rod could become loose and separate from the steering knuckle. This could result in a loss of steering control. Safety Risk: A loss of steering control could create a risk of a crash. Corrective Actions: Nissan will notify owners by mail and instruct you take your vehicle to a dealer to re-tighten the nut on the left and right steering tie rods. If the nut is missing, a new nut and washer will be installed.

Listed for the model year, not checked against your VIN. Nissan confirms which apply.
Check your VIN with Nissan Canada or call a Nissan dealer with your VIN.
www.nissan.ca/service/vin-recall.html

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $19,487[5], $963 under the median of $20,450[4].



Lowest ask	$15,999
Middle half	$19,487 – $22,995
Median ask	$20,450
This car	$19,487

Same model year · 13 live listings · as of 28 Oct 2026

OTHER 2021 NISSAN ALTIMA LISTINGS [5]

Cornwall, ON · 85,904 km	$21,000
North Bay, ON · 29,661 km	$24,695
Toronto, ON · 69,404 km	$19,999
Peterborough, ON · 50,489 km	$24,990
Etobicoke, ON · 139,168 km	$15,999
Carleton Place, ON · 56,233 km	$24,491

§4 EVENTS

2021	Model year 2021[1] Assembly plant Canton, Mississippi, United States
5 Mar 2021	Transport Canada recall 2021117[2] Issued for the model year · Steering
11 Sep 2023	Transport Canada recall 2023504[2] Issued for the model year · Visual system
21 Jun 2026	Listed for sale, Levis, QC[5] St-Nicolas Nissan · asking $19,487
28 Oct 2026	Listing last updated[5] asking $19,487

§5 DOCUMENTS

Window sticker — We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 13 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.