Register entry, as of 28 October 2026 Listed for sale Record ID d77f99edebae

2019 Nissan Altima SV

2.5 L, 4 cylinders · 4WD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1N4	BL4DW	9	K	N	326588
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Nissan North America, Inc.	Altima · 2.5 L	Verified	2019	Canton	Build sequence

§1 IDENTITY [1]

Model year	2019	Engine	2.5 L, 4 cylinders
Make	Nissan	Fuel	Gasoline
Model	Altima	Drive	4WD
Trim	SV	Maker	NISSAN NORTH AMERICA, INC.
Body	Sedan	Plant	Canton, Mississippi, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/nissan/altima/2019

4 recalls listed by Transport Canada for this model year

Visual system

2023504 11 Sep 2023

Issue: On certain vehicles, the rearview camera wiring harness could be damaged by movement and vibrations. If this happens, the rearview camera image may not display correctly or may not display at all. Canadian regulations require the rearview image to display when reversing. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Nissan will notify owners by mail and advise you to bring your vehicle to a dealership to inspect the rearview camera wiring harness, apply a protective tape, and reroute it. If the wiring is damaged, the rearview camera and wiring harness will be replaced.

Tires

2021140 12 Mar 2021

Issue: Certain vehicles were built with tires that may have been cured too long. As a result, the sidewall could crack or the tread and belts could separate. This could lead to a sudden loss of air pressure and could cause a tire failure. Note: This recall only affects certain Continental tires, with specific date codes and mold numbers. Safety Risk: A tire failure could cause a loss of control and increase the risk of a crash. Corrective Actions: Nissan will notify the owners by mail and instruct them to take the vehicle to a dealer to inspect and replace the tires, if necessary.

Visual system

2019459 13 Sep 2019

Issue: On certain vehicles, the rear view camera system does not return to the default setting when the transmission is shifted to reverse. This could cause a reduction in rear visibility if a driver had previously adjusted the camera display. Canadian regulations require that the rear view image returns to its original setting each time the camera is turned on. Safety Risk: Reduced rear visibility could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct them to take their vehicle to a dealer to update the software for the rear view camera.

Brakes

2019156 26 Mar 2019

Issue: On certain vehicles, the brake light switch may not be in the correct position. This would result in the brake lamps staying on at all times. This could also allow the transmission to be shifted out of the park (P) position without applying the brakes. Safety Risk: Shifting out of park without applying the brakes could cause unintended vehicle movement. If the brake lights stay on, a following driver may not recognize when a vehicle ahead is braking. Either of these outcomes could increase the risk of a crash. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to inspect the brake pedal assembly. The assembly will be replaced as required.

> Listed for the model year, not checked against your VIN. Nissan confirms which apply.
> Check your VIN with Nissan Canada or call a Nissan dealer with your VIN.
> www.nissan.ca/service/vin-recall.html

United States: 7 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $14,999[5], $2,000 under the median of $16,999[4].



Lowest ask	$8,999
Middle half	$14,699 – $19,359
Median ask	$16,999
This car	$14,999

Same model year · 14 live listings · as of 28 Oct 2026

OTHER 2019 NISSAN ALTIMA LISTINGS [5]

Pickering, ON · 72,539 km	$20,998
100 Mile House, BC · 81,185 km	$18,995
Penticton, BC · 181,500 km	$15,404
Ottawa, ON · 147,229 km	$14,599
Prince George, BC · 109,353 km	$18,995
Kitchener, ON · 67,306 km	$16,999

§4 EVENTS

2019	Model year 2019[1] Assembly plant Canton, Mississippi, United States
26 Mar 2019	Transport Canada recall 2019156[2] Issued for the model year · Brakes
13 Sep 2019	Transport Canada recall 2019459[2] Issued for the model year · Visual system
12 Mar 2021	Transport Canada recall 2021140[2] Issued for the model year · Tires
11 Sep 2023	Transport Canada recall 2023504[2] Issued for the model year · Visual system

16 Dec 2025	Listed for sale, Halton Hills, ON[5] Motor Palace · asking $14,999
28 Oct 2026	Listing last updated[5] asking $14,999

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 14 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.