Register entry, as of 27 October 2026 Listed for sale Record ID 802293920728

# 2020 Nissan Altima Platinum

2.5 L, 4 cylinders · 4WD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 1N4 | BL4FW | 4 | L | N | 303508 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Nissan North America, Inc. | Altima · 2.5 L | Verified | 2020 | Canton | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2020 | Engine | 2.5 L, 4 cylinders |
| Make | Nissan | Fuel | Gasoline |
| Model | Altima | Drive | 4WD |
| Trim | Platinum | Maker | NISSAN NORTH AMERICA, INC. |
| Body | Sedan | Plant | Canton, Mississippi, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/nissan/altima/2020

**3** recalls listed by Transport Canada for this model year

### Visual system

2023504 11 Sep 2023

Issue: On certain vehicles, the rearview camera wiring harness could be damaged by movement and vibrations. If this happens, the rearview camera image may not display correctly or may not display at all. Canadian regulations require the rearview image to display when reversing. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Nissan will notify owners by mail and advise you to bring your vehicle to a dealership to inspect the rearview camera wiring harness, apply a protective tape, and reroute it. If the wiring is damaged, the rearview camera and wiring harness will be replaced.

### Tires

2021140 12 Mar 2021

Issue: Certain vehicles were built with tires that may have been cured too long. As a result, the sidewall could crack or the tread and belts could separate. This could lead to a sudden loss of air pressure and could cause a tire failure. Note: This recall only affects certain Continental tires, with specific date codes and mold numbers. Safety Risk: A tire failure could cause a loss of control and increase the risk of a crash. Corrective Actions: Nissan will notify the owners by mail and instruct them to take the vehicle to a dealer to inspect and replace the tires, if necessary.

### Steering

2021117 5 Mar 2021

Issue: On certain vehicles, the steering tie rod nut may not have been properly tightened. As a result, the tie rod could become loose and separate from the steering knuckle. This could result in a loss of steering control. Safety Risk: A loss of steering control could create a risk of a crash. Corrective Actions: Nissan will notify owners by mail and instruct you take your vehicle to a dealer to re-tighten the nut on the left and right steering tie rods. If the nut is missing, a new nut and washer will be installed.

> Listed for the model year, not checked against your VIN. Nissan confirms which apply.
> Check your VIN with Nissan Canada or call a Nissan dealer with your VIN.
> www.nissan.ca/service/vin-recall.html

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $19,888[5], $1,893 over the median of $17,995[4].

| | |
|---|---|
| Lowest ask | $15,390 |
| Middle half | $17,119 – $19,978 |
| Median ask | $17,995 |
| This car | $19,888 |

Same model year · 10 live listings · as of 27 Oct 2026

### OTHER 2020 NISSAN ALTIMA LISTINGS [5]

| | |
|---|---|
| Lasalle, ON · 60,588 km | $22,938 |
| La Guadeloupe, QC · 115,000 km | $16,389 |
| Carignan, QC · 103,440 km | $16,995 |
| Toronto, ON · 113,540 km | $17,995 |
| Lévis, QC · 44,975 km | $17,995 |
| Calgary, AB · 86,010 km | $24,888 |

## §4 EVENTS

| | |
|---|---|
| 2020 | Model year 2020[1]<br>Assembly plant Canton, Mississippi, United States |
| 5 Mar 2021 | Transport Canada recall 2021117[2]<br>Issued for the model year · Steering |
| 12 Mar 2021 | Transport Canada recall 2021140[2]<br>Issued for the model year · Tires |
| 11 Sep 2023 | Transport Canada recall 2023504[2]<br>Issued for the model year · Visual system |
| 26 Oct 2026 | Listed for sale, Calgary, AB[5]<br>Fish Creek Nissan · asking $19,888 |
| 27 Oct 2026 | Listing last updated[5]<br>asking $19,888 |

## §5 DOCUMENTS

Window sticker We have not collected this label yet.

## SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 10 live listings, as of 27 Oct 2026

[5] Live public dealer listings on Cardog, as of 27 Oct 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.