Register entry, as of 27 October 2026 Listed for sale Record ID c2ae6a6c5c60

# 2019 Nissan Titan

5.6 L, 8 cylinders · 4WD · Pickup · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 1N6 | AA1E5 | 3 | K | N | 521860 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Nissan North America, Inc. | Titan · 5.6 L | Verified | 2019 | Canton | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2019 | Engine | 5.6 L, 8 cylinders |
| Make | Nissan | Fuel | Gasoline |
| Model | Titan | Drive | 4WD |
| Trim | Not in the decode | Maker | NISSAN NORTH AMERICA, INC. |
| Body | Pickup | Plant | Canton, Mississippi, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/nissan/titan/2019

**3** recalls listed by Transport Canada for this model year

### Tires

2021140 12 Mar 2021

Issue: Certain vehicles were built with tires that may have been cured too long. As a result, the sidewall could crack or the tread and belts could separate. This could lead to a sudden loss of air pressure and could cause a tire failure. Note: This recall only affects certain Continental tires, with specific date codes and mold numbers. Safety Risk: A tire failure could cause a loss of control and increase the risk of a crash. Corrective Actions: Nissan will notify the owners by mail and instruct them to take the vehicle to a dealer to inspect and replace the tires, if necessary.

### Visual system

2019459 13 Sep 2019

Issue: On certain vehicles, the rear view camera system does not return to the default setting when the transmission is shifted to reverse. This could cause a reduction in rear visibility if a driver had previously adjusted the camera display. Canadian regulations require that the rear view image returns to its original setting each time the camera is turned on. Safety Risk: Reduced rear visibility could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct them to take their vehicle to a dealer to update the software for the rear view camera.

### Electrical

2019319 27 Jun 2019

Issue: On certain trucks, the alternator wiring harness may have been damaged during assembly. This could cause a short circuit to occur. It may result in abnormal electrical activity (i.e. interior lights flickering, intermittent radio) and could prevent the battery from charging. Over time, the battery could discharge. Ultimately, this may result in an engine stall. In rare cases, the short circuit may result in an engine compartment fire. Safety Risk: A loss of engine power and/or a loss of power to electrical systems could increase the risk of a crash. An electrical short circuit could create a fire risk. Corrective Actions: Nissan will notify owners by mail and instruct them to take their truck to a dealer to inspect the alternator wiring harness. The harness will be repositioned or replaced if necessary.

> Listed for the model year, not checked against your VIN. Nissan confirms which apply.
> Check your VIN with Nissan Canada or call a Nissan dealer with your VIN.
> www.nissan.ca/service/vin-recall.html

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $32,877[5], $4,828 over the median of $28,049[4].

| | |
|---|---|
| Lowest ask | $18,888 |
| Middle half | $21,498 – $33,343 |
| Median ask | $28,049 |
| This car | $32,877 |

Same configuration · 14 live listings · as of 27 Oct 2026

### OTHER 2019 NISSAN TITAN LISTINGS [5]

| | |
|---|---|
| Newmarket, ON · 130,688 km | $28,198 |
| Beloeil, QC · 166,085 km | $20,995 |
| Ottawa, ON · 182,308 km | $19,871 |
| Ajax, ON · 93,800 km | $35,000 |
| Fredericton, NB · 49,286 km | $35,381 |
| Innisfil, ON · 135,045 km | $27,900 |

## §4 EVENTS

| | |
|---|---|
| 2019 | Model year 2019[1]<br>Assembly plant Canton, Mississippi, United States |
| 27 Jun 2019 | Transport Canada recall 2019319[2]<br>Issued for the model year · Electrical |
| 13 Sep 2019 | Transport Canada recall 2019459[2]<br>Issued for the model year · Visual system |
| 12 Mar 2021 | Transport Canada recall 2021140[2]<br>Issued for the model year · Tires |
| 26 Oct 2026 | Listed for sale, Fernie, BC[5]<br>FERNIE CHRYSLER · asking $32,877 |

## §5 DOCUMENTS

Window sticker We have not collected this label yet.

## SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 14 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.