Register entry, as of 27 October 2026 Listed for sale Record ID 5fe53aae3faf

2017 Nissan NV High Roof

5.6 L, 8 cylinders · Cargo Van · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1N6	AF0LY	6	H	N	802374
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Nissan North America, Inc.	NV · 5.6 L	Verified	2017	Canton	Build sequence

§1 IDENTITY [1]

Model year	2017	Engine	5.6 L, 8 cylinders
Make	Nissan	Fuel	Gasoline
Model	NV	Drive	Not in the decode
Trim	High Roof	Maker	NISSAN NORTH AMERICA, INC.
Body	Cargo Van	Plant	Canton, Mississippi, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/nissan/nv/2017

2 recalls listed by Transport Canada for this model year

Airbag

2020136 31 Mar 2020

Issue: On certain vehicles, the driver-front airbag inflator could be defective. This could cause the airbag to deploy with more force than normal. It could also cause the inflator to rupture. If the airbag inflator ruptures, fragments could be propelled toward the occupants or cause damage to the airbag and prevent it from inflating properly. Safety Risk: If the vehicle is involved in a crash where the airbag deploys, the airbag inflator could rupture and create a risk of injury or death. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to replace the driver-front airbag inflator or airbag module.

Electrical

2018440 22 Aug 2018

On certain vehicles equipped with a mechanical key ignition system, a spring in the ignition switch could wear and break. This may allow the ignition key to inadvertently move from the ON position to the accessory (ACC) position while driving, causing the engine to shut off and the airbag system to lose power. The resulting loss of motive power, and change in steering and brake forces could increase the risk of a crash causing injury and/or damage to property. Additionally, in the event of a crash, this may also cause the airbags not to function. Correction: Dealers will inspect the lot number of the ignition switch, and replace it with a new one if it is affected. Note: Until the correction is performed, owners are advised to remove all objects from the ignition key ring, such as additional keys, key chains, etc.

Listed for the model year, not checked against your VIN. Nissan confirms which apply.
Check your VIN with Nissan Canada or call a Nissan dealer with your VIN.
www.nissan.ca/service/vin-recall.html

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $24,900[5], $5,555 over the median of $19,345[4].



Lowest ask	$14,777
Middle half	$15,968 – $22,718
Median ask	$19,345
This car	$24,900

Same model year · 8 live listings · as of 27 Oct 2026

§4 EVENTS

2017	Model year 2017[1] Assembly plant Canton, Mississippi, United States
22 Aug 2018	Transport Canada recall 2018440[2] Issued for the model year · Electrical
31 Mar 2020	Transport Canada recall 2020136[2] Issued for the model year · Airbag
25 Oct 2025	Listed for sale, Milton, ON[5] Alexander The Great Inc. · asking $24,900
27 Oct 2026	Listing last updated[5] asking $24,900

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 8 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.