Register entry, as of 29 October 2026 Listed for sale Record ID 726f31f8626c

# 2025 Volkswagen Atlas Cross Sport 4Motion SEL

2.0 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 1V2 | BE2CA | 8 | S | C | 220089 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Volkswagen Group Of Ame… | Atlas Cross Sport · 2.0 L | Verified | 2025 | Chattanooga | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2025 | Engine | 2.0 L, 4 cylinders |
| Make | Volkswagen | Fuel | Gasoline |
| Model | Atlas Cross Sport | Drive | AWD |
| Trim | 4Motion SEL | Maker | VOLKSWAGEN GROUP OF AMERICA, INC. |
| Body | Sport Utility Vehicle | Plant | Chattanooga, Tennessee, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/volkswagen/atlas-cross-sport/2025

**4** recalls listed by Transport Canada for this model year

### Visual system

2026357 22 Jul 2026

Issue: Under certain conditions, a software problem could cause the rearview camera image not to display when the transmission is shifted into reverse. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Volkswagen will notify owners by mail and advise you to take your vehicle to a dealership to update the rearview camera software.

### Suspension

2025355 25 Jun 2025

Issue: On certain vehicles, certain bolt(s) on the chassis, brake system and/or suspension may not have been tightened properly. As a result, the bolt(s) could loosen and cause a loss of control. Safety Risk: A loss of control could increase the risk of a crash. Corrective Actions: Volkswagen will notify owners by mail and advise you to take your vehicle to a dealership to replace the affected bolt(s) on the chassis, brake system and/or suspension.

### Visual system

2025272 21 May 2025

Issue: On certain vehicles, a software problem could cause the rearview camera image not to display properly. Canadian regulations require the rearview image to display properly when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that doesn't display properly could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Volkswagen will notify owners by mail and advise you to take your vehicle to a dealership to update the infotainment display software.

### Engine

2025079 17 Feb 2025

Issue: On certain vehicles, the engine cover may come loose after service. If this happens, the engine cover could contact hot surfaces in the engine compartment and melt. Safety Risk: An engine cover that melts onto a hot surface could create the risk of a fire. Corrective Actions: Volkswagen will notify owners by mail and advise you to take your vehicle to a dealership to remove the engine cover.

> Listed for the model year, not checked against your VIN. Volkswagen confirms which apply.
> Check your VIN with Volkswagen Canada or call a Volkswagen dealer with your VIN.
> www.vw.ca/en/owners-and-drivers/recalls.html

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $44,900[5], $1,080 under the median of $45,980[4].




| | |
|---|---|
| Lowest ask | $37,990 |
| Middle half | $43,008 – $49,597 |
| Median ask | $45,980 |
| This car | $44,900 |

Same model year · 37 live listings · as of 29 Oct 2026

OTHER 2025 VOLKSWAGEN ATLAS CROSS SPORT LISTINGS [5]

| | |
|---|---|
| Mirabel, QC · 22,348 km | $43,344 |
| Kitchener, ON · 12,856 km | $55,697 |
| Edmonton, AB · 44,092 km | $38,900 |
| London, ON · 12,856 km | $55,697 |
| Stratford, ON · 46,589 km | $50,000 |
| Kentville, NS · 10,940 km | $43,477 |

## §4 EVENTS

| | |
|---|---|
| 2025 | Model year 2025[1]<br>Assembly plant Chattanooga, Tennessee, United States |
| 17 Feb 2025 | Transport Canada recall 2025079[2]<br>Issued for the model year · Engine |
| 21 May 2025 | Transport Canada recall 2025272[2]<br>Issued for the model year · Visual system |
| 25 Jun 2025 | Transport Canada recall 2025355[2]<br>Issued for the model year · Suspension |
| 17 Apr 2026 | Listed for sale, Edmonton, AB[5]<br>Norden Volkswagen · asking $44,900 |
| 22 Jul 2026 | Transport Canada recall 2026357[2]<br>Issued for the model year · Visual system |

| | |
|---|---|
| 29 Oct 2026 | Listing last updated[5]<br>asking $44,900 |

## §5 DOCUMENTS

| | |
|---|---|
| Window sticker | We do not collect window stickers for this manufacturer. |

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 37 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.