Register entry, as of 29 November 2026 Listed for sale Record ID 5651dcebdbf1

2022 Volkswagen Atlas 4Motion SEL

3.6 L, 6 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1V2	BR2CA	1	N	C	520792
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Volkswagen Group Of Ame…	Atlas · 3.6 L	Verified	2022	Chattanooga	Build sequence

§1 IDENTITY [1]

Model year	2022	Engine	3.6 L, 6 cylinders
Make	Volkswagen	Fuel	Gasoline
Model	Atlas	Drive	AWD
Trim	4Motion SEL	Maker	VOLKSWAGEN GROUP OF AMERICA, INC.
Body	Sport Utility Vehicle	Plant	Chattanooga, Tennessee, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/volkswagen/atlas/2022

7 recalls listed by Transport Canada for this model year

Airbag

2024354 19 Jun 2024

Issue: On certain vehicles, the passenger occupant detection system (PODS) may malfunction. This could cause the airbag system to turn off the passenger-front airbag even when a passenger is seated. Note: This problem would cause an error message to display on the instrument panel and a warning chime to sound. The airbag indicator light would also display "passenger airbag off". Safety Risk: An airbag that is turned off could increase the risk of injury to a passenger in a crash. Corrective Actions: Volkswagen will notify owners by mail and advise you to take your vehicle to a dealership to replace the PODS sensor mat and seat harness. Volkswagen advises that you shouldn't use the front passenger seat if a PODS error message displays on the instrument panel or if the airbag indicator light displays "passenger airbag off" with an occupant in the seat.

Suspension

2022612 26 Oct 2022

Issue: On certain vehicles, the bolts for the left-rear trailing arm may not have been properly tightened. As a result, the bolts may loosen over time and fall out. If this happens, the trailing arm may break and cause a sudden loss of vehicle control. Safety Risk: A loss of control could create the risk of a crash. Corrective Actions: Volkswagen will notify owners by mail and instruct you to take your vehicle to a dealership to replace the left-rear trailing arm bolts.

Engine

2022576 7 Oct 2022

Issue: On certain vehicles, the connecting rod bearings may become damaged. If this happens, the engine could make abnormal noises and a warning light may turn on. If you continue to drive the vehicle with these symptoms, the engine could fail and/or an oil leak could occur. Safety Risk: An engine failure can cause a sudden loss of power, which could increase the risk of a crash. An oil leak could create the risk of a vehicle fire. Corrective actions: Volkswagen will notify owners by mail and instruct you to take your vehicle to a dealership for an engine inspection test. The engine will be replaced, if necessary.

Structure

2022489 31 Aug 2022

Issue: On certain vehicles, the trailer hitch bolts may not have been properly tightened. As a result, the bolts could loosen, and the hitch could detach from the vehicle while towing a trailer. Safety Risk: A trailer hitch that detaches from a vehicle could create a risk of a crash. Corrective Actions: Volkswagen will notify owners by mail and instruct you to take your vehicle to a dealership to tighten the trailer hitch bolts.

Visual system

2022382 20 Jul 2022

Issue: Under certain conditions, the rearview camera image may not appear on the center screen. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Volkswagen will notify owners by mail and instruct you to take your vehicle to a dealership to update the infotainment software.

Fuel system

2022182 13 Apr 2022

Issue: On certain vehicles, the long fuel injectors may have been assembled without a filter element. As a result, fuel could leak into the engine compartment. Safety Risk: A fuel leak in the engine compartment can create the risk of a fire. Corrective Actions: Volkswagen will notify owners by mail and instruct you to take your vehicle to a dealership to replace the long fuel injectors.


1 more on the model-year record, cardog.app/tools/recalls/volkswagen/atlas/2022

> Listed for the model year, not checked against your VIN. Volkswagen confirms which apply. Check your VIN with Volkswagen Canada or call a Volkswagen dealer with your VIN.
> www.vw.ca/en/owners-and-drivers/recalls.html

United States: 7 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $24,998[5], $2,996 under the median of $27,994[4].



Lowest ask	$19,995
Middle half	$26,120 – $30,890
Median ask	$27,994
This car	$24,998

Same configuration · 22 live listings · as of 29 Nov 2026

OTHER 2022 VOLKSWAGEN ATLAS LISTINGS [5]

Dartmouth, NS · 86,265 km	$34,985
Mascouche, QC · 90,363 km	$27,995
Gananoque, ON · 90,738 km	$3,199,995
Edmonton, AB · 116,390 km	$27,994
London, ON · 269,020 km	$17,995
Mascouche, QC · 48,225 km	$34,995

§4 EVENTS

2022 Model year 2022[1]
Assembly plant Chattanooga, Tennessee, United States

11 Mar 2022	Transport Canada recall 2022110[2] Issued for the model year · Airbag
13 Apr 2022	Transport Canada recall 2022182[2] Issued for the model year · Fuel system
20 Jul 2022	Transport Canada recall 2022382[2] Issued for the model year · Visual system
31 Aug 2022	Transport Canada recall 2022489[2] Issued for the model year · Structure
7 Oct 2022	Transport Canada recall 2022576[2] Issued for the model year · Engine
26 Oct 2022	Transport Canada recall 2022612[2] Issued for the model year · Suspension
19 Jun 2024	Transport Canada recall 2024354[2] Issued for the model year · Airbag
22 Nov 2026	Listed for sale, Woodbridge, ON[5] Martin Grove Volkswagen · asking $24,998
29 Nov 2026	Listing last updated[5] asking $24,998

§5 DOCUMENTS

Window sticker	We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 22 live listings, as of 29 Nov 2026
[5] Live public dealer listings on Cardog, as of 29 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.